

Microchip Part#s Affected:

DSPIC30F5013

DSPIC30F6010A

DSPIC30F6013A

DSPIC30F6014A

Description of Change:

CHANGE IN BILL OF MATERIAL

Impacts to Data Sheet:

NONE

Reason for Change:

TO IMPROVE MANUFACTURABILITY

Estimated Change Implementation Date(s):

August 31, 2007