

Product Change Notification - SYST-09JFLS469

Date: 09 Feb 2012

Product Category: Analog (Linear & Mixed Signal) AND Interface; 8-bit Microcontrollers

Device Family:  

Notification subject: Data Sheet - MCP6546/6R/6U/7/8/9 Datasheet Data Sheet Document Revision

Notification text:
SYST-09JFLS469
Microchip has released a new DeviceDoc for the MCP6546/6R/6U/7/8/9 Datasheet of devices. If you are using one of these devices please read the document located at [MCP6546/6R/6U/7/8/9 Datasheet](#).

Notification Status: Final

Description of Change: - Updated Package Types drawing to show correctly the device representation for SC-70 package. - Updated packages temperatures in Temperature Characteristics table. - Corrected the marking information table for the 5-Lead SC-70 package (MCP6546 and MCP6546U) in Section 5.1 "Package Marking Information". - Updated package outline drawings in Section 5.1 "Package Marking Information" to show all views for each package. - Minor editorial changes.

Pre Change: NA

Post Change: NA

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 09 Feb 2012

NOTE: Please be advised that this is a change to the document only the product has not been changed..

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [MCP6546/6R/6U/7/8/9 Datasheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

MCP6546

MCP6547

MCP6548

MCP6549