


## Product Change Notification - SYST-30WRSL614

---

**Date:** 30 Jul 2012

**Product Category:** Analog (Linear & Mixed Signal) AND Interface

**Device Family:** 

**Notification subject:** Data Sheet - ENC28J60 Stand-Alone Ethernet Controller with SPI Interface Data Sheet Document Revision

**Notification text:** SYST-30WRSL614  
Microchip has released a new DeviceDoc for the ENC28J60 Stand-Alone Ethernet Controller with SPI Interface of devices. If you are using one of these devices please read the document located at [ENC28J60 Stand-Alone Ethernet Controller with SPI Interface](#).

**Notification Status:** Final

**Description of Change:** 1) Removed from Preliminary status. 2) Described connection for the QFN metal thermal pad. 3) Modified the description of the TXERIF interrupt flag to indicate that it is held low on an interrupt until the interrupt flag or interrupt enable is cleared.

**Pre Change:** NA

**Post Change:** NA

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 30 Jul 2012

**NOTE:** Please be advised that this is a change to the document only the product has not been changed..

**Markings to Distinguish Revised from Unrevised Devices:**N/A

**Attachment(s):** [ENC28J60 Stand-Alone Ethernet Controller with SPI Interface](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

ENC28J60