



## Product Change Notification - SYST-18KJMP635

---

**Date:** 18 Oct 2012

**Product Category:** 8-bit Microcontrollers

**Device Family:**  

**Notification subject:** Data Sheet - dsPIC33EPXXX(GP/MC/MU)806/810/814 and PIC24EPXXX(GP/GU)810/814 Data Sheet Data Sheet Document Revision

**Notification text:**  
 SYST-18KJMP635  
 Microchip has released a new DeviceDoc for the dsPIC33EPXXX(GP/MC/MU)806/810/814 and PIC24EPXXX(GP/GU)810/814 Data Sheet of devices. If you are using one of these devices please read the document located at [dsPIC33EPXXX\(GP/MC/MU\)806/810/814 and PIC24EPXXX\(GP/GU\)810/814 Data Sheet](#).

**Notification Status:** Final

**Description of Change:** 1) Updated Section 34.0 "Packaging Information". 2) Removed Preliminary status from document. 3) Minor text edits throughout the document.

**Pre Change:** NA

**Post Change:** NA

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 18 Oct 2012

**NOTE:** Please be advised that this is a change to the document only the product has not been changed..

**Markings to Distinguish Revised from Unrevised Devices:**N/A

**Attachment(s):** [dsPIC33EPXXX\(GP/MC/MU\)806/810/814 and PIC24EPXXX\(GP/GU\)810/814 Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Parts Affected

PIC24EP512GU814  
dsPIC33EP256MU814  
PIC24EP256GU814  
dsPIC33EP512MU814  
dsPIC33EP512MU810  
dsPIC33EP256MU810  
PIC24EP512GU810  
PIC24EP256GU810  
dsPIC33EP512GP806  
dsPIC33EP512MC806  
PIC24EP512GP806  
dsPIC33EP256MU806