

Product Change Notification - CYER-31WHUB555

Date: 02 Jun 2011 **Product Category:** Memory

Device Family:

图图

Notification subject:

CCB 1061.02: Qualification of 48B WFBGA at PTI_SZ Assembly Site.

Notification text:

PCN Status: Initial notification

Microchip Parts Affected:

See attachments of affected catalog part numbers (CPN) labeled as...

PCN_CYER-31WHUB555_Affected_CPN.xls PCN_CYER-31WHUB555_Affected_CPN.pdf

Description of Change:

Qualification of 48B WFBGA package at PTI_SZ assembly site.

Impacts to Data Sheet:

None

Reason for Change:

To Improve On-Time Delivery Performance

Change Implementation Status:

In Progress

Estimated First Ship Date:

December 1, 2011 (date code: 1149)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts,

due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices: Traceability code

Revision History:

June 2, 2011: Issued initial notification.

Attachment(s):

PCN_CYER-31WHUB555_Affected_CPN.pdf PCN_CYER-31WHUB555_Affected_CPN.xls PCN_CYER-31WHUB555_Qual Plan.pdf

Please contact your local $\underline{\text{Microchip sales office}}$ with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at http://www.microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to microchipDIRECT and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

| CYER-31WHUB555 - 0 | CCB 1061.02: Qualification of 48B WFBGA at PTI_SZ Assembly Site. |
|----------------------------|--|
| Parts Affected | |
| | |
| SST39LF400A | |
| SST39VF200A | |
| SST39VF400A | |
| SST39VF800A | |
| SST39WF1601 SST39WF1602 | |
| SST39WF400A | |
| SST39WF400B | |
| SST39WF800A | |
| SST39WF800B | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| D . M 1 | 2011 |
| Date: Thursday, June 02, | 2011 |