Product Change Notification

The information below reflects a change that is being implemented.

Notice Date:

Product Category:

Notification Subject:

Notification Body:

Microchip Part#s Affected

93AA46A 93AA46B 93AA56A 93AA56B 93AA66A 93AA66B 93AA76A 93AA76B 93AA86A 93AA86B 93C46A 93C46B 93C56A 93C56B 93C66A 93C66B 93C76A 93C76B 93C86A 93C86B 93LC46A 93LC46B 93LC56A 93LC56B 93LC66A 93LC66B 93LC76A 93LC76B 93LC86A 93LC86B **MCP1251 MCP4022** 05/09/2005

Battery Management; Linear Devices; Mixed Signal Devices; Power Management; Thermal Management; 93xxx

Change #557 : QUALIFICATION OF 6L SOT-23 PACKAGE AT HANA

MCP4023 MCP603 MCP6043 MCP6143 MCP6273 MCP6283 MCP6293 MCP73826 **PIC10F200 PIC10F202 PIC10F204** PIC10F206 **TC1035 TC1038 TC1039** TC1072 **TC1073 TC1219** TC1220 TC1221 TC1222 TC1240 **TC1240A TC1240A** TC2014 **TC2015** TC2054 **TC2055** TC2185 **TC2186** TC3826 TC670

Description of Change: NEW ASSEMBLY SITE

Effects on Data Sheet: NONE

Reason for Change: INCREASED CAPACITY

Estimated Change Implementation Date(s): JUNE, 2005

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code, Device Marking, Ship Container Marking) SHIP CONTAINER MARKING, DEVICE MARKING