

Product Change Notification

The information below reflects a change that is being implemented.

Notice Date: 06/28/2005

Product Category: Battery Management; Linear Devices; Mixed Signal Devices; Power Management; Supervisor; Thermal Management; CAN Communication; LIN Communication; 24xxx; 25xxx; 93xxx; PIC12xxx; rfPIC; SDP

Notification Subject: Change #571 - New Leadframe Supplier for 8L SOIC .150"

Notification Body:
Microchip Part#s Affected
24AA01/24LC01B 24AA014/24LC014
24AA02/24LC02B 24AA02/24LC02B
24AA024/24LC024
24AA025/24LC025
24AA04/24LC04B 24AA04/24LC04B
24AA08/24LC08B
24AA16/24LC16B
24AA22A/24LC22A
24AA256/24LC256
24AA32A/24LC32A
24AA52/24LCS52/24LCS52A
24AA64/24LC64
24AAS22A/24LCS22A
24C01C
24C02C
24LC01B
24LC09
24LC21A
24LC32A
24LCS21A
25AA080A/25C080A/25LC080A
25AA080B/25C080B/25LC080B

25AA160A/25C160A/25LC160A
25AA160B/25C160B/25LC160B
25AA256/25LC256
93AA46/93LC46 93AA46A/93LC46A 93AA46AX/93LC46AX
93AA46B/93LC46B 93AA46BX/93LC46BX
93AA46C/93LC46C 93AA46CX/93LC46CX
93AA56/93AA56C/93LC56/93LC56C
93AA56A/93LC56A 93AA56AX/93LC56AX
93AA56B/93LC56B/93AA56B/93LC56B
93AA56BX/93LC56BX
93AA56CX/93LC56CX
93AA66/93C66/93LC66
93AA66A/93LC66A 93AA66AX/93LC66AX
93AA66B/93LC66B 93AA66BX/93LC66BX
93AA66C/93LC66C 93AA66CX/93LC66CX
93AA76C/93LC76C
93AA86C/93LC86C
93C46A 93C46AX
93C46B 93C46BX
93C46C 93C46CX
93C56A 93C56AX
93C56B 93C56BX
93C56C 93C56CX
93C66A 93C66AX
93C66B 93C66BX
93C66C 93C66CX
93C76C
93C86C
93LC46A 93LC46AX
93LC46B 93LC46BX
93LC56B 93LC56BX
93LC66B 93LC66BX
MCP1250
MCP130
MCP1726
MCP201
MCP2122
MCP2551 MCP3551
MCP3553
MCP4011 MCP4021
MCP4821 MCP4822
MCP4921
MCP6002

MCP6021 MCP6022 MCP6023
MCP6041 MCP6043
MCP6141 MCP6142 MCP6143
MCP6232
MCP6241 MCP6242
MCP6271/MCP6281/MCP6291
MCP6272/MCP6282/MCP6292
MCP6273/MCP6283/MCP6293
MCP6275/MCP6285/MCP6295
MCP6541 MCP6542 MCP6543
MCP6546 MCP6547 MCP6548
MCP6G01 MCP6G03
MCP6G41 MCP6G43
MCP6S21 MCP6S22
MCP6S91 MCP6S92
MCP9801
MCRF202
MCRF450X/SNX MCRF451X
MCRF452X MCRF455X
PIC12C509A/PIC12LC509A
PIC12F629
PIC12F675
PIC12F683
RFTXD0412
TC1025 TC1026
TC1029
TC1041
TC1044S/TC7660S/TC7662B
TC1107
TC1121
TC1173/TC1174
TC1232
TC1263 TC1265 TC1268
TC1300K/TC1300R/TC1300Y
TC1315
TC1320/TC1321/TC1322
TC1410 TC1410N
TC1411 TC1411N
TC1412 TC1412N
TC1413 TC1413N
TC1426/TC426/TC4426
TC1427/TC427/TC4427
TC1428/TC428/TC4428

TC3400
TC429
TC4404 TC4405
TC4420
TC4426A TC4427A
TC4428A TC4429
TC4432
TC622 TC623C TC624
TC642B/TC646B/TC647B/TC648B/TC649B
TC7660 TC7660H
TC7660M TC7660S/TC7662B
TC77
TC913A/TC913B
TCN75 TCN75A

Description of Change:
Change of Leadframe Supplier

Impacts to Data Sheet:
None

Reason for Change:
Subcontractor has changed leadframe vendors. The new vendor, ASM has provided leadframes for several of our assembly sites, including MTAI.

Estimated Change Implementation Date(s):
JUNE 13, 2005

Markings to Distinguish Revised From Unrevised Devices:
(e.g.: Date Code, Device Marking, Ship Container Marking)
Tracability code, COO, Date Code