




Product Change Notification - CYER-22LSUP207

Date: 28 Jun 2011
Product Category: 16-bit Microcontrollers and Digital Signal Controllers; 32-bit PIC Microcontrollers
Device Family: 
Notification subject: CCB 1066: Qualification of 121L XBGA (10x10) with DS7409HGB substrate at ANAP assembly site
Notification text:

PCN Status:
Initial notification

Microchip Parts Affected:
See attachments of affected catalog part numbers (CPN) labeled as...
[PCN_CYER-22LSUP207_Affected_CPN.xls](#)
[PCN_CYER-22LSUP207_Affected_CPN.pdf](#)

Description of Change:
Qualification of 121L XBGA (10x10) with DS7409HGB substrate at ANAP assembly site.

Pre Change:
CCL-HL832NX substrate

Post Change:
DS7409HGB substrate

Impacts to Data Sheet:
None

Reason for Change:
To improve on time delivery performance

Change Implementation Status:
In Progress

Estimated First Ship Date:
September 30, 2011 (date code: 1140)

NOTE: Please be advised that during the transition period customers may receive pre and post change parts, due to existing inventory of the pre changed parts.

Markings to Distinguish Revised from Unrevised Devices:
Traceability code

Revision History:
June 28, 2011: Issued initial notification.

Attachment(s): [PCN_CYER-22LSUP207_Affected_CPN.pdf](#)
[PCN_CYER-22LSUP207_Affected_CPN.xls](#)
[PCN_CYER-22LSUP207_Qual Plan.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."~

Parts Affected

PIC24FJ128DA210
PIC24FJ256GB210
PIC32MX320F128L
PIC32MX340F128L
PIC32MX360F256L
PIC32MX360F512L
PIC32MX440F128L
PIC32MX460F256L
PIC32MX460F512L
PIC32MX534F064L
PIC32MX564F064L
PIC32MX564F128L
PIC32MX575F256L
PIC32MX575F512L
PIC32MX664F064L
PIC32MX664F128L
PIC32MX675F256L
PIC32MX675F512L
PIC32MX695F512L
PIC32MX764F128L
PIC32MX775F256L
PIC32MX775F512L
PIC32MX795F512L