

# Product Change Notification

The information below reflects a change that is being implemented.

Notice Date:

05/26/2005

Product Category:

Battery Management; Infrared Devices; Linear Devices; Mixed Signal Devices; Power Management; RS232; Supervisor; Thermal Management; CAN Communication; Infrared Communication; LIN Communication; Serial Communication; 24xxx; 25xxx; 93xxx; PIC12xxx; rPIC; RFID; SDP

Notification Subject:

Change #558 - QUALIFICATION OF 8L SOIC PACKAGE IN STRIP MAGAZINE FORM AT HANA

Notification Body:

Microchip Part Number

24AA00/24LC00

24AA01/24LC01B

24AA014/24LC014

24AA02/24LC02B

24AA024/24LC024

24AA025/24LC025

24AA04/24LC04B

24AA08/24LC08B

24AA128/24LC128

24AA16/24LC16B

24AA22A/24LC22A

24AA256/24LC256

24AA32A/24C32A/24LC32A

24AA32A/24LC32A

24AA52/24LCS52/24LCS52A

24AA64/24LC64

24AAS22A/24LCS22A

24ACR01

24ACR02

24C00

24C01C

24C02C

24FC128

24FC256

24LC01B

24LC025

24LC211/24LC21A


24LCS21A

25AA040/25C040/25LC040  
25AA080A/25C080A/25LC080A  
25AA080B/25C080B/25LC080B  
25AA160A/25C160A/25LC160A  
25AA160B/25C160B/25LC160B  
25AA256/25LC256  
25AA320/25C320/25LC320  
25AA640/25LC640  
93AA46A/93LC46A  
93AA46AX/93LC46AX  
93AA46B/93LC46B  
93AA46BX/93LC46BX  
93AA46C/93LC46C  
93AA46CX/93LC46CX  
93AA56/93LC56  
93AA56A/93LC56A  
93AA56AX/93LC56AX  
93AA56B/93LC56B  
93AA56BX/93LC56BX  
93AA56C/93LC56C  
93AA56CX/93LC56CX  
93AA66A/93LC66A  
93AA66AX/93LC66AX  
93AA66B/93LC66B  
93AA66BX/93LC66BX  
93AA66C/93LC66C  
93AA66CX/93LC66CX  
93AA76C/93LC76C  
93AA86C/93LC86C  
93C46A  
93C46AX  
93C46B  
93C46BX  
93C46C  
93C46CX  
93C56A  
93C56AX  
93C56B  
93C56BX  
93C56C  
93C56CX  
93C66A  
93C66AX  
93C66B  
93C66BX  
93C66C  
93C66CX  
93C76C  
93C86C  
93CS46A/93LC46A

93LC46AX  
93LC46B  
93LC46BX  
93LC56A  
93LC56AX  
93LC56B  
93LC56BX  
93LC66A  
93LC66AX  
93LC66B  
93LC66BX  
CLF320/HCS320  
HCS101  
HCS201  
MCP102/MCP103  
MCP111  
MCP112  
MCP120  
MCP121  
MCP130  
MCP131  
MCP1726-ADJ  
MCP1726-FIXED  
MCP201  
MCP2122  
MCP2551  
MCP3001  
MCP3002  
MCP3201  
MCP3202  
MCP3301  
MCP41010  
MCP41050  
MCP41100  
MCP4821  
MCP4822  
MCP4921  
MCP6001  
MCP6002  
MCP601  
MCP602  
MCP6021  
MCP6022  
MCP6023  
MCP603  
MCP6041  
MCP6042  
MCP6043  
MCP606  
MCP607

MCP608  
MCP6141  
MCP6142  
MCP6143  
MCP616  
MCP617  
MCP618  
MCP6231  
MCP6232  
MCP6241  
MCP6242  
MCP6271/MCP6281/MCP6291  
MCP6272/MCP6282/MCP6292  
MCP6273/MCP6283/MCP6293  
MCP6275/MCP6285/MCP6295  
MCP6541  
MCP6542  
MCP6543  
MCP6546  
MCP6547  
MCP6548  
MCP6S21  
MCP6S22  
MCP6S91  
MCP6S92  
MCP9801  
MCP9803  
MCRF200/MCRF250  
MCRF202  
MCRF355  
MCRF360  
MCRF450X/SNX  
MCRF451X  
MCRF452X  
MCRF455X  
PIC12C508A/PIC12LC508A  
PIC12C509A/PIC12LC509A  
PIC12CR509A/PIC12LCR509A  
PIC12F508  
PIC12F509  
PIC12F629  
PIC12F635  
PIC12F675  
PIC12F683  
TC1025  
TC1026  
TC1029  
TC1041  
TC1044S  
TC1107

TC1121  
TC1173  
TC1173/TC1174  
TC1174  
TC1232  
TC1263  
TC1265  
TC1266  
TC1268  
TC1300K/TC1300R/TC1300Y  
TC1300R/TC1300Y  
TC1315  
TC1320/TC1321/TC1322  
TC1410  
TC1410N  
TC1411  
TC1411N  
TC1412  
TC1412N  
TC1413  
TC1413N  
TC1426/TC426/TC4426  
TC1427/TC427/TC4427  
TC1428/TC428/TC4428  
TC3400  
TC429  
TC4404  
TC4405  
TC4420  
TC4426A  
TC4427A  
TC4428A  
TC4429  
TC4431  
TC4432  
TC620C  
TC620H  
TC621C  
TC621H  
TC622  
TC623C  
TC624  
TC642  
TC642/TC647  
TC642B/TC646B/TC647B/TC648B/TC649B  
TC646  
TC646/TC649  
TC647  
TC648  
TC649



TC682  
TC7660  
TC7660H  
TC7660M  
TC7660S/TC7662B  
TC77  
TC913A/TC913B  
TCM680  
TCM850  
TCM851  
TCM852  
TCM853  
TCN75  
TCN75A

Description of Change:  
NEW ASSEMBLY SITE

Effects on Data Sheet:  
NONE

Reason for Change:  
INCREASED CAPACITY, ABILITY TO STRIP TEST

Estimated Change Implementation Date(s):  
JUNE, 2005

Markings to Distinguish Revised From Unrevised Devices: (e.g.: Date Code,  
Device Marking, Ship Container Marking)  
SHIP CONTAINER MARKING, DEVICE MARKING