

Product Change Notification – 01-2022.USA

Product Lines:	XLR etherCON Cat 6	Part No:	BXX* NC* NE8MC6-MO*
----------------	-------------------------------	----------	------------------------------------

Piece Part:	Bushing		
-------------	---------	--	--

Engineering Change Request:	2020-0533 2021-0597	Date:	18 March 2022
-----------------------------	------------------------	-------	---------------

Comments:	Bushing redesign
-----------	------------------

Affected products:	BXX-0-BLACK BXX-CR BXX-WOR NC3FDX-EMC-SPEC NC3FM-C NC3FM-C-B NC3FRX NC3FRX-B NC3FRX-BAG NC3FXX NC3FXX-B NC3FXX-B-CRYSTAL NC3FXX-B-D NC3FXX-B-M-D NC3FXX-BAG NC3FXX-BAG-D NC3FXX-D NC3FXX-EMC NC3FXX-EMC-B NC3FXX-HA NC3FXX-HA-BAG NC3FXX-HD-B-D NC3FXX-HD-D NC3FXX-HE NC3FXXA-B-D NC3FXXA-B-H-D NC3FXXA-BAG-D NC3FXXA-D NC3MRX NC3MRX-B NC3MRX-BAG NC3MXX NC3MXX-B NC3MXX-B-CRYSTAL NC3MXX-B-D NC3MXX-B-M-D NC3MXX-BAG NC3MXX-BAG-D NC3MXX-D
--------------------	--

	NC3MXX-EMC NC3MXX-HA NC3MXX-HA-BAG NC3MXX-HD-B-D NC3MXX-HD-D NC3MXX-HE NC3MXX-HE-D NC3MXXA-B-D NC3MXXA-B-H-D NC3MXXA-BAG-D NC3MXXA-D NC4FRX NC4FRX-B NC4FRX-BAG NC4FXX NC4FXX-B NC4FXX-B-D NC4FXX-BAG NC4FXX-BAG-D NC4FXX-D NC4FXX-HD-D NC4MRX NC4MRX-B NC4MRX-BAG NC4MXX NC4MXX-B NC4MXX-B-D NC4MXX-BAG NC4MXX-BAG-D NC4MXX-D NC5FRX NC5FRX-B NC5FRX-BAG NC5FXX NC5FXX-B NC5FXX-B-D NC5FXX-BAG NC5FXX-BAG-D NC5FXX-D NC5FXX-HD-D NC5MRX NC5MRX-B NC5MRX-BAG NC5MXX NC5MXX-B NC5MXX-B-D NC5MXX-BAG NC5MXX-BAG-D NC5MXX-D
--	--

	NC5MXX-HD-D NC6FRX NC6FRX-B NC6FRX-BAG NC6FSXX NC6FSXX-B NC6FSXX-BAG NC6FXX NC6FXX-B NC6FXX-BAG NC6MRX NC6MRX-B NC6MRX-BAG NC6MSXX NC6MSXX-B NC6MSXX-BAG NC6MXX NC6MXX-B NC6MXX-BAG NC7FRX NC7FRX-B NC7FRX-BAG NC7FXX NC7FXX-B NC7FXX-BAG NC7MRX NC7MRX-B NC7MRX-BAG NC7MXX NC7MXX-B NC7MXX-BAG NE8MC6-MO NE8MC6-MO-D
--	---

First shipment of modified product:	O51
-------------------------------------	-----

Engineering Change Notice

As part of the continuous improvement of our products we improved the bushing of above listed products as follows:

1. Gate location has been changed.



2. Rubber lip added to bushing to improve stability of the coding ring (see picture below).

3. Neutrik logo added (see picture below).

