

27501 Bella Vista Pkwy Warrenville, IL 60555

08/01/2024

## **Product Change Notice #082401**

Type of Change:	<ul><li>☑ End of Life</li><li>☐ Facility Change</li><li>☐ Design Change</li></ul>	<ul><li>☐ Material Change</li><li>☐ Process Change</li><li>☐ Other</li></ul>
Part Series Affected: B60 series, BGA series, C series, CR series, CSM series, E series, M series, R2 series, S series, VM series, VR series, VX series, W series (Full part list available on next page)		
Description of Change: Ohmite is discontinuing a number of heatsink part numbers. There may be emerging applications where the sales history of some discontinued parts would change significantly when mass production takes place. Ohmite remains open to reinstituting certain discontinued parts should the opportunity warrant it.		
Reason for Change: Recent tariff duty increases have led to a large increase in price for some of Ohmite's heatsinks. To better serve our customers, we have decided to discontinue less popular heatsink part numbers and will instead focus on more popular heatsink options to fulfill Ohmite customer needs.		
Effective Date: 08/01/2024		
Date Last Time Buy: Ohmite will continue selling the discontinued heatsink part numbers until our current inventory is extinguished.		
Date of Last Time Shipment: Ohmite will continue selling the discontinued heatsink part numbers until our current inventory is extinguished.		
Recommended Replacement: Ohmite has many heatsink options that are still available. Please reach out if you're interested in finding an alternative to one of our discontinued parts.		
For further technical questions related to this PCN, please contact dchakraborty@ohmite.com.		
Best Regards,		
Joe Misulonas Marketing Manager jmisulonas@ohmite.com		

Information, data and drawings embodied in this correspondence are strictly confidential and are supplied on the understanding that they will be held confidentially and not disclosed to third parties without the prior written consent of Ohmite Manufacturing Company, Inc.



## Part Numbers Affected

B60-075-AE B60-075-VE BGAH150-075E **BGAH150-125E** BGAH170-075E BGAH190-090E BGAH270-175E BGAH310-075E BGAH325-075E **BGAH375-125E** BGAH425-125E BGAH450-125E C220-025-1AE C220-025-1VE C220-075-3AE C220-075-3VE C247-050-2VE C247-075-3AE C247-075-3VE C264-030-1AE C264-030-1VE C264-058-2AE C264-058-2VE C264-085-3AE C264-085-3VE C2A-XT4-46E C2V-XT4-46E CR401-25AE CR401-25VE CR401-50AE CR401-50VE CR401-75AE CR401-75VE

CSM222-30AE EA-T220-38E EA-T220-51E EA-T220-64E EV-T220-38E EV-T220-51E EV-T220-64E MA-102-55E MA-301-27E MV-301-27E MV-302-55E R2V-CT4-38E SA-LED-113E SA-LED-125E SA-LED-151E SA-LED-176E SV-LED-113E SV-LED-125E SV-LED-151E SV-LED-176E SV-LED-314E SV-LED-325E VM2-038-1AE VRA-27-101E VRA-55-101E VRV-27-101E VRV-55-101E VXA-35-101E VXA-55-101E VXV-35-101E VXV-55-101E WA-T264-101E WV-T264-101E