

na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

Product Change Notice: JW Relay Sockets Part Display Marking Change

PCN.PG06.04.11.2024 04.11.2024

About This Notice:

We would like to inform that the JW socket relays are subject to change. The marking displayed on the product body, inner carton, and outer carton will be changed in order to comply with the display specifications of the certification standard.

Effective Date:


November 1, 2023.

Change Details:

For the product body, the CSA mark is added. For the Inner Carton, the UL mark is removed, and CSA mark is added. Lastly, the CSA and UL logos are both deleted from the outer carton.

	JW1-PS			
	Before	After		
Product Body	Use " CSA Monogram Mark " for CSA mark Panasonic JAPAN (T) JW1-PS AJW8015	Use " CSA Component Acceptance Mark " as CSA mark Panasonic JW1-PS AJW8015 Add A		
Inner carton	Panasonic® ■ JW1-PS ■ ■ AJW8015 ■ ■ 10A 250V AC ● SOCKET 15PCS. (Fib.) ***********************************	Panasonic ■ JW1-PS ■ AJW8015 ■ 10 A 250 V AC SOCKET 18PCS. (R) **TORNER MEDICAL PROPERTY OF THE PARAMETER AND ACCORDINATION OF THE PARAMETER AND ACCOR		
Outer carton	Panasonic JYVI-P8 AJVV8015 JW-SOCKET 100 Pcs. Interest folders, Ca ₁ (bc. MAX: RLAHVN)	Mark delete Panasonic JW1-PS AJW8015 JW-SOCKET 100 Pcs, TSYNGRET (NAMED IN JAMAGE I		

Panasonic INDUSTRY



na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

		na.industriai.pariasonic.com	industrial@us.pariasonic.com	1-000-344-2112		
		JW2-PS (Same as JW1-PS)				
		Before	After			
	Product Body	Panasonic JAPAN AL SP JW2-PS AJW8025	Panasonic JAPAN TAL JW2-PS AJW8025 AG	dd ▲		
	Inner carton	Panasonic ■ JW2-PS ■ AJW8025 ■ 5A 250 V AC ■ SOCKET 10PCS. (To) **COMMENT CHARGET CIT. US MESS AND.	Panasonic • JW2-PS • AJW8025 • 5A 250 V AC SOCKET 10PCS. (©) PROCED BARRING OF MICHON			
	Outer carton	Panasonic JW2-PS AJW8025 B B TOO PCS. Panasonic Priustry Co., Ltd. MADE NI JAPAN.	Mark delete Panasonic J 12 - PS A J W8 0 2 5 J W - S O C KET 100 PCS. Panasonic industry Co., Ltd. MADE N. JAPAN			
Affected Parts:	JW1-PS (JW1 PC board socket) JW2-PS (JW2 PC board socket)					
Datasheet(s):	See attached.					
Notes:	The part number, specification, safety certifications, and price remain unchanged. CSA requires a CSA component acceptance mark if ratings are to be displayed on the outside of the product whereas UL does not need to display the mark on the packaging when displaying the mark on the product.					

Panasonic PCN.PG06.04.11.2024 JW Relay Sockets Part Display Marking Change

Affected Series	Affeceted Part Numbers	Suggested Replacement Series	Suggested Replacement Part Numbers	Comments
JW Relay Accessory	JW1-PS	N/A	N/A	Product body: CSA Cmark added.
				Inner Carton: UL mark removed and CSA mark added.
				Outer carton: CSA and UL logo deleted
JW Relay Accessory	JW2-PS	N/A	N/A	Product body: CSA Cmark added.
				Inner Carton: UL mark removed and CSA mark added.
				Outer carton: CSA and UL logo deleted