


IN Your Innovation

Product Change Notification (PCN)

PhotoMOS® notification of standard change

Change of UL certification

Date: July 4th, 2024
No.: T-1524



Reason for change	UL certification change from UL508 and UL1577 to UL1577 only
Series affected*	DIP4, DIP6, DIP8, SOP4, SOP6, SOP8, Power DIP, SIL4 Part number, specification and price remain unchanged.
Replacement recommendation	Not needed, no technical changes of the relays.
Change schedule	From June 2024 shipments onwards

* Including some customized products. Please contact our sales representative for applicable part numbers

IN Your Innovation

Part numbers affected

Product type	Package	Part No.
PhotoMOS®	SOP4	AQY***S
	SOP6	AQV***S
	SOP8	AQW***S
	DIP4	AQY***
	DIP6	AQV***
	DIP8	AQW***
	PD4	AQY*7*
	SIL4	AQZ*0*
	SIL4	AQZ19*
MOSFET Drivers	SOP4	APV*121S
	DIP6	APV*122
Solid State Relay	DIP8	AQH*2*3