

Product Change Notification (PCN)

Nov. 2011

Notification of change of production plant for PhotoMOS relays



We would like to inform you that the production plant for some PhotoMOS Relays SOP4pin, DIP4pin & DIP8pin type will be temporary changed as follows:

1. Contents

Our production in Navanakorn (Thailand) - Panasonic Electric Works, Thailand Ltd. - is directly affected by the flood disaster and not able to produce for the time being. Manufacturing of the affected PhotoMOS types is transferred to our factory in Japan - Panasonic Electric Works Co. Ltd. (ISE, Japan).

2. Types

SOP4pin type

AQY210S*, AQY212S*, AQY214S*, AQY212GS* (X or Z)

DIP4pin type

AQY210EH, AQY212EH**, AQY214EH**, AQY212GH**, AQY211EH** (A or AX or AZ)**

DIP8pin type

AQW210EH, AQW212EH**, AQW214EH**, AQW210HL** (A or AX or AZ)**

3. Schedule

From **November 2011** production onwards until recovery of Thailand factory.

4. Performance and Quality remain unchanged