

## **Product change information**

PCN No.:	CBG182011	Date:	03.12.2018
----------	-----------	-------	------------

Order No.	Designation
See list	A and Al


Description of change					
☐ Product appearance (fit)	☐ Product geometry (form)	☐ Product function (function)			

## UL certification for special ferrules recalled by Underwriters Laboratories (UL)

Phoenix Contact has recently been informed by Underwriters Laboratories (UL) that they made a mistake during the certification of our ferrules. Along with the standard ferrules, the UL body also tested and certified the special ferrules (color and length versions) in accordance with UL 486F, which are NOT mentioned in this standard. UL has withdrawn our certification for these special ferrules. This means that we have to remove the UL logo from the packaging and that the file has to be corrected. Under pressure from Phoenix Contact, UL will adjust the UL 486F standard accordingly. UL has not yet announced the date of implementation.

Important: This series of changes only affects certain special ferrules. All other ferrules remain unchanged and continue to have UL certification, even if the current UL file is not up to date. The batch version number (V/C) will be changed.

## PHCENIX PHOENIX CONTACT GmbH & Co. KG Flachsmarkstr. 8, D-32825 Blomberg www.phoenixcontact.com Date: 2018-11-13 15:03 4 017918 093679 AI 0,75-8 BU Ord.No.: 32 00 02 7 Made by Phoenix Contact in Germany Made by Phoenix Contact in Germany TOUS: CRIMPFOX 6; CRIMPFOX CENTRUS 'HIS, CRIMPFOX DUO 10, CF 50001000 TOUS: TRANDED CU WIRE/ WIRE CLASS B,C,K,M



Expected initial delivery of the changed product(s)

As of now

Phoenix