

Product change notification (PCN)

Title / short description	PSR-MC40 hardware optimization
Affected article category	Functional safety
Change category	Marking
Change number	CDN200022-00

Purpose/objective of the change

As part of product optimization, a second-source component is used.

Detailed description of the change

A hardware optimization has been carried out on the listed articles. All articles are fully compatible with the previous article versions.

Identifying characteristics

On the right-hand side of the housing, the HW version will be increased.

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2020-08-14	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☒ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- MC40_printing_old.png
- MC40_printing_new.png
- Material_list.csv
- PCN-CDN200022-00 PSR-MC40 Hardwareoptimierung_DE
- PCN-CDN200022-00 PSR-MC40 hardware optimization_EN

Material list

Item	Article Type	Revision/production batch		Item	Substitute item Type
		old	new		
2700569	PSR-MC40-3NO-1DO-24DC-SC	05/--	06/--		
2700570	PSR-MC40-3NO-1DO-24DC-SP	05/--	06/--		

Produktänderungsmitteilung (PCN)

Titel / kurze Beschreibung	PSR-MC40 Hardwareoptimierung
Betroffene Artikelkategorie	Funktionale Sicherheit
Änderungskategorie	Beschriftung
Änderungsnummer	CDN200022-00

Zweck/Ziel der Änderung

Im Rahmen einer Produktoptimierung wird auf ein Second-Source Bauteil zurückgegriffen.

Detailbeschreibung der Änderung

Bei den gelisteten Artikeln wurde eine Hardware-Optimierung durchgeführt. Alle Artikel sind zu den vorherigen Artikelrevisionen voll kompatibel.

Identifizierende Merkmale

Auf der rechten Gehäuseseite wird der HW-Stand erhöht.

Beginn der Herstellung (SOP)	-	Letztmalige Lieferung (LTD)	-
Inkrafttreten der Änderung (EOP)	2020-08-14	Einstellung von Service (EOSR)	-
Einstellung des Vertriebs (EOS)	-		

Kurzfristige Änderung (< 6 Monate) oder Abkündigung (< 12 Monate), auf Grund von:

- | | | |
|---|--|--|
| ☐ Software / Firmware Bugfix | ☐ Kurzfristiger Lieferstopp durch den Lieferanten | ☐ Kurzfristiger Rückruf durch den Lieferanten |
| ☐ Höhere Gewalt | ☒ Produktverbesserung mit Kundennutzen | |
| ☐ Sonstiges | | |


Anlagen

- MC40_printing_old.png
- MC40_printing_new.png
- Material_list.csv
- PCN-CDN200022-00 PSR-MC40 Hardwareoptimierung_DE
- PCN-CDN200022-00 PSR-MC40 hardware optimization_EN


Materialliste

Art.-Nr.	Artikel Typ	Revision/Versionscharge		Art.-Nr.	Ersatzartikel Typ
		alt	neu		
2700569	PSR-MC40-3NO-1DO-24DC-SC	05/--	06/--		
2700570	PSR-MC40-3NO-1DO-24DC-SP	05/--	06/--		

Item	Type	old	new	Substitute item	Replacement product designation	eCl@ss 9.0
2700569	PSR-MC40-3NO-1DO-24DC-SC	05/--	06/--			27371819
2700570	PSR-MC40-3NO-1DO-24DC-SP	05/--	06/--			27371819



Current



New