

PRODUCT CHANGE NOTIFICATION

Product Category LOOSE PIECE CABLE TIES **20230629-1**

Product Group PLASTIC CABLE TIES

ISSUE DATE: 29-Jun-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Effective December 1, 2023 the following part numbers will be discontinued and replaced with an alternate part number as indicated.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	6	30
Old product discontinuation date*	2023	12	1

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		

LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customer-service@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
SST1M-C	Compatible	SST1.5M-M	PLT1M-C		01-DEC-2023
SST1M-C0	Compatible	SST1.5M-M0	PLT1M-C0		01-DEC-2023
SST1M-M	Compatible	SST1.5M-M	PLT1M-M		01-DEC-2023
SST1M-MP	Compatible	SST1.5M-M	PLT1M-M		01-DEC-2023
SST1M-M0	Compatible	SST1.5M-M0	PLT1M-M0		01-DEC-2023
SST1M-M30	Complex	PLT1M-M30		Yes	01-DEC-2023
SST3I-M	Compatible	SST4I-M	PLT3I-M		01-DEC-2023
SST3I-M0	Compatible	SST4I-M0	PLT3I-M0		01-DEC-2023
SSM2S-C	Complex	PLM2S-C		Yes	01-DEC-2023
SSM2S-D	Complex	PLM2S-D		Yes	01-DEC-2023
SSM2S-D0	Complex	PLM2S-D0		Yes	01-DEC-2023
SSM4S-D	Complex	PLM4S-D		Yes	01-DEC-2023
SST3S-C0	Compatible	SST4S-C0	PLT3S-M		01-DEC-2023
SST3S-C0/W	Compatible	SST4S-C0	PLT3S-M		01-DEC-2023
SST3S-M	Compatible	SST4S-M	PLT3S-C0		01-DEC-2023
SST3S-M0	Compatible	SST4S-M0	PLT3S-M0		01-DEC-2023
SST3S-M30	Compatible	SST4S-M30	PLT3S-M30		01-DEC-2023

Replacement Type Definition

DIRECT
REPLACEMENT

Exact same part in a different package size, or has any other update that doesn't change the product itself

COMPATIBLE

The replacement part is different in a way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like *CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.

NO REPLACEMENT

No replacement product is available.