

PRODUCT CHANGE NOTIFICATION

Product Category COPPER PATCHCORDS 202220629
 Product Group ENTERPRISE CONNECTIVITY
 ISSUE DATE: June 29th, 2022
 IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Pan-Net Patch Cords - Packaging Change

Existing copper patch cords lines are changing as part of the Panduit Corp effort to prioritize environment conciousness and sustainability. The Network Infrastructure Enterprise team is reducing single-use plastic packaging consumption for copper patch cord products and replacing materials with flag labels. Executed as a running change across the patch cord product offering, over the second half of 2022 no changes to part numbers are expected.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	7	1
Old product discontinuation date*			

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA		
			EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
UTP28X%					
UTP6AX%					
STP28X%					
STP6X%					
UTPK6A%					
STPK6X%					
UTP6AL%					
NK6APC%					
UTP28SP%					
UTP28SP%					
UTPSP%					
UTPKSP%					
UTPSPL%					
NK6PC%					
UTP28CH%					
UTPCH%					
STPCH%					
NK5EPC%					