

## PRODUCT CHANGE NOTIFICATION

Product Category TERMINALS **20220822-2**

Product Group TERMINALS AND REELSMART

ISSUE DATE: August 15th, 2022

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

### DESCRIPTION OF CHANGE: (Required)

Panduit will be moving the UL required markings from the bottom to the top of the terminal tongue on our #8 stud size Loose Piece and ReelSmart™ terminals. There will also be an addition of a "8" to help differentiate #8 sized terminals from closely sized #6 and #10 sizes which may help avoid misinstallation and improve convenience for installers and quality inspectors. This is expected to be a running change over the course of several months as this is cosmetic only, and will not affect the performance of the product.

Photos/Drawing (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

### DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022		
Old product discontinuation date*			

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

### CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	CHINA: 400-820-1900 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	HONG KONG: 800-965768 <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	INDONESIA: 001 803 65 7571 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	JAPAN: +81-3-6863-6000 <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	KOREA: 02-2182-7300 <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	MALAYSIA 1800 801435 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	SINGAPORE: 1-800-7263848 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	TAIWAN: 0080 165 1487 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	THAILAND: 001-800-65-6385 <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
	LATIN AMERICA	BRAZIL 08000562613 (Toll Free) <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) <a href="mailto:MEX-customer-service@panduit.com">MEX-customer-service@panduit.com</a>	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
NORTH AMERICA	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	EMEA	EMEA: +44 208 6017219 <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
P18-8R-C					
P18-8R-M					
PV18-8RX-MY					
PV18-8R-MY					
PV18-8R-CY					
PV18-8RX-CY					
PV18-8R-E					
PV14-8R-M					
PV14-8RX-M					
P14-8R-M					
P14-8R-C					
PV14-8RX-C					
PV14-8R-C					
PV14-8R-E					
PV10-8R-D					
PV10-8R-L					
PV10-8RB-2K					
PV10-8RX-D					
P10-8R-D					
P10-8R-L					
PV10-8RX-L					
PV10-8R-E					
P18-8LF-M					
P18-8LF-C					
PV18-8LFX-MY					
PV18-8LF-MY					
PV18-8LFX-CY					
PV18-8LF-CY					
PV14-8LF-C					
PV14-8LF-M					
PV14-8LFX-C					
PV14-8LFX-M					
P14-8LF-M					
P14-8LF-C					
PV14-8LF-E					
P10-8LF-L					
P10-8LF-D					
PN10-8LF-D					
PV10-8LF-D					
PV10-8LF-L					
PV10-8LFX-D					
PV10-8LFX-L					
PN10-8LF-L					
PNF10-8LF-D					
PNF10-8LF-L					
PV10-8LF-E					
PNF18-8R-3K					
PV18-8RB-3K					
PN18-8R-M					
PN18-8R-3K					
PNF18-8R-C					
PN18-8R-C					
PK18-8R-C					
PNF18-8R-M					
PN18-8R-E					
PNF14-8R-3K					
PN14-8R-3K					
PN14-8R-M					
PV14-8RB-3K					
PK14-8R-C					
PN14-8RX-C					
PN14-8R-C					

PNF14-8R-C					
PNF14-8R-M					
PN14-8R-E					
PNF10-8R-2K					
PN10-8R-D					
PN10-8R-L					
PN10-8R-2K					
PK10-8R-L					
PN10-8RX-L					
PNF10-8R-D					
PNF10-8R-L					
PN10-8R-E					
PNF18-8LF-3K					
PV18-8LFB-3K					
PN18-8LF-M					
PN18-8LF-3K					
PN18-8LF-C					
PNF18-8LF-C					
PNF18-8LF-M					
PNF14-8LF-3K					
PN14-8LF-C					
PN14-8LF-M					
PN14-8LF-3K					
PV14-8LFB-3K					
PNF14-8LF-C					
PNF14-8LF-M					
PN14-8LF-E					

# Replacement Type Definition

---

DIRECT  
REPLACEMENT

Exact same part in a different package size, or has any other update that doesn't change the product itself

COMPATIBLE

The replacement part is different in a way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like *CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.

NO REPLACEMENT

No replacement product is available.