



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECN #: 293105

2. Date of Announcement: February 21, 2017

3. Series:

- SEAF - .050 PITCH SOCKET ARRAY ASSEMBLY

4. Part #'s Affected


- SEAF-XX-XX-X-XX-X-RA-XX-TR

5. Description of Change:


Form change only; a top lip was added and the shroud depth was increased. This will be a rolling change and new revision material will be used once current revision material is depleted. This change has no effect on mating with existing SEAM connectors.

6. Method of Identifying Change

On the new product, there is a raised section in the center of the top of the mating face. On the old revision, this area was flat.



Previous Revision Product



New Revision Product

7. Reason for Change:

Form change made to allow for development of SEAX with new latching options.

8. Impact of Change on Form, Fit, or Function:

- Form - There is an elevated part on the mating face that is coplanar with the top standoffs.

9. Projected Implementation Date: March 20, 2017