

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
01	002	010	0000000503	See list below	Fuseholder complete	FPG4	n.a.


\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected							
<b>FPG4 complete</b>							
3101.0040	3101.0045						
<b>FPG4 socket</b>							
3101.4015.1							
<b>FPG4 carrier</b>							
3101.8011	3101.8012	3101.8511					

**2 Type of change**

- Change of markings

**3 Detailed description of change**



**4 Reason of change**

- Newly approved nominal voltage according to IEC 60127-6

**5 Release date**

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

**6 Impact of change and recommended action**

Form	Yes	Modified marking on product
Fit	Yes No	No change for dimension
Function	Yes No	No change in function
Manufacturing	Yes No	No change for manufacturing site
Label	Yes No	No change on label
Packaging	Yes No	No change in packaging

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">Data Sheet</a>	

Product Change Notification						FPG4 change of the marks	
owner	creation date	release date	released by	change order no	rev	page	
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	A	1 of 1	D10-010-918