

1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.			
SBU PG PUG Type							
80 084 001 0000006145	See list below	EMC	FMAB-72				
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							

List of part numbers affected							
5500.2021	5500.2024	5500.2107	5500.2110	5500.2113			
5500.2022	5500.2025	5500.2108	5500.2111	5500.2114			
5500.2023	5500.2106	5500.2109	5500.2112	5500.2115			

2 Type of change

Change of product and packaging label due to production transfer from Slovachia (SK) to Romania (RO)

3 Detailed description of change

Change of factory code from SK to TO Change of origin from SK to RO



4 Reason of change

Reorganization of production process.

5 Release date

The change will be rolled-out starting June 2017 and lasts approx. 2 months depending on the variant.

6 Impact of change and recommended action

Form No No change in form

Fit No No change for dimension

Function No No change in function

Production site Yes Change of production site

Label Yes Change on label

Packaging No No change in packaging

Product Change Notification				PCN FMAB-72 Family - Production site			
owner	creation date	release date	released by	change order no	rev	page	D40 046 222
segatro	2017-06-07	2017-06-07	romanogu	2013028	Α	1 of 2	D10-016-223



7 Reference Documents / Attachments

Kind of document	Remarks
Datasheet FMAB-72	

Product Change Notification				PCN FMAB-72 Family - Production site			
owner	creation date	release date	released by	change order no	rev	page	D40 046 000
segatro	2017-06-07	2017-06-07	romanogu	2013028	Α	2 of 2	D10-016-223