

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|--------------------|--------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 01 | 002 | 010 | 0000000503 | See list below | Circuit protection | FPG4 | n.a. |

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected



FPG4 complete

| | | | |
|---------------------|-----------|-----------|--|
| 3101.0040 | 3101.0045 | | |
| FPG4 socket | | | |
| 3101.4015.1 | | | |
| FPG4 carrier | | | |
| 3101.8011 | 3101.8012 | 3101.8511 | |

2 Type of change

- Change of markings

3 Detailed description of change

| Old product appearance | New product appearance |
|--|---|
|  |  |

4 Reason of change

- Enhanced rated voltage approved according to UL 4248-1 and CSA C22.2 no. 4248.1

5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

| | | |
|---------------|--------|----------------------------------|
| Form | Yes | Modified marking on product |
| Fit | Yes No | No change for dimension |
| Function | Yes No | No change in function |
| Manufacturing | Yes No | No change for manufacturing site |
| Label | Yes No | No change on label |
| Packaging | Yes No | No change in packaging |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|----------------------------|---------|
| Data Sheet | |

| Product Change Notification | | | | | FPG4 marking change | | |
|-----------------------------|---------------|--------------|-------------|-----------------|---------------------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | D10-010-918 |
| dislercy | 2017-08-02 | 2017-08-02 | nowakfr | 2013402 | B | 1 of 1 | |