

### 1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PGU Type				
02 007 002 0000002326	See list below	Connectors	6061	

List of part numbe	rs affected			
6162.0045	6162.0046	6162.0047	6162.0048	6162.0049
6162.0050	6162.0051	6162.0052	6162.0053	6162.0054
6162.0055	6162.0056	6162.0057	6162.0058	6162.0059
6162.0060	6162.0061	6162.0062	6162.0089	6162.0109
6162.0123	6162.0125	6162.0129	6162.0130	6162.0131
6162.0132	6162.0136	6162.0151	6162.0159	6162.0157
6162.0158	6162.0159	6162.0100	6162.0168	6162.0170
6162.0172	6162.0175	6162.0177	6162.0178	6162.0181
3-100-757	3-100-885	6162.0083	3-102-988	3-102-989
3-103-455	3-107-592			

### 2 Type of change


Standards update and modification of approval marks.


# 3 Detailed description of change



Engineering Documentation			PCN 6061 Appliance Inlet				
owner	creation date	release date	released by	change order no	rev	page	D40 005 400
lokhanze	28.04.2018	09.11.2018	limachcl	2016052	Α	1 of 2	D10-025-138







# 4 Reason of change

Standards update according to the new UL/CSA 60320-1

#### 5 Release date

The change will be rolled-out starting ww 17/2018 and lasts approx. 6 months depending on the variant. Products manufactured before as well as after this date still have a valid approval certificate.

### 6 Impact of change and recommended action

Form Yes Replacement of UR and cCSAus mark with combined cURus mark.

Fit No Function No Manufacturing No -

Label Yes Replacement of UR and cCSAus mark with combined cURus mark.

Packaging No -

### 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 6061	

Engineering Documentation			PCN 6061 Appliance Inlet				
owner	creation date	release date	released by	change order no	rev	page	D40 005 400
lokhanze	28.04.2018	09.11.2018	limachcl	2016052	Α	2 of 2	D10-025-138