

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	005	016	0000001164	See list below	Connectors	KM	
02	006	016	0000001533	See list below	Connectors	KMF	
02	005	115	0000001137	See list below	Connectors	CMF	
02	005	016	0000001210	See list below	Connectors	6762	


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

See detailed List of Part numbers at the end of the document

2 Type of change

- Change of production process
- 2nd source for built-in line switch to secure availability and delivery to customers.

3 Detailed description of change



- Change: 2nd source for the built-in line switch
The built-in line switch can be delivered by 2 different suppliers from now on (switches are technically identical according SCHURTER Specifications)

4 Reason of change

- Production process improvement
Identical built-in line switch integration successfully accomplished to overcome difficulties in supply.

2nd Source built-in line switch Approval Files:

- ENEC File Number ENEC-03935
- UL File Number E524325

5 Release date

The change will be rolled-out starting ww 14/2022 (Date code 2214 or higher on label).

Product Change Notification					PCN KM/KMF/CMF/6762		
owner	creation date	release date	released by	change order no	rev	page	D10-063-055
kummerpa	07.02.2022	15.02.2022	muehlema	2023496	A	1 of 2	

6 Impact of change and recommended action

- Form
- Fit
- Function
- Manufacturing Note: 2nd source for built-in line switch with updated approvals
- Label
- Packaging

7 Reference Documents / Attachments

Kind of document	Document Title
Data Sheet	Type KM
Data Sheet	Type KMF
Data Sheet	Type CMF
Data Sheet	Type 6762

List of part numbers affected for type KM			
KM00.1105.11	KM01.1205.11		
KM00.1105.1101			
KM00.1105.1102			
KM00.1205.11			
KM00.1405.11			
KM00.2105.11			
KM00.2205.11			
KM00.3100.1101			
KM01.1105.11			
KM01.1105.1101			

List of part numbers affected for type KMF			
KMF0.2113.11	KMF1.1123.11	KMF1.1191.1102	KMF1.1263.11
KMF0.2123.11	KMF1.1123.1101	KMF1.1193.11	KMF1.1291.11
KMF0.2143.11	KMF1.1123.1102	KMF1.1193.1103	KMF1.1293.11
KMF0.2163.11	KMF1.1123.1104	KMF1.1211.11	
KMF0.2193.11	KMF1.1141.11	KMF1.1213.11	
KMF0.2293.11	KMF1.1143.11	KMF1.1221.11	
KMF1.1111.11	KMF1.1161.11	KMF1.1223.11	
KMF1.1113.11	KMF1.1161.1101	KMF1.1241.11	
KMF1.1121.11	KMF1.1163.11	KMF1.1243.11	
KMF1.1121.1101	KMF1.1191.11	KMF1.1261.11	

List of part numbers affected for type CMF			
CMF2.1015.11			
CMF2.1015.12			

List of part numbers affected for type 6762			
4304.6051	3-128-296		
4304.6064	3-128-329		
4304.6072	3-131-824		
4304.6120	3-134-743		
4304.6169			
3-101-048			
3-103-816			
3-120-523			
3-122-687			
3-127-408			

Product Change Notification					PCN KM/KMF/CMF/6762		
owner	creation date	release date	released by	change order no	rev	page	D10-063-055
kummerpa	07.02.2022	15.02.2022	muehlema	2023496	A	2 of 2	