

1 Products affected


Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	005	116	0000001132	KP01.1XXX.01		KP01 (FH)	
02	005	116	0000001133	KP01.10XX.01 KP01.10XX.06		KP01 (outlet)	
02	005	116	0000001134	KP01.11XX.XX KP01.12XX.XX KP01.16XX.XX KP01.17XX.XX		KP01 (switch)	

*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)


2 Type of change

Approval marks SEV and SEMKO removed, CCC new.


Old label:



KP01 (outlet)






KP01 (switch)



KP01 (FH)

New label:



3 Reason of change

Approval marks SEV and SEMKO removed, CCC new.

4 Released date

Release for production
Depletion of stock is not terminated

Ww11/2012

5 Impact of change and recommended action

Form: N/A
Fit: N/A
Function: N/A
Production Site: N/A
Product label: Approval marks SEV and SEMKO removed, CCC new.

KP01					0118.2098	
Creation date:	Created by:	Release date:	Released by:	Notification No.	Index	Page
02.03.2012 14:32:12	hoa	05.03.2012	hoa	23214	-	1 von 1