

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	043	0000002295	4795.0000	Connectors	4795 Appliance Outlet

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)



**2 Type of change**

With the production of the new tool the Tension relief has changed too.

**3 Detailed description of change**

The flange of the Tension relief was round, what caused an insufficient hold of the Tension relief.

NEW the flange of the Tension relief is square, what improves the holding of the Tension relief.



**4 Reason of change**

According to 60320-1 sect. 22 (Cords and their connection) the Tension relief with the round flange could fall out. As there have been made new tools for the moulding parts the holding of the Tension relief got improved with a square flange.

**5 Released date**

Release of production

Ww 37

**6 Impact of change and recommended action**

Form: Square flange on the Tension relief  
 Fit: n/a  
 Function: Better holding of the Tension relief  
 Production Site: n/a  
 Product Label: n/a

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
PCN	0118.2109	Tension relief new with square flange

4795					0118.2126	
creation date	created by	release date	released by	notification no.	revision	page
2012-09-13	sha	2012-09-14	sha	23911		1 of 1