

1 Products affected

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU / PG	PGU	Type				
02	007	003	0000002298	4798.xxxx	Connector	4798
02	007	003	0000002298	4798.xxxx.xx	Connector	4798


*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

2 Type of change


A new tool has been made.
Modification of the approval marks.

3 Detailed description of change

Old version



New version



4 Reason of change

With the production of the new tool the approval marks got updated.
New approvals ENEC10 and CCC.

5 Released date

Release of production

ww 40/2012

6 Impact of change and recommended action

Form: New approval marks
Fit: n/a
Function: n/a
Production Site: New tool
Product Label: n/a

7 Reference Documents / Attachments

Kind of document	Document number	Remarks
none		

4798					0118.2113	
creation date	created by	release date	released by	notification no.	revision	page
2012-07-20	hollenpe	2013-03-15	bisanger	23726	-	1 of 1