

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU   PG	PGU	Type				
02	005	016	0000001169	See list below	Power Entry Modules w/o Filters	DD11

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected					
DD11.0111.1110	DD11.0111.1111	DD11.0113.1110	DD11.0113.1111	DD11.0114.1110	DD11.0114.1111
DD11.0121.1110	DD11.0121.1111.01	DD11.0121.1111	DD11.0123.1110	DD11.0123.1111	
DD11.0124.1110	DD11.0124.1111	DD11.0131.1110	DD11.0131.1111		

**2 Type of change**



Enlarging of the fusedrawer slot.

**3 Detailed description of change**

Fusedrawer slot enlarged.

New

Old



DD11					0118.2182	
creation date	created by	release date	released by	notification no.	revision	page
2013-07-29	hollenpe	2013-12-04	hollenpe	25005	-	1 of 2

**4 Reason of change**

Implementation of V-Lock cord retention function.  
 Precondition: new fusedrawer required (see PCN 0118.2133).

**5 Released date**

The change will be rolled-out individually by all part numbers affected starting ww 02/2014 and last approx. 9 months.

**6 Impact of change and recommended action**

Form: New form is fully backwards compatible (can be used with old fusedrawer, see PCN 0118.2133).  
 Fit: n/a  
 Function: The new expanded slot allows applying V-Lock cord sets for cord retaining (new fuse drawer necessary).  
 Production Site: n/a  
 Product Label: n/a

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
<a href="#">PCN fusedrawer 2</a>	0118.2133	
<a href="#">Data sheet Fusedrawer 2</a>		
<a href="#">Datasheet DD11</a>		

DD11					0118.2182	
creation date	created by	release date	released by	notification no.	revision	page
2013-07-29	hollenpe	2013-12-04	hollenpe	25005	-	2 of 2