

Date: September 27, 2016

**PCN- 27785**

## Product Change Notification

Change Title:

REMOVE HOLE IN TERMINALS FOR RA\*PC10\* SERIES HIGH AMP POWER JACKS

Product (s) Affected:

RAPC10, RAPC10P, RAPC10PS, RAPC10S

RASPC10, RASPC10P, RASPC10PS, RASPC10S

Reason for Change:

DISCOURAGE USE FOR LEAD WIRE ATTACH. THE TERMINALS CAN FATIGUE AND CRACK IF OVERMANIPULATED DURING WIRE ATTACH OR DUE TO MANIPULATION OR VIBRATION OF UNSUPPORTED WIRING. PARTS ARE SUPPORTED FOR PCB ASSEMBLY.

Description of Change:

REMOVE THE HOLES IN THE TERMINALS (SHUNT AND SLEEVE). A SMALL HOLE WILL REMAIN IN THE TIP TERMINAL, THE SAME AS THE STANDARD POWER JACK.

Estimated Schedule of Change:

IMMEDIATE - OCTOBER 1, 2016

---

### Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: \_\_\_\_\_

Signature

(Electronic Signature is acceptable)

Print

Company: \_\_\_\_\_

Location: \_\_\_\_\_

Title: \_\_\_\_\_

Date: \_\_\_\_\_

Please return the signed PCN form to the attention of:

**Switchcraft** Customer Service Department

[jpulliam@switchcraft.com](mailto:jpulliam@switchcraft.com)

FAX: 773-792-2129