



08-Oct-2014

PCN #:E-14-014715

Subject:TERMINAL, RING TONGUE, PIDG, NYLON, IR AND MISCELLANEOUS 12-

Description of Change: REPLACING VENDOR DISCONTINUED NYLON 6/6 RESIN WITH STANDARD PIDG NYLON 6/6 RESIN. THE FOLLOWING PART NUMBERS ARE IMPACTED BY THIS CHANGE ALL OTHER PART NUMBERS ARE REVISION LEVEL CHANGES ONLY TO MEET INTERNAL SPECIFICATION REQUIREMENTS.
321620,151469,134017-1,327654,329391,330896,330896-2,327743,1-327743-1,323682,2-323682-1,322724,320631,2-320631-1,8-320631-2,320630,2-320630-2,8-320630-1,320627,1-320627-0,8-320627-2,36203,35634,2-35634-1,35316,35106,2-35106-1,8-35106-2,34974,2-34974-1,34810,1-34810-1,34806,2-34806-2,2-34806-3,8-34806-2,34805,2-34805-1,8-34805-1,33734,640174-1,2-320577-1,2-320577-2,2-320576-2,2-320576-3,2-320569-5,2-320569-6,2-320568-2,2-320568-3,134019-1,52077-1,52077-2,2-36161-3,2-36161-4,2-36161-5,2-36161-6,2-36161-8,53057,53056,53055,53054,53078,53051,53050,53049,2-326875-4,2-326875-5,2-323916-3,2-323914-2,1958448-1,2-328976-1,2-328976-2,2-320575-2,2-320575-3,2-320564-1,2-320564-2,2-320563-3,2-320563-4,2-320561-3,2-320561-4,134122-1,134021-1,52274,52274-1,51864-6,

Reason: Product Improvement.

51864-7,51864-8,51864-9,1-51864-0,1-51864-1,1-51864-3,1-51864-5,1-51864-7,6-51864-1,7-51864-1,8-51864-1,9-51864-1,9-51864-5,2-328975-1,2-328975-2,2-328975-3,2-320573-1,2-320573-2,2-320573-3,2-320572-2,2-320572-3,2-320572-4,2-320571-3,2-320571-4,2-320571-5,1-320551-2,1-320551-3,1-320551-4,1-320551-5,1-320551-7,1-320551-8,7-320551-1,8-320551-1,131644-1,52307,52307-1,52284-2,52284-3,52284-4,52273,52273-1,52273-2,8-52273-1,9-52273-1,51863-2,51863-3,51863-4,51863-5,51863-6,51863-7,8-51863-1,9-51863-1,2-36153-3,2-36153-4,2-36153-5,2-36153-6,2-36153-8,2-36153-9,7-36153-1,8-36153-1,9-36153-1,2-36149-3,2-36149-4,2-36149-5,7-36149-1

Impact of Change:form - fit - function

Key Dates:

Contact By Date:27-Feb-2015

Implementation Date:27-Feb-2015

Product Affected

1-320551-4

320630

(Alias Part Numbers:

"668-1023-04")

326875

(Alias Part Numbers:

"4-00520-2060")

320564

(Alias Part Numbers:

"A69728-000"

"AMPS-0-0320564-0")

2-36153-2

2-320630-2

34806

(Alias Part Numbers:

"AMP-0-0034806-0"

"C46815-000")

328975

2-320572-1

36161

(Alias Part Numbers:

"AMP-0-0036161-0"

"E87226-000")

320568

(Alias Part Numbers:

"F51639-001")

1-51864-0

(Alias Part Numbers:

"AMPS-1-0051864-0"

"E21090-000")

2-328975-2

51863-1

323914

(Alias Part Numbers:

"2-14492-4220")

Product Affected

2-36153-3

1-320551-1

51864-9

51864-4

2-320569-3

2-320573-4

36153

(Alias Part Numbers:

"E15470-000"

"AMP-0-0036153-0"

"2-14492-1160")

51864-7

53055

51864-2

2-36153-5

320631

320571

(Alias Part Numbers:

"CN5242-000"

"AMP-0-0320571-0"

"2-14492-3160")

51863-2

2-320572-3

320563

(Alias Part Numbers:

"D12388-000"

"AMPS-0-0320563-0")

2-320563-3

52274

1-51864-1

51864-8

323916

(Alias Part Numbers:

"2-14492-8220")

36149

(Alias Part Numbers:

"2-42937-0285")

52273-1

320561

(Alias Part Numbers:

Product Affected

"CF0318-000"

"AMP-0-0320561-0"

"500-095-0000"

"2-14492-6140")

2-320568-1

(Alias Part Numbers:

"403802838")

2-320571-2

2-320575-2

2-320571-3

51864-5

2-320561-3

35106

2-36149-5

34810

(Alias Part Numbers:

"AMP-0-0034810-0"

"D14886-000")

51863-4

320569

(Alias Part Numbers:

"A22724-000"

"AMPS-0-0320569-0")

2-320571-4

320551

(Alias Part Numbers:

"F14692-001"

"AMP-0-0320551-0"

"500-095-0002"

"2-14492-8160")

320577

(Alias Part Numbers:

"D24803-000"

"HUB-RINGTERM-12-10-3/8SD")

51864-6

2-320569-6

2-36161-8

320573

53057

320572

Product Affected

(Alias Part Numbers:

"EF5287-000"

"AMP-0-0320572-0")

2-36161-3

2-36161-4

1-320551-3

2-36161-2

(Alias Part Numbers:

"402624795")

1-320551-2

51864-1

51864

2-36153-4

2-320563-2

34805

320575

2-320631-1

52273

2-323914-1

320576

51863-3

51863

(Alias Part Numbers:

"4-16211-9784")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.