



13-Aug-2015

PCN #:E-15-011086

**Subject:**RF/Coax Connectors with low or no recent sales activity.

**Description of Change:** Part Obsolescence. Note: some parts on this Engineering Change are not obsolete but are on drawings that are being revised due to the obsolescence of other parts on the same drawing. The following part numbers are being discontinued (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant differences described. Please verify all substitute or alternate part numbers provided are suitable for your specific application. Drawings are available via [TE.com](http://TE.com).

**Reason:** Discontinuance.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**30-Oct-2015

**Implementation Date:**30-Oct-2015

**Last Order Date:** 30-Oct-2015

**Last Ship/EOL Date:**29-Jan -2016

**Product Affected**

2-331350-6

5-331350-3

6-331693-2

1-221265-0

2-331350-5

1757333-1

1-221265-1

The dates on the product change notification (PCN) are best estimate dates

determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.