



16-Dec-2015

PCN #:P-15-012431

Subject:Mass Parts Obsolescence

Description of Change: Parts not in stock or showing as having any global stock movements for two years to be made obsolete.

Reason: Part status change.Part status change.Part status change to help with tidying up of REACH/RoHS data. Dates amended compared to previous PCN.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:14-Dec-2015

Last Ship/EOL Date:15-Dec-2015

Product Affected

884415-001

(Alias Part Numbers:

"9-1196882-8"

"TV06RW-11-01-PD-L/C")

Recommended Replacement

C73724-000

(Alias Part Numbers:

"8-1201277-5"

"HSJC0/1-0/22615K")

682079-000

(Alias Part Numbers:

"5-1195361-9"

"D38999/24WF11SN")

Product Affected

Recommended Replacement

1-161209-3
CH1337-000
(Alias Part Numbers:
"HSJC0-26802K"
"4-1899532-5")

CV0935-000
(Alias Part Numbers:
"6-1899735-8"
"KHKB-26411")

416637-000
(Alias Part Numbers:
"8-1193139-3"
"D38999/26WJ35SA")

D16577-000
(Alias Part Numbers:
"4-1202064-3"
"HSJC0/3-0/23987F")

E67020-000
(Alias Part Numbers:
"7-1201713-3"
"HSJC0/14-0/23381F")

CA6876-000
(Alias Part Numbers:
"HSJC0/19-0/24661K"
"1-1899128-8")

E26089-000
(Alias Part Numbers:
"1-1200624-5"
"HBJC3/6-0/21006G")

269257-001
(Alias Part Numbers:
"3-1191987-2")

Product Affected
"PTG55A-10-7-SN")

Recommended Replacement

CV1463-000
(Alias Part Numbers:
"KHKB-25969")

D96759-000
(Alias Part Numbers:
"7-1200624-2"
"HSJC0/5-0/21036G")

D43133-000
(Alias Part Numbers:
"1-1899079-0"
"HSJC0/1-0/24327K")

CH4986-000
(Alias Part Numbers:
"4-1899654-1"
"HSJC0-27458K")

CV0516-000
(Alias Part Numbers:
"8-1899722-9"
"HBJC4-27627F")

CF7728-001
(Alias Part Numbers:
"10-241802-127"
"6-1899233-8")

D24003-001
(Alias Part Numbers:
"7-1201441-9"
"602GB06E12-10SN(416)")

CG6761-000
(Alias Part Numbers:
"HSJC0-25538K"
"7-1899268-2")

Product Affected

Recommended Replacement

CH2997-000

(Alias Part Numbers:
"2-1899602-5"
"KHKB-27172")

CV1301-000

(Alias Part Numbers:
"5-1899751-0"
"KHKB-26464R11243")

CH1001-001

(Alias Part Numbers:
"TV06RW-11-02PN(W52)"
"2-1899522-5")

861754-000

(Alias Part Numbers:
"8-1199529-7"
"HSJC0/3-0/19591K")

CH1757-001

(Alias Part Numbers:
"9-1899551-9"
"RS-290-4588")

CH2805-000

(Alias Part Numbers:
"2-1899593-3"
"KHKB-27158")

314889-001

(Alias Part Numbers:
"1-1192383-0"
"CECC75201002-
CD35MCAA01G")

CV0339-000

(Alias Part Numbers:
"7-1899711-6")

Product Affected
"KHKB-27576")

Recommended Replacement

854597-001
(Alias Part Numbers:
"5-1196661-1"
"CECC75201002-
AD97FCNA01G")

CV0306-000
(Alias Part Numbers:
"1899711-1"
"KHKB-27600")

318888-000
(Alias Part Numbers:
"8-1198300-8"
"D38999/26WC4SN")

CH3530-000
(Alias Part Numbers:
"6-1899613-2"
"HSJC0-27237K")

CH1350-000
(Alias Part Numbers:
"KHKB-26808"
"6-1899532-0")

CV0337-000
(Alias Part Numbers:
"7-1899711-4"
"KHKB-27574")

CH1357-000
(Alias Part Numbers:
"HSJC0-26812K"
"7-1899532-1")

368559-000
(Alias Part Numbers:

Product Affected

Recommended Replacement

"3-1192762-9"
"HSJC0/6-6/14177K")

011315-000
(Alias Part Numbers:
"5-1190089-5"
"D38999/26WH21PN")

CJ7445-001
(Alias Part Numbers:
"M39029/58-353"
"1899304-8")

9-161117-3
CN6323-000
(Alias Part Numbers:
"7-1899489-2"
"KHKB-26045")

CH3597-000
(Alias Part Numbers:
"2-1899615-3"
"HSJC0-27179K")

CV0266-001
(Alias Part Numbers:
"4-1899710-9"
"418-5052/11-35SB(W52W280)")

CJ5941-001
(Alias Part Numbers:
"OC-015"
"1899294-9")

595385-000
(Alias Part Numbers:
"4-1194708-3"
"D38999/26WE35SA")

CN8125-000

Product Affected
(Alias Part Numbers:
"HSJC0-26038K"
"6-1899499-2")

Recommended Replacement

CH2977-000
(Alias Part Numbers:
"8-1899600-2"
"KHKB-834747")

F51723-001
(Alias Part Numbers:
"3-1201549-2"
"102-1951")

CJ0048-000
(Alias Part Numbers:
"HSJC0/1-0/24603K"
"8-1899245-0")

CM3754-001
(Alias Part Numbers:
"TR1807PFS1NBE"
"5-1899410-9")

E91378-000
(Alias Part Numbers:
"1-1201489-8"
"HSJC0/2-0/22183K")

CV2035-000
(Alias Part Numbers:
"KHKB-8500")

184941-000
(Alias Part Numbers:
"1-1191343-6"
"62GB-56T-16-26S")

C54398-000
(Alias Part Numbers:

Product Affected
"HSJC0/108-4/24272K"
"3-1899067-6")

Recommended Replacement

5-161107-0
CP8104-000
(Alias Part Numbers:
"HSJC0-26922K"
"7-1899555-3")

CH1056-001
(Alias Part Numbers:
"JT02RE-14-35SA-023"
"4-1899523-3")

CV2021-000
(Alias Part Numbers:
"9-1899767-2"
"KHKB-27814")

CG6752-000
(Alias Part Numbers:
"HSJC0-25529K"
"4-1899268-7")

699906-000
(Alias Part Numbers:
"HSJC0/4-1/24343K"
"8-1899068-6")

CV1294-000
(Alias Part Numbers:
"1899751-8"
"KHKB-27559R39030")

366453-001
(Alias Part Numbers:
"7-1192747-5"
"488-208")

CH2721-000

Product Affected
(Alias Part Numbers:
"1-1899590-9"
"HSJC0-27125K")

Recommended Replacement

CA7681-001
(Alias Part Numbers:
"508/1/31026/140"
"1899132-3")

D77674-000
(Alias Part Numbers:
"HSJC0/4-4/24028F")

C15015-000
(Alias Part Numbers:
"3-1200625-4"
"HSJC0/5-0/21046G")

F39307-000
(Alias Part Numbers:
"6-1201547-5"
"D38999/20WD19PN")

605163-001
(Alias Part Numbers:
"3-1194788-1"
"CECC75201002-AB35FCNA01G")

CH3339-000
(Alias Part Numbers:
"2-1899610-4"
"KHKB-27254")

811703-000
(Alias Part Numbers:
"5-1196313-6"
"D38999/26WA98SA")

8-161117-4
CV0055-001

Product Affected

Recommended Replacement

(Alias Part Numbers:

"5-1899704-1"

"418-5052/11-98SB(W52W280)")

CH1338-000

(Alias Part Numbers:

"KHKB-26802"

"4-1899532-6")

329669-000

(Alias Part Numbers:

"1192492-6"

"D38999/26WH53SN")

CJ3056-000

(Alias Part Numbers:

"D38999/26FC35SA"

"8-1899270-5")

EB1256-000

(Alias Part Numbers:

"D38999/26#E26PA-ZNCO")

822327-000

(Alias Part Numbers:

"1-1196413-7"

"D38999/20WC08PN")

646163-001

(Alias Part Numbers:

"418-1406-9"

"1195103-8")

CV1281-000

(Alias Part Numbers:

"6-1899750-1"

"KHKB-27682")

CN7743-000

(Alias Part Numbers:

Product Affected
"HSJC0-25984K"
"5-1899497-7")

Recommended Replacement

CV1027-000
(Alias Part Numbers:
"6-1899740-7"
"KHKB-27664")

CA6704-000
(Alias Part Numbers:
"HSJC0-23942K/1-CS2106"
"5-1899126-9")

CH1767-000
(Alias Part Numbers:
"6-1899552-4"
"KHKB-26900")

CH2742-000
(Alias Part Numbers:
"3-1899590-6"
"KHKB-26936")

CN7329-001
(Alias Part Numbers:
"BACC63BP14D7PN"
"9-1899495-2")

CH2649-000
(Alias Part Numbers:
"7-1899588-8"
"KHKB-815933")

F69559-000
(Alias Part Numbers:
"1-1202092-4"
"HSJC0/1-0/22823K")

CH4290-000
(Alias Part Numbers:

Product Affected

Recommended Replacement

"1899636-1"
"KHKB-27339")

CL0039-001
(Alias Part Numbers:
"163-448"
"8-1899316-0")

CF2763-001
(Alias Part Numbers:
"130106"
"1-1899206-4")

CV0583-001
(Alias Part Numbers:
"2-1899726-6"
"GF062HDC4LNES")

CH0815-000
(Alias Part Numbers:
"KHKB-26648"
"3-1899517-7")

CG6753-000
(Alias Part Numbers:
"HSJC0-25530K"
"4-1899268-8")

CN6328-000
(Alias Part Numbers:
"7-1899489-7"
"KHKB-26040")

F45815-001
(Alias Part Numbers:
"454-283"
"4-1199706-8")

CN0912-001
(Alias Part Numbers:

Product Affected
"180-091NFH7-13-4PN"
"9-1899459-4")

Recommended Replacement

CN9320-000
(Alias Part Numbers:
"HSJC0-25998K"
"7-1899506-8")

CL8382-001
(Alias Part Numbers:
"5-1899370-7"
"KTFG-4518")

CJ3066-000
(Alias Part Numbers:
"62GB-56TG16-26S(416)"
"9-1899270-4")

C35024-000
(Alias Part Numbers:
"3-1200414-6"
"D38999/24WE35PC")

CH3203-000
(Alias Part Numbers:
"6-1899607-7"
"HSJC0-27142K")

E16084-000
(Alias Part Numbers:
"1-1200624-0"
"HBJC3/11-0/21037G")

042652-000
(Alias Part Numbers:
"9-1200085-6"
"HSJC0/5-2/20093F")

CH1815-000
(Alias Part Numbers:

Product Affected
"1-1899554-1"
"HSJC0-26903K")

Recommended Replacement

628207-000
(Alias Part Numbers:
"8-1194973-1"
"D38999/26WB1PC")

CH5194-000
(Alias Part Numbers:
"2-1899660-2"
"KHKB-27380")

C56886-000
(Alias Part Numbers:
"8-1200624-2"
"HSJC0/2-0/21212G")

CJ8604-000
(Alias Part Numbers:
"KHKB-25578/1-MS"
"1-1899309-8")

A00265-000
(Alias Part Numbers:
"9-1201207-4"
"KTFA-4440")

CH2755-000
(Alias Part Numbers:
"8-1899590-6"
"HBJC0-27133F")

CV2663-000
(Alias Part Numbers:
"KHKB-27383R49552")

CM8398-001
(Alias Part Numbers:
"3-1899441-4")

Product Affected
"RS521-2/02")

Recommended Replacement

D05494-000
(Alias Part Numbers:
"HBJC7/12-6/24179K"
"3-1899066-1")

CJ0597-001
(Alias Part Numbers:
"AB05-6100-10-06SN00"
"7-1899248-1")

CG6699-000
(Alias Part Numbers:
"HSJC0-25476K"
"9-1899265-4")

CH1907-000
(Alias Part Numbers:
"2-1899559-3"
"HSJC0-26955F")

004793-000
(Alias Part Numbers:
"6-1190036-5"
"D38999/24WC98SN")

EB1308-000
(Alias Part Numbers:
"D38999/26#J4PN-ZNCO")

CH3336-000
(Alias Part Numbers:
"2-1899610-1"
"KHKB-27251")

161204-9
983045-000
(Alias Part Numbers:
"2-1197595-2")

Product Affected
"HSJC0/4-2/16711K")

Recommended Replacement

CN7579-000
(Alias Part Numbers:
"KHKB-25984"
"1899497-2")

CN9230-000
(Alias Part Numbers:
"HBJC4-26692F"
"1-1899506-3")

CJ1672-000
(Alias Part Numbers:
"HSJC0/2-2/24130K"
"9-1899254-6")

CN2289-001
(Alias Part Numbers:
"193376-0160"
"3-1899469-8")

CV0068-000
(Alias Part Numbers:
"8-1899704-0"
"KHKB-27485")

C58798-000
(Alias Part Numbers:
"HBJC8/20-3/24286K"
"4-1899066-2")

CH2565-000
(Alias Part Numbers:
"6-1899585-5"
"KHKB-26402")

491119-000
(Alias Part Numbers:
"7-1193673-6")

Product Affected
"D38999/26WE26SN")

Recommended Replacement

CH3098-000
(Alias Part Numbers:
"2-1899605-9"
"KHKB-836508")

CF0050-001
(Alias Part Numbers:
"MS3456LS-36-52P"
"9-1899147-4")

CH1170-000
(Alias Part Numbers:
"KHKB-26707"
"1-1899527-1")

C19625-000
(Alias Part Numbers:
"HSJC0/5-1/24270K"
"1899069-2")

CH4702-000
(Alias Part Numbers:
"1-1899647-6"
"KHKB-16739")

310098-000
(Alias Part Numbers:
"3-1200084-8"
"HSJC0/5-2/20034F")

C67357-000
(Alias Part Numbers:
"9-1201283-1"
"GD400341-0316-00")

CN4589-000
(Alias Part Numbers:
"8-1899480-4")

Product Affected
"KHKB-26374")

Recommended Replacement

CH2038-001
(Alias Part Numbers:
"6-1899564-8"
"608-36T18-32SC")

CH2546-000
(Alias Part Numbers:
"4-1899585-6"
"KHKB-27121LU")

CH5318-000
(Alias Part Numbers:
"3-1899668-4"
"HSJC0-27473K")

032043-000
(Alias Part Numbers:
"4-1190248-6"
"HBJC3/4-0/16713K")

CN8039-000
(Alias Part Numbers:
"KHKB-26587"
"1-1899499-3")

CH3237-001
(Alias Part Numbers:
"1899608-6"
"D38999/26#B2SB-ZNCO")

CL5321-000
(Alias Part Numbers:
"KHKB-25596/2-MS"
"8-1899352-4")

CN3575-001
(Alias Part Numbers:
"BACC63BV14B7S8")

Product Affected
"6-1899475-9")

Recommended Replacement

CH2406-000
(Alias Part Numbers:
"5-1899581-1"
"HBJC4-25078K")

CN1942-000
(Alias Part Numbers:
"7-1899466-1"
"KHKB-25548")

CG6708-000
(Alias Part Numbers:
"HSJC0-25485K"
"1899266-5")

CH3315-000
(Alias Part Numbers:
"9-1899609-4"
"HSJC0-27263K")

161612-000
(Alias Part Numbers:
"9-1199142-6"
"D38999/26WD5PA")

CH1549-000
(Alias Part Numbers:
"KHKB-26523"
"1899542-4")

CH2892-000
(Alias Part Numbers:
"1899598-6"
"KHKB-23123")

A62628-000
(Alias Part Numbers:
"1-1200625-3")

Product Affected
"HSJC0/10-0/21026G")

Recommended Replacement

CH2728-000
(Alias Part Numbers:
"2-1899590-5"
"KHKB-27125")

CN6338-000
(Alias Part Numbers:
"8-1899489-4"
"HSJC0-26040K")

CM8479-000
(Alias Part Numbers:
"9-1899441-1"
"KHKB-26353")

416415-6
416415-8
CH2155-000
(Alias Part Numbers:
"1-1899569-2"
"KHKB-12430")

CN2439-000
(Alias Part Numbers:
"602GB05EG10-6S(586)"
"6-1899470-5")

519232-000
(Alias Part Numbers:
"5-1199530-0"
"HSJC0/10-4/19572K")

C69498-000
(Alias Part Numbers:
"3-1202089-1"
"HSJC0/18-0/24096F")

CH4421-000

Product Affected
(Alias Part Numbers:
"8-1899638-3"
"KHKB-25408")

Recommended Replacement

CG6731-000
(Alias Part Numbers:
"HSJC0-25508K"
"1-1899268-0")

CH2079-001
(Alias Part Numbers:
"9-1899565-4"
"APH21-033123-546")

CN5508-001
(Alias Part Numbers:
"RS-541-4599"
"8-1899486-9")

167551-001
(Alias Part Numbers:
"9-1191219-4"
"D38999/20WA35SN")

CH3260-000
(Alias Part Numbers:
"4-1899608-3"
"HSJC0-27227F")

F72814-000
(Alias Part Numbers:
"6-1202064-9"
"HSJC0/9-8/23967F")

CF7723-001
(Alias Part Numbers:
"120R-1/4-WATT"
"6-1899233-5")

D03521-000

Product Affected
(Alias Part Numbers:
"1200625-1"
"HSJC0/5-0/21051G")

Recommended Replacement

129617-000
(Alias Part Numbers:
"3-1190941-2"
"D38999/26WF35SA")

D14810-000
(Alias Part Numbers:
"1200625-7"
"HSJC0/4-0/21235G")

CV1461-000
(Alias Part Numbers:
"KHKB-25963")

CN5405-000
(Alias Part Numbers:
"2-1899486-1"
"KHKB-26042")

9-161117-0
C16916-000
(Alias Part Numbers:
"HBJC2/8-0/24033F")

CN4588-000
(Alias Part Numbers:
"8-1899480-3"
"KHKB-26373")

CN5406-000
(Alias Part Numbers:
"2-1899486-2"
"KHKB-26046")

932403-000
(Alias Part Numbers:

Product Affected
"2-1197227-0"
"HSJC0/1-0/18221K")

Recommended Replacement

CV1458-000
(Alias Part Numbers:
"2-1899756-1"
"HSJC0-25971K")

C75165-001
(Alias Part Numbers:
"5-1200620-1"
"MS3126E8-2PN")

E83613-000
(Alias Part Numbers:
"6-1200623-5"
"HSJC0/5-0/21050G")

770313-000
(Alias Part Numbers:
"7-1196001-5"
"D38999/26WG35SA")

CH4609-001
(Alias Part Numbers:
"1-1899645-3"
"D38999/26#G75SN-ZNCO")

A27399-000
(Alias Part Numbers:
"HSJC0/8-0/24155K"
"1-1899069-7")

CV0195-000
(Alias Part Numbers:
"1899708-9"
"KHKB-27559")

CH1326-000
(Alias Part Numbers:

Product Affected

Recommended Replacement

"KHKB-26796"
"3-1899532-4")

CJ7107-001
(Alias Part Numbers:
"181-111"
"3-1899302-3")

158701-000
(Alias Part Numbers:
"8-1191146-0"
"HSJC0/38-13/13734K")

CF0369-001
(Alias Part Numbers:
"7-1899159-6"
"418-6031-13P1201-09")

EB1143-000
(Alias Part Numbers:
"D38999/20#F32SN-ZNCO")

CH3332-000
(Alias Part Numbers:
"1-1899610-6"
"KHKB-27247")

CH1351-000
(Alias Part Numbers:
"HSJC0-26809K"
"6-1899532-2")

CL3938-001
(Alias Part Numbers:
"CR06180-6"
"6-1899341-5")

CV0814-001
(Alias Part Numbers:
"7-1899732-4"

Product Affected
"418-6032-17P0601-04")

Recommended Replacement

D54437-000
(Alias Part Numbers:
"5-1201836-7"
"HBJC6/12-0/23601F")

CH2541-001
(Alias Part Numbers:
"4-1899585-1"
"RS-267-3694")

CJ2766-001
(Alias Part Numbers:
"SB-ORD-130"
"5-1899266-9")

CH5181-000
(Alias Part Numbers:
"1899660-9"
"KHKB-27367")

CM8397-001
(Alias Part Numbers:
"RS-231-1374"
"3-1899441-2")

CH0764-000
(Alias Part Numbers:
"KHKB-736306"
"7-1899515-4")

CV0316-000
(Alias Part Numbers:
"1-1899711-0"
"KHKB-27610")

A72873-000
(Alias Part Numbers:
"6-1200318-1")

Product Affected
"HBJC4/4-0/20606F")

Recommended Replacement

CH4530-000
(Alias Part Numbers:
"7-1899640-1"
"KHKB-27343HS")

CH7803-000
(Alias Part Numbers:
"5-1899685-6"
"KHKB-16687")

A08308-001
(Alias Part Numbers:
"5-1201445-4"
"5940-99-971-9170")

C99312-001
(Alias Part Numbers:
"5-1201510-5"
"534-783")

CJ0536-001
(Alias Part Numbers:
"HCPH380"
"5-1899248-0")

CM1009-001
(Alias Part Numbers:
"MS3106E-40-56P"
"4-1899387-3")

042749-000
(Alias Part Numbers:
"8-1190327-9"
"HSJC0/1-0/18218K")

CJ8561-001
(Alias Part Numbers:
"M80-8890405")

Product Affected
"8-1899308-9")

Recommended Replacement

CH0819-000
(Alias Part Numbers:
"KHKB-26708"
"4-1899517-1")

CH1165-000
(Alias Part Numbers:
"KHKB-26702"
"1899527-6")

C56560-000
(Alias Part Numbers:
"1-1201760-5"
"HSJC0/2-0/23119K")

CH3350-000
(Alias Part Numbers:
"3-1899610-5"
"KHKB-27265")

979557-000
(Alias Part Numbers:
"6-1197566-8"
"HSJC0/1-0/18223K")

CG6705-000
(Alias Part Numbers:
"HSJC0-25482K"
"1899266-2")

CV1278-000
(Alias Part Numbers:
"5-1899750-8"
"KHKB-27679")

CH4983-001
(Alias Part Numbers:
"3-1899654-8")

Product Affected
"PC10015-06-20-2PA-1-ZB")

Recommended Replacement

336431-000
(Alias Part Numbers:
"3-1192540-3"
"D38999/20WA98SN")

CG6644-000
(Alias Part Numbers:
"HSJC0-25421K"
"3-1899265-0")

CH1575-000
(Alias Part Numbers:
"9-1899543-5"
"HSJC0-26860K")

CL0025-001
(Alias Part Numbers:
"15366021"
"6-1899316-8")

CH4412-000
(Alias Part Numbers:
"3-1899638-7"
"KHKB-25542")

A82097-000
(Alias Part Numbers:
"2-1201852-7"
"HBJC3/14-2/23354K-10")

CH4405-000
(Alias Part Numbers:
"3-1899638-0"
"KHKB-25490")

CN9454-001
(Alias Part Numbers:
"RS-408-9451")

Product Affected

Recommended Replacement

"8-1899507-4")

CH2527-000

(Alias Part Numbers:

"6-1899584-9"

"HSJC0-27120K")

CM9446-001

(Alias Part Numbers:

"PC4D0002-C-19A-1-CZ"

"6-1899448-9")

CN6342-000

(Alias Part Numbers:

"HBJC0/4-2/23302K"

"8-1899489-9")

CH4406-000

(Alias Part Numbers:

"3-1899638-1"

"KHKB-25491")

CN2625-001

(Alias Part Numbers:

"RS-613-9233"

"3-1899471-9")

158482-000

(Alias Part Numbers:

"4-1198852-8"

"D38999/26WH35SC")

D03748-000

(Alias Part Numbers:

"HBJC7/48-6/24234K"

"1899067-5")

CH1219-001

(Alias Part Numbers:

"221C14F22"

Product Affected
"4-1899528-0")

Recommended Replacement

CH1764-000
(Alias Part Numbers:
"6-1899552-1"
"HSJC0-26900K")

913067-000
(Alias Part Numbers:
"1197090-4"
"HSJC0/10-0/12379K")

641617-000
(Alias Part Numbers:
"1-1195071-4"
"HSJC0/3-0/18317K")

CA7244-000
(Alias Part Numbers:
"HSJC0/2-0/24548K"
"9-1899129-3")

CH0760-000
(Alias Part Numbers:
"KHKB-736297"
"7-1899515-0")

CV1495-001
(Alias Part Numbers:
"RS-622-6977")

CH1565-000
(Alias Part Numbers:
"3-1899543-9"
"KHKB-26878")

D12355-000
(Alias Part Numbers:
"9-1200912-7"
"HSJC0/5-0/21564F")

Product Affected**Recommended Replacement**

CV0324-000

(Alias Part Numbers:
"6-1899711-1"
"KHKB-27612")

E04417-001

(Alias Part Numbers:
"7-1201648-8"
"99-0406-75-03")

433159-000

(Alias Part Numbers:
"1193258-5"
"HSJC0/15-8/16718K")

CH4446-000

(Alias Part Numbers:
"1-1899639-3"
"KHKB-25501")

986691-000

(Alias Part Numbers:
"9-1197620-7"
"D38999/26WG41SN")

308585-000

(Alias Part Numbers:
"3-1192337-2"
"D38999/24WJ8AC")

CJ3989-001

(Alias Part Numbers:
"EGG-0K-303-CLL"
"7-1899276-8")

CN7480-000

(Alias Part Numbers:
"KHKB-26036"
"6-1899496-7")

Product Affected

Recommended Replacement

E99542-000

(Alias Part Numbers:
"HSJC0/8-1/24296K"
"2-1899069-3")

CG6817-000

(Alias Part Numbers:
"HSJC0-25594K"
"8-1899269-1")

CG6744-000

(Alias Part Numbers:
"HSJC0-25521K"
"3-1899268-6")

CF0388-000

(Alias Part Numbers:
"HSJC0/12-12/24963K"
"5-1899161-9")

CN0016-000

(Alias Part Numbers:
"KHKB-VCS/CONNECTORS"
"9-1899453-6")

CH2425-000

(Alias Part Numbers:
"7-1899581-0"
"KHKB-25075")

085053-000

(Alias Part Numbers:
"1-1190628-2"
"D38999/24WF35SN")

E84328-000

(Alias Part Numbers:
"3-1201825-2"
"HSJC0/3-0/22180K")

Product Affected**Recommended Replacement**

CH2615-001

(Alias Part Numbers:

"7-1899587-0"

"380-A-S-009-N-14-05-F3")

CH6164-000

(Alias Part Numbers:

"3-1899677-4"

"KHKB-18879")

CA6660-001

(Alias Part Numbers:

"DTS26Z17-28PN951H"

"3-1899126-2")

CH2525-001

(Alias Part Numbers:

"6-1899584-2"

"RS-267-3587")

CH5321-000

(Alias Part Numbers:

"3-1899668-7"

"HSJC0-24931K")

CV2354-000

(Alias Part Numbers:

"KHKB-26811R78969")

003447-000

(Alias Part Numbers:

"1-1190026-1"

"HBJC4/7-0/16784K")

A62735-000

(Alias Part Numbers:

"2-1200085-4"

"HBJC3/10-0/20114F")

Product Affected

Recommended Replacement

CH2039-001

(Alias Part Numbers:

"6-1899564-9"

"CH2038-001")

A72891-000

(Alias Part Numbers:

"1-1200625-8"

"HSJC0/5-0/21056G")

CH4947-000

(Alias Part Numbers:

"2-1899653-0"

"KHKB-27436")

CM2985-000

(Alias Part Numbers:

"3-1899402-8"

"KHKB-25596")

CG6766-000

(Alias Part Numbers:

"HSJC0-25543K"

"8-1899268-1")

CN7568-000

(Alias Part Numbers:

"KHKB-25695"

"8-1899496-9")

CN5447-000

(Alias Part Numbers:

"5-1899486-0"

"HSJC0-26032K")

CV2574-000

(Alias Part Numbers:

"KHKB-27825")

C45971-001

Product Affected
(Alias Part Numbers:
"9-1201890-3"
"BCPC6S-1")

Recommended Replacement

CH8060-000
(Alias Part Numbers:
"7-1899687-2"
"KHKB-16721")

335715-000
(Alias Part Numbers:
"8-1192535-1"
"HSJC0/4-0/16760K")

CH3334-000
(Alias Part Numbers:
"1-1899610-8"
"KHKB-27249")

CH4002-000
(Alias Part Numbers:
"2-1899627-1"
"KHKB-27329")

CH1585-000
(Alias Part Numbers:
"1899544-6"
"KHKB-26861")

CH8059-000
(Alias Part Numbers:
"7-1899687-1"
"KHKB-16742")

CJ1445-001
(Alias Part Numbers:
"RR00E22-7SN-9443"
"4-1899253-7")

939891-001

Product Affected
(Alias Part Numbers:
"617050-001"
"2-1197278-9")

Recommended Replacement

D21617-000
(Alias Part Numbers:
"1201727-8"
"HSJC0/10-0/23042K")

CH1557-000
(Alias Part Numbers:
"KHKB-26854"
"8-1899542-0")

CV0988-000
(Alias Part Numbers:
"KHKB-27661HS")

CN7483-000
(Alias Part Numbers:
"KHKB-26583"
"7-1899496-0")

716379-000
(Alias Part Numbers:
"8-1195604-9"
"D38999/24WD35PN")

CA4946-000
(Alias Part Numbers:
"HSJC0-24759F"
"2-1899116-8")

CM1013-001
(Alias Part Numbers:
"MS3106R-28-51S"
"4-1899387-5")

CH1898-000
(Alias Part Numbers:

Product Affected
"1-1899559-3"
"HSJC0-26945F")

Recommended Replacement

CN3075-000
(Alias Part Numbers:
"7-1899473-1"
"KHKB-18853")

CH3826-000
(Alias Part Numbers:
"5-1899622-9"
"KHKB-862872")

772124-001
(Alias Part Numbers:
"454-277"
"9-1199705-2")

CF0954-000
CF0128-000
(Alias Part Numbers:
"HSJC0/62-0/21476K"
"1899152-8")

752828-000
(Alias Part Numbers:
"1-1200085-5"
"HSJC0/5-0/20098F")

CH2500-000
(Alias Part Numbers:
"3-1899583-5"
"KHKB-27090")

F19755-000
(Alias Part Numbers:
"HBJC3/31-12/24255K"
"6-1899066-8")

CV0489-000

Product Affected
(Alias Part Numbers:
"3-1899719-8"
"HSJC0-19689K")

Recommended Replacement

CN5449-000
(Alias Part Numbers:
"5-1899486-2"
"HSJC0-26042K")

947522-000
(Alias Part Numbers:
"9-1200083-3"
"HSJC0/5-2/20084F")

D67611-000
(Alias Part Numbers:
"8-1202076-0"
"HBJC5/19-0/24011F")

596945-001
(Alias Part Numbers:
"1-1194721-4"
"FV585080")

CH2610-001
(Alias Part Numbers:
"6-1899587-5"
"6020-18-32SF0")

CH3589-000
(Alias Part Numbers:
"9-1899614-0"
"KHKB-821659")

CJ3881-001
(Alias Part Numbers:
"USB -1.1-(A)-PLUG"
"6-1899276-4")

049801-000

Product Affected
(Alias Part Numbers:
"4-1190381-8"
"HSJC0/1-0/18146K")

Recommended Replacement

CH3202-000
(Alias Part Numbers:
"6-1899607-6"
"HSJC0-27140K")

348001-000
(Alias Part Numbers:
"8-1192618-2"
"D38999/26WF32SN")

C60905-000
(Alias Part Numbers:
"HSJC0/3-0/24216K"
"8-1899068-1")

CG6820-000
(Alias Part Numbers:
"HSJC0-25597K"
"8-1899269-4")

251513-001
(Alias Part Numbers:
"1-1191843-4"
"C2507-10SL-3HNO")

F89814-000
(Alias Part Numbers:
"3-1201789-3"
"GD400054-0178-00R")

A37679-000
(Alias Part Numbers:
"1202036-9"
"HSJC0/10-0/23632K")

CG6812-000

Product Affected
(Alias Part Numbers:
"HSJC0-25589K"
"7-1899269-6")

Recommended Replacement

137057-001
(Alias Part Numbers:
"6-1190993-2"
"D38999/24WB98SN")

CV3180-000
(Alias Part Numbers:
"G9588S1632NF6")

CH4814-000
(Alias Part Numbers:
"9-1899649-2"
"HBJC3-25297K")

CH3625-000
(Alias Part Numbers:
"3-1899617-5"
"KHKB-27298")

C40346-000
(Alias Part Numbers:
"7-1199521-0"
"HSJC0/14-0/19592K")

F92044-001
(Alias Part Numbers:
"5-1201760-8"
"DSS5XPXXB01X")

CV1497-001
(Alias Part Numbers:
"A30199")

CH4155-000
(Alias Part Numbers:
"3-1899631-5")

Product Affected
"KHKB-951088")

Recommended Replacement

075479-000
(Alias Part Numbers:
"2-1190564-8"
"HBJC3/7-0/13547K")

889441-000
(Alias Part Numbers:
"62GB-523-08-33P"
"7-1196919-2")

579968-000
(Alias Part Numbers:
"8-1200084-3"
"HBJC4/9-0/20048F")

158978-000
(Alias Part Numbers:
"6-1197928-6"
"W700-ENG-CHG-FR")

CN0867-000
(Alias Part Numbers:
"7-1899459-7"
"KHKB-25401")

CH8967-000
(Alias Part Numbers:
"1899695-4"
"KHKB-26356")

A13966-000
(Alias Part Numbers:
"7-1201228-1"
"GD400087-0180-03")

CH3220-000
(Alias Part Numbers:
"8-1899607-4"

Product Affected
"KHKB-27142")

Recommended Replacement

CH2401-000
(Alias Part Numbers:
"4-1899581-6"
"HSJC0-25072K")

CN9472-001
(Alias Part Numbers:
"222S14M12"
"1899508-2")

CH4958-001
(Alias Part Numbers:
"5-1899653-7"
"SC7065")

CH1794-000
(Alias Part Numbers:
"5-1899553-7"
"HSJC0-26906F")

CH1523-000
(Alias Part Numbers:
"KHKB-26836"
"7-1899541-2")

D40721-000
(Alias Part Numbers:
"5-1202079-6"
"HSJC0/4-0/23152K")

A45487-000
(Alias Part Numbers:
"6-1200625-7"
"HBJC4/8-2/21221G")

644519-000
(Alias Part Numbers:
"2-1195091-1")

Product Affected
"D38999/26WD97SB")

Recommended Replacement

CN0480-000
(Alias Part Numbers:
"9-1899457-3"
"KHKB-26464")

CL8122-001
(Alias Part Numbers:
"5-1899369-4"
"440HJ030N1303")

E02467-000
(Alias Part Numbers:
"2-1201512-6"
"KHKB-20719")

CJ5554-001
(Alias Part Numbers:
"557T240NC132"
"2-1899292-8")

D36931-001
(Alias Part Numbers:
"795-305910"
"8-1899091-7")

CH4387-000
(Alias Part Numbers:
"1-1899638-2"
"KHKB-25424")

CH6173-000
(Alias Part Numbers:
"4-1899677-3"
"KHKB-18867")

CH1161-000
(Alias Part Numbers:
"KHKB-26647")

Product Affected
"1899527-2")

Recommended Replacement

872111-001
(Alias Part Numbers:
"8-1196786-7"
"TV06RW-11-01-SN-L/C")

CN7482-000
(Alias Part Numbers:
"KHKB-26582"
"6-1899496-9")

E58569-000
(Alias Part Numbers:
"8-1202091-8"
"HSJC0/1-0/22822K")

CH0924-000
(Alias Part Numbers:
"1899522-1"
"HSJC0-26780K")

CH3444-000
(Alias Part Numbers:
"1-1899612-5"
"180-060XM06-17-08SN")

CH3328-000
(Alias Part Numbers:
"1-1899610-2"
"KHKB-27243")

D99255-000
(Alias Part Numbers:
"7-1202115-1"
"400Z860")

CH3137-000
(Alias Part Numbers:
"7-1899605-8")

Product Affected
"HSJC0-27218F")

Recommended Replacement

CJ1015-001
(Alias Part Numbers:
"PAN6433-2F-18-35PB"
"1899251-7")

CH7222-000
(Alias Part Numbers:
"KHKB-25947")

EB1208-000
(Alias Part Numbers:
"D38999/26#B01SN-ZNCO")

E24742-000
(Alias Part Numbers:
"1-1201018-1"
"HSJC0/2-0/21058K")

679131-000
(Alias Part Numbers:
"6-1195338-8"
"HSJC0/10-0/12674K")

C15270-000
(Alias Part Numbers:
"3-1201813-5"
"HSJC0/6-6/22247K")

837685-000
(Alias Part Numbers:
"1-1196538-1"
"HBJC3/6-0/14542K")

765195-000
(Alias Part Numbers:
"1195957-7"
"D38999/26WE35PE")

Product Affected

Recommended Replacement

CH2152-000

(Alias Part Numbers:

"1899569-9"

"KHKB-26193")

CH3302-000

(Alias Part Numbers:

"8-1899609-1"

"HSJC0-27250K")

CM9890-000

(Alias Part Numbers:

"62GB-56TG16-26PB"

"7-1899452-4")

921305-000

(Alias Part Numbers:

"4-1197148-0"

"D38999/20WJ46AN")

CL0385-000

(Alias Part Numbers:

"HSJC0/173-24/17331K"

"3-1899319-8")

CA5692-001

(Alias Part Numbers:

"457-5211")

CF0178-000

(Alias Part Numbers:

"7-1899152-1"

"HSJC0/8-0/21527K")

A45425-000

(Alias Part Numbers:

"1-1201233-0"

"KTFA-4468")

CH1825-000

Product Affected
(Alias Part Numbers:
"6-1899554-4"
"KHKB-VVR-MHSTK")

Recommended Replacement

CH2229-000
(Alias Part Numbers:
"7-1899573-5"
"KHKB-27095")

CJ8399-000
(Alias Part Numbers:
"HBJC2-25771F"
"8-1899307-7")

CV4112-000
(Alias Part Numbers:
"KHKB-27847")

CM1237-001
(Alias Part Numbers:
"10-552944-99"
"1899389-9")

E73375-000
(Alias Part Numbers:
"HSJC0/8-0/24242K"
"2-1899069-2")

CV0297-000
(Alias Part Numbers:
"9-1899710-2"
"HSJC0-27603K")

CH2799-000
(Alias Part Numbers:
"1-1899593-4"
"KHKB-EPD101624A(HHB)")

CH5190-000
(Alias Part Numbers:

Product Affected

Recommended Replacement

"1-1899660-8"
"KHKB-27376")

CG6749-000
(Alias Part Numbers:
"HSJC0-25526K"
"4-1899268-3")

CV3045-001
(Alias Part Numbers:
"ST1215")

CH1724-000
(Alias Part Numbers:
"1-1899551-0"
"KHKB-26895")

CN9247-001
(Alias Part Numbers:
"L24321201000"
"3-1899506-0")

CL9708-001
(Alias Part Numbers:
"TV07RW-23-35SN(W52)"
"8-1899377-5")

CM5196-001
(Alias Part Numbers:
"8D7-25Z19SA"
"5-1899420-2")

CV0345-000
(Alias Part Numbers:
"8-1899711-2"
"KHKB-27582")

D85137-000
(Alias Part Numbers:
"7-1201438-6")

Product Affected
"HSJC0/1-1/22220K")

Recommended Replacement

CM1594-001
(Alias Part Numbers:
"10-40811-04"
"6-1899391-4")

CH2907-000
(Alias Part Numbers:
"6-1899598-8"
"KHKB-EPD107584A(HHB)")

175099-000
(Alias Part Numbers:
"2-1191273-9"
"HSJC0/6-0/16719K")

CH2042-001
(Alias Part Numbers:
"7-1899564-2"
"608-36T20-41PN")

CH1914-000
(Alias Part Numbers:
"3-1899559-0"
"HSJC0-26963F")

CH1579-000
(Alias Part Numbers:
"9-1899543-9"
"HSJC0-26864K")

CH9801-000
(Alias Part Numbers:
"5-1899697-9"
"HBJC3-26012K")

E96317-000
(Alias Part Numbers:
"HBJC4/12-3/24163K")

Product Affected
"2-1899066-6")

Recommended Replacement

CH3326-000
(Alias Part Numbers:
"1-1899610-0"
"KHKB-27241")

541435-001
(Alias Part Numbers:
"1-1194246-5"
"CECC75201002-CD35FCNA01G")

CH3446-001
(Alias Part Numbers:
"1-1899612-7"
"800-006-16M6-7SN")

CH7809-000
(Alias Part Numbers:
"8-1899685-0"
"KHKB-16717")

CF0184-000
(Alias Part Numbers:
"HSJC0/36-36/21532K"
"7-1899152-9")

248104-000
(Alias Part Numbers:
"1200909-8"
"HBJC3/32-24/19648K")

CH1168-000
(Alias Part Numbers:
"KHKB-26705"
"1899527-9")

EB1122-000
(Alias Part Numbers:
"D38999/20#B98PA-ZNCO")

Product Affected

Recommended Replacement

E59217-000

(Alias Part Numbers:

"6-1202002-0"

"HBJC5/20-0/23853K")

CM9983-000

(Alias Part Numbers:

"SBMS3106E-14S-5PNM11"

"3-1899453-8")

E42037-000

(Alias Part Numbers:

"2-1200624-3"

"HBJC4/17-4/21016G")

CH4414-000

(Alias Part Numbers:

"3-1899638-9"

"KHKB-25446")

027414-000

(Alias Part Numbers:

"8-1199531-5"

"HSJC0/1-1/19569K")

2091406-1

CN8714-000

(Alias Part Numbers:

"KHKB-26597"

"8-1899503-2")

CH0816-000

(Alias Part Numbers:

"KHKB-26649"

"3-1899517-8")

CF3463-000

CL7690-000

(Alias Part Numbers:

Product Affected
"HBJC2-26067F"
"1899368-6")

Recommended Replacement

CJ0970-001
(Alias Part Numbers:
"602GB00E18-32PB(416)"
"7-1899250-5")

CV1455-000
(Alias Part Numbers:
"1-1899756-8"
"HSJC0-25963K")

CV1017-001
(Alias Part Numbers:
"M81511-26EJ01S1")

CV0786-001
(Alias Part Numbers:
"1899731-8"
"62GBSS-56T14-12PN")

CG6748-000
(Alias Part Numbers:
"HSJC0-25525K"
"4-1899268-1")

CF0193-000
(Alias Part Numbers:
"HSJC0/18-9/24830K"
"8-1899152-8")

877358-000
(Alias Part Numbers:
"5-1198263-7"
"HSJC0/10-4/18871K")

C88931-000
(Alias Part Numbers:
"7-1201866-9")

Product Affected
"HSJC0/10-0/23613K")

Recommended Replacement

CH1720-000
(Alias Part Numbers:
"1899551-6"
"HSJC0-26886K")

A88307-001
(Alias Part Numbers:
"7-1202107-4"
"8197029-4")

CG6659-000
(Alias Part Numbers:
"HSJC0-25436K"
"4-1899265-5")

CN7577-000
(Alias Part Numbers:
"KHKB-25709"
"9-1899496-9")

A28698-000
(Alias Part Numbers:
"4-1201283-4"
"GD400109-0110-04")

CM4773-001
(Alias Part Numbers:
"CECC75201002-CA98FCCA01G"
"8-1899416-2")

E11318-000
(Alias Part Numbers:
"HBJC5/18-9/24192K"
"9-1899066-2")

CL3933-001
(Alias Part Numbers:
"CR06178-1")

Product Affected

Recommended Replacement

"6-1899341-0")

D53768-000

(Alias Part Numbers:

"1-1201727-5"

"HSJC0/16-6/23162K")

CJ3490-001

(Alias Part Numbers:

"HARNWARE-TRAIN"

"4-1899273-3")

246787-000

(Alias Part Numbers:

"3-1191810-4"

"62GB-523-22-55P")

CN9263-001

(Alias Part Numbers:

"8HEB-7E-SP0022C"

"4-1899506-1")

E10765-000

(Alias Part Numbers:

"1-1201565-2"

"D38999/24WD5PN")

CV1979-000

(Alias Part Numbers:

"KHKB-22274")

C66757-001

(Alias Part Numbers:

"9-1201705-5"

"99-1430-820-04")

F31596-000

(Alias Part Numbers:

"HBJC3/8-4/24198K"

"8-1899066-4")

Product Affected

Recommended Replacement

729441-000

(Alias Part Numbers:
"1195699-4"
"HSJC0/1-0/18228K")

316453-000

(Alias Part Numbers:
"2-1192398-0"
"HSJC0/17-9/16674K")

CF0156-000

(Alias Part Numbers:
"HSJC0/2-0/21509K"
"4-1899152-9")

CF2895-000

(Alias Part Numbers:
"GD400265-0380-05R"
"5-1899207-1")

CN3577-001

(Alias Part Numbers:
"BACC63BV14B7S6"
"7-1899475-1")

CH2559-000

(Alias Part Numbers:
"5-1899585-9"
"KHKB-26394")

CG6769-000

(Alias Part Numbers:
"HSJC0-25546K"
"8-1899268-5")

C16841-000

(Alias Part Numbers:
"5-1200582-8"
"D38999/20WG41SN")

Product Affected**Recommended Replacement**

D22397-000

(Alias Part Numbers:
"1200625-9"
"HSJC0/4-0/21220G")

CH4455-001

(Alias Part Numbers:
"4-1899639-9"
"DC-24660-33-OBS")

CH9805-000

(Alias Part Numbers:
"6-1899697-3"
"KHKB-26010")

427497-001

(Alias Part Numbers:
"5-1193216-9"
"M24308/2-3")

CV1012-000

(Alias Part Numbers:
"2-1899740-9"
"HSJC0/56-2/15852K")

CH2358-000

(Alias Part Numbers:
"6-1899579-1"
"HSJC0-27118F")

CH1771-000

(Alias Part Numbers:
"7-1899552-4"
"KHKB-26902")

1478388-1

(Alias Part Numbers:
"CV3778-000"
"AMP-0-1478388-1")

Product Affected

Recommended Replacement

CJ3503-001

(Alias Part Numbers:
"HARNWARE-DATABUS-
TRAIN"
"5-1899273-2")

D05693-000

(Alias Part Numbers:
"4-1200085-8"
"HSJC0/5-2/20026F")

E49108-000

(Alias Part Numbers:
"1201726-7"
"602GB06E12-3PN(416)")

F86910-000

(Alias Part Numbers:
"HSJC0/8-0/24241K"
"2-1899069-1")

CH2310-001

(Alias Part Numbers:
"9-1899576-9"
"DW-AD-623-M5-725")

CL1374-001

(Alias Part Numbers:
"8-1899326-7"
"TVP02RW-17-06SN(W52)
(W404)")

CV1963-000

(Alias Part Numbers:
"KHKB-27378R19104")

C19920-001

(Alias Part Numbers:
"M39029/64-369")

Product Affected

Recommended Replacement

CV1464-000

(Alias Part Numbers:
"KHKB-25971")

CM5681-000

(Alias Part Numbers:
"FV-700805"
"4-1899422-6")

CH4426-000

(Alias Part Numbers:
"8-1899638-8"
"KHKB-25473")

CH2479-000

(Alias Part Numbers:
"8-1899582-8"
"KHKB-27110")

5-161107-4

CF0123-000

(Alias Part Numbers:
"HSJC0/59-59/21471K"
"1899152-1")

CV1953-000

(Alias Part Numbers:
"KHKB-27382R91773")

CV3567-000

(Alias Part Numbers:
"KHKB-1991210-1")

CH3433-000

(Alias Part Numbers:
"9-1899611-8"
"HSJC0-27163K")

799391-001

Product Affected
(Alias Part Numbers:
"4-1196180-6"
"M81969/14-01")

Recommended Replacement

809277-000
(Alias Part Numbers:
"3-1196289-9"
"D38999/26WD19PA")

F81932-000
(Alias Part Numbers:
"6-1201229-4"
"GD400256-0164-23")

CF0719-000
(Alias Part Numbers:
"HSJC0/5-0/25036K"
"3-1899180-5")

CV0343-000
(Alias Part Numbers:
"8-1899711-0"
"KHKB-27580")

D85933-000
(Alias Part Numbers:
"9-1201831-2"
"HSJC0/4-0/23022K")

CM4823-001
(Alias Part Numbers:
"62GB-523-08-02S"
"1-1899417-7")

A55888-000
(Alias Part Numbers:
"4-1202045-6"
"HSJC0/19-4/23943F")

CJ3501-001

Product Affected
(Alias Part Numbers:
"HARNWARE-ADMIN-TRAIN"
"5-1899273-1")

Recommended Replacement

CL0375-000
(Alias Part Numbers:
"FGG-0B-560ZZC"
"3-1899319-2")

888209-000
(Alias Part Numbers:
"1196910-7"
"D38999/26WJ61PN")

530677-001
(Alias Part Numbers:
"1194168-9"
"CECC75201002-
CA35MCNA01G")

CV0338-000
(Alias Part Numbers:
"7-1899711-5"
"KHKB-27575")

A24443-000
(Alias Part Numbers:
"5-1201437-5"
"HSJC0/6-0/22264K")

CV0443-001
(Alias Part Numbers:
"1-1899717-6"
"DEMM15F225")

CV0939-000
(Alias Part Numbers:
"7-1899735-2"
"KHKB-26415")

Product Affected**Recommended Replacement**

759585-000

(Alias Part Numbers:
"62GB-56TG16-26PN"
"7-1195917-3")

C11395-000

(Alias Part Numbers:
"7-1201421-9"
"GD400005-0130-00")

CM3375-001

(Alias Part Numbers:
"508-1-31720-220"
"1-1899407-6")

CL3949-001

(Alias Part Numbers:
"CR07188-2"
"7-1899341-7")

CH1583-000

(Alias Part Numbers:
"1899544-4"
"KHKB-26859")

CV3199-000

(Alias Part Numbers:
"KHKB-16693")

C69109-000

(Alias Part Numbers:
"3-1202091-5"
"HBJC5/24-0/22294K")

CN6728-000

(Alias Part Numbers:
"HSJC0-26593K"
"1899493-3")

CA4949-000

Product Affected
(Alias Part Numbers:
"HSJC0-24762F"
"3-1899116-1")

Recommended Replacement

CG6687-000
(Alias Part Numbers:
"HSJC0-25464K"
"8-1899265-2")

402591-000
(Alias Part Numbers:
"2-1193039-4"
"D38999/20WD05SB")

E60973-000
(Alias Part Numbers:
"HBJC5/23-0/24159K"
"9-1899066-5")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.