



22-Dec-2015

PCN #:P-15-012457

Subject:Discontinuance

Description of Change: The Data and Devices (DND) business unit of TE Connectivity has made the decision to discontinue the manufacture and sales of the below mentioned parts (obsolete status). Last time buy and last time ship information is provided below.

Reason: Part status change.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:31-Jan-2016

Last Ship/EOL Date:30-Apr-2016

Product Affected

1918403-3

(Alias Part Numbers:

"CK5490-000"

"AMP-0-1918403-3")

5502632-7

7-5209250-0

(Alias Part Numbers:

"CF1877-000")

1693539-1

(Alias Part Numbers:

"F03094-000"

"AMP-0-1693539-1")

Recommended Replacement

Product Affected

Recommended Replacement

2-5502632-6

1828456-1

(Alias Part Numbers:

"CK6429-000"

"AMP-0-1828456-1")

5504632-4

(Alias Part Numbers:

"CH9697-000"

"PER-5504632-4")

2064685-1

1754625-1

(Alias Part Numbers:

"CK6414-000"

"AMP-0-1754625-1")

5504632-6

1828874-6

5503137-6

502748-2

(Alias Part Numbers:

"AMP-0-0502748-2"

"C61356-000")

5502781-5

(Alias Part Numbers:

"CB2556-000"

"AMP-0-5502781-5")

1-1828874-3

1828874-8

1278705-2

1828892-1

(Alias Part Numbers:

"CK6482-000"

"AMP-0-1828892-1")

1828874-7

Product Affected
(Alias Part Numbers:
"CZ7255-000"
"AMP-0-1828874-7")

Recommended Replacement

7-5209250-2
(Alias Part Numbers:
"CF1875-000")

1828874-1
9-5209285-9
(Alias Part Numbers:
"CF1954-000")

1374737-3
7-5209250-3
(Alias Part Numbers:
"CF1874-000")

1828456-3
1985150-4
1918373-2
1374352-1
5502781-3
2-5502632-1
5501506-7
(Alias Part Numbers:
"CB2623-000"
"AMP-0-5501506-7")

5503137-3
1754625-3
1-5502632-8
5504632-1
5502632-8
502750-1
(Alias Part Numbers:
"A17471-000"
"AMP-0-0502750-1")

7-5209250-7

Product Affected
(Alias Part Numbers:
"CF1869-000")

Recommended Replacement

1374737-1
(Alias Part Numbers:
"CX0339-000"
"AMP-0-1374737-1")

1918373-1
1918372-1
2-5502632-5
5502781-1
1918403-1
(Alias Part Numbers:
"CK6578-000"
"AMP-0-1918403-1")

1278705-3
(Alias Part Numbers:
"AMP-0-1278705-3"
"D47514-000")

1-5503137-7
(Alias Part Numbers:
"EB7504-000"
"AMP-1-5503137-7")

1985150-2
502750-2
(Alias Part Numbers:
"FSA-ADP-T1-1"
"867113-000")

5503137-5
(Alias Part Numbers:
"EB7503-000"
"AMP-0-5503137-5")

5209250-5
(Alias Part Numbers:

Product Affected
"CA4605-000")

Recommended Replacement

1918372-2
1966062-5
1-5209250-5
(Alias Part Numbers:
"CA5144-000")

1374727-3
(Alias Part Numbers:
"CK9486-000"
"AMP-0-1374727-3")

5502781-2
1828456-4
5502781-4
1374737-2
2125019-1
2064431-1
5501506-2
(Alias Part Numbers:
"CB2555-000"
"AMP-0-5501506-2")

7-5209285-0
(Alias Part Numbers:
"FS0974-000")

5503137-2
5504632-2
2-5502632-4
1-5502632-2
(Alias Part Numbers:
"CB2619-000"
"AMP-1-5502632-2")

5503137-1
1918373-3
5502632-9
(Alias Part Numbers:

Product Affected**Recommended Replacement**

"A61211-000"

"AMP-0-5502632-9")

1-5502632-0

1918918-1

(Alias Part Numbers:

"CK6506-000"

"AMP-0-1918918-1")

1918403-2

(Alias Part Numbers:

"CN7384-000"

"AMP-0-1918403-2")

1374352-2

502862-1

(Alias Part Numbers:

"161926-000"

"FSA-FC-PRO-COVER-CN01")

1693539-3

(Alias Part Numbers:

"590467-000")

7-5209250-5

(Alias Part Numbers:

"CF1871-000")

5503137-4

2125019-2

(Alias Part Numbers:

"EE3492-000")

1985150-1

2125101-1

504632-4

5504632-4

(Alias Part Numbers:

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.