



17-Aug-2018

PCN #:E-18-013059

Subject:Part obsolescence.

Description of Change: Parts to be made obsolete if not created, sold, or in stock for 2 years. The following part numbers are being obsoleted (obsolete status) and no longer available. Please consult with your local customer sales representative for further details.

Reason: Discontinuance. To assist in REACH coding. Parts can be made active again should they be required. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:17-Aug-2018

Last Ship/EOL Date:18-Aug-2018

Product Affected

CH8267-001

(Alias Part Numbers:

"8-1899688-8"

"M39029/11-145")

Recommended Replacement

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.