



09-Dec-2019

PCN #:E-19-019103

Subject:Part Number Obsolete Part number 1444693002 replaced with part number 144469-000

Description of Change: Part number 1444693002 replaced with part number 144469-000 The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application- Drawings are available via TE.com.

Reason: Discontinuance. Part number 1444693002 replaced with part number 144469-000 Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Key Dates:

Last Order Date:10-Dec-2019

Last Ship/EOL Date:06-Jan-2020

Product Affected

1444693002

(Alias Part Numbers:

"1200376-8"

"FLHTC0311-16-9")

Recommended Replacement

144469-000

(Alias Part Numbers:

"1-1191044-0"

"FLHTC0311-16-9")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.