



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019875

PCN Date: 20-OCT-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
044674-000	NO			2-1190343-1, 209M412-19B			
068659-000	NO		RAY068659-000	2-1190517-8, TXR76AB00-1406AI			
093385-000	NO		RAY093385-000	1-1190685-0, TXR40AB00-1612BI			
099503-000	NO		RAY099503-000	2-1190729-9, TXR54AC00-0804AI			
112873-000	NO			4-1190823-8, TXR41AB00-2410AI			
130209-000	NO		RAY130209-000	6-1190945-5, TXR40BW00-1810AI			
131975-000	NO		RAY131975-000	3-1190959-9, TXR40SJ00-1006AI			
145697-000	NO		RAY145697-000	6-1191052-2, TXR41AB00-1006AI			
146995-000	NO		RAY146995-000	3-1191062-0, TXR40AB00-1410AI			
168289-000	NO			4-1191225-3, TXR41AB00-2414AI			
169269-000	NO		RAY169269-000	3-1191232-0, TXR40AB00-1407AI			
179233-000	NO			9-1191302-2, TXR40BW00-1610AI			
254995-000	NO			8-1191866-9, TXR76AB00-0804AI			
308763-000	NO			5-1192338-7, TXR40AC00-2410AI			
320635-000	NO		RAY320635-000	8-1192430-7, TXR41AB00-1406AI			
337735-000	NO			6-1192549-4, TXR40BW00-1608AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
377253-000	NO			1-1192825-4, TXR40BW00-2416AI			
415359-000	NO			3-1193130-6, TXR40BW00-1005AI			
432825-000	NO			4-1193255-9, 204M014-19B06-40			
449341-000	NO		RAY449341-000	6-1193375-2, TXR40BW00-1814AI			
455940-000	NO			1-1193422-7, 203M908-19B			
584487-000	NO			5-1194628-6, TXR40AB90-2412AI			
616803-000	NO			6-1194874-4, 204M112-19B04-40			
638339-000	NO			8-1195045-7, TXR40AB00-1414AI			
638701-000	NO			6-1195048-4, TXR40BW00-1007AI			
734059-000	NO		RAY734059-000	2-1195733-2, TXR40AB00-1810AI			
743425-000	NO			3-1195800-9, TXR54AB00-2808AI			
749301-000	NO		RAY749301-000	2-1195844-5, TXR40AB90-1208AI			
754567-000	NO			2-1195882-0, TXR76AB00-1006AI			
799612-000	NO			1-1196182-0, TXR54AB00-2216AI			
837783-000	NO			8-1196538-1, TXR18AB00-1606AI			
883337-000	NO			1-1196875-2, TXR40AC00-1204AI			
883741-000	NO			1196878-4, TXR40AB90-2016BI			
928279-000	NO			1197198-1, TXR41AB90-1006AI			
929031-000	NO		RAY929031-000	1197203-9, TXR40AB00-1814AI			
953753-000	NO			9-1197384-8, TXR40BW00-1206AI			
AAE9406-00	NO			STXR41SJ00-1210AI			
CF0574-000	NO		RAYCF0574-000	STXR40BW00-1614AI			
CH3923-000	NO			3-1899625-2, TXR40AB00-1610AIJ			
CW0599-000	NO			TX40AZ00-2408			
EG0498-000	NO			TXR54AC00-1814BI			
EG1539-000	NO			BND40AB00-1208W			
EH8414-000	NO		RAYEH8414-000	STXR40SJ00-0807AI			



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019875

PCN Date: 20-OCT-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
044674-000	NO			2-1190343-1, 209M412-19B			
068659-000	NO		RAY068659-000	2-1190517-8, TXR76AB00-1406AI			
093385-000	NO		RAY093385-000	1-1190685-0, TXR40AB00-1612BI			
099503-000	NO		RAY099503-000	2-1190729-9, TXR54AC00-0804AI			
112873-000	NO			4-1190823-8, TXR41AB00-2410AI			
130209-000	NO		RAY130209-000	6-1190945-5, TXR40BW00-1810AI			
131975-000	NO		RAY131975-000	3-1190959-9, TXR40SJ00-1006AI			
145697-000	NO		RAY145697-000	6-1191052-2, TXR41AB00-1006AI			
146995-000	NO		RAY146995-000	3-1191062-0, TXR40AB00-1410AI			
168289-000	NO			4-1191225-3, TXR41AB00-2414AI			
169269-000	NO		RAY169269-000	3-1191232-0, TXR40AB00-1407AI			
179233-000	NO			9-1191302-2, TXR40BW00-1610AI			
254995-000	NO			8-1191866-9, TXR76AB00-0804AI			
308763-000	NO			5-1192338-7, TXR40AC00-2410AI			
320635-000	NO		RAY320635-000	8-1192430-7, TXR41AB00-1406AI			
337735-000	NO			6-1192549-4, TXR40BW00-1608AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
377253-000	NO			1-1192825-4, TXR40BW00-2416AI			
415359-000	NO			3-1193130-6, TXR40BW00-1005AI			
432825-000	NO			4-1193255-9, 204M014-19B06-40			
449341-000	NO		RAY449341-000	6-1193375-2, TXR40BW00-1814AI			
455940-000	NO			1-1193422-7, 203M908-19B			
584487-000	NO			5-1194628-6, TXR40AB90-2412AI			
616803-000	NO			6-1194874-4, 204M112-19B04-40			
638339-000	NO			8-1195045-7, TXR40AB00-1414AI			
638701-000	NO			6-1195048-4, TXR40BW00-1007AI			
734059-000	NO		RAY734059-000	2-1195733-2, TXR40AB00-1810AI			
743425-000	NO			3-1195800-9, TXR54AB00-2808AI			
749301-000	NO		RAY749301-000	2-1195844-5, TXR40AB90-1208AI			
754567-000	NO			2-1195882-0, TXR76AB00-1006AI			
799612-000	NO			1-1196182-0, TXR54AB00-2216AI			
837783-000	NO			8-1196538-1, TXR18AB00-1606AI			
883337-000	NO			1-1196875-2, TXR40AC00-1204AI			
883741-000	NO			1196878-4, TXR40AB90-2016BI			
928279-000	NO			1197198-1, TXR41AB90-1006AI			
929031-000	NO		RAY929031-000	1197203-9, TXR40AB00-1814AI			
953753-000	NO			9-1197384-8, TXR40BW00-1206AI			
AAE9406-00	NO			STXR41SJ00-1210AI			
CF0574-000	NO		RAYCF0574-000	STXR40BW00-1614AI			
CH3923-000	NO			3-1899625-2, TXR40AB00-1610AIJ			
CW0599-000	NO			TX40AZ00-2408			
EG0498-000	NO			TXR54AC00-1814BI			
EG1539-000	NO			BND40AB00-1208W			
EH8414-000	NO		RAYEH8414-000	STXR40SJ00-0807AI			