



19-Jan-2022

PCN #: P-22-022032

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity was informed by one of its material supplier on a consolidation in their manufacturing plant for PVDF based Color Concentrates (CC). TE Wire and Cable plants in Tijuana and Redwood City use PVDF CCs as colorant for outer insulation layer in spec 44 and FLDW primary wires. TE has evaluated the PVDF CCs from the supplier's new manufacturing location and no change to Form, Fit and Function of finished parts has been observed.

Reason : Part status change. TE was notified by its material supplier that except for Black PVDF CC, no change has been made in material formulation and recipe for PVDF CCs produced from their new manufacturing site. Due to health and safety policy of vendor's new manufacturing site with respect to handling raw carbon black pigments, this CC has undergone a change of one raw material component. TE evaluated these changes on the key characteristics of the CCs and the finished goods and no impact on the properties and performance of finished parts has been observed. Test reports on the wire characteristics can be provided upon request. In addition to the evaluation conducted by TE, FAIs will be performed on the first manufactured primary wire lot per each gauge for validation.

Key Dates :

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
382403-000	"9-1192862-5", "44A1121-22-0/9-0"		
209981K001	"7-1191521-2"		
836843-000	"9-1196531-6", "FB-44-7026A-0219CS896"		
CR3720-000			
766779-003	"9-1197924-6", "EPD68607A-ING"		

886437-002	"7-1197924-4", "EPD70027A-ING"		
265580-000	"3-1199501-5", "EPD-NAV-79417"		
461717-000	"44AM4131-20-0/2/9-9CS356", "2-1193463-7"		
C49996K001			
800213-000	"5-1196187-8", "FB-44-7026A-0222CS896"		
EJ1846-000	"44A9786-18-ELC6-9CS3433"		
C03875-000	"1200693-6", "EPD-RWC-10946-L087"		
CN2051-000			
202587-001	"7-1191468-0", "FB-44-4022-0001"		
309733K001	"5-1192345-3"		
303147-000	"3-1192296-6", "EPD-ROK-10326"		
F80790-000	"44A0111-14-0CS2896", "9-1200416-0"		
396281-000	"4-1192972-1", "EPD51047A-18-0"		
546268-000	"5-1199501-4", "EPD-NAV-85413"		
A56982K001	"6-1200803-1"		
352845-000	"5-1192650-5", "EPD49342A"		
166059K001	"8-1191198-4"		
493207K001	"8-1193688-8"		

433793-000	"7-1193262-2", "FB-44-7024A-0202"		
282520-000	"8-1192117-7", "44A0311-18-0-US"		
382515-000	"5-1192864-7", "44A4121-24-0/9-9-MX"		
EF7915-000			
973543K001	"2-1197524-8"		
439387K001	"1193302-2"		
911199-000	"8-1197076-9", "EPD48805B-US"		
EM0370-000	"EPD106293 A-US"		
849391-000	"1-1196623-4", "EPD-RWC-15753"		
CA0194-000	"44A0131-22-0/1/6-MX"		
EG8852-000	"400R1131-22-0/6/9-9"		
EG2008-000	"44A0121-24-0/9-L016"		
CS7472-000			
835938-000	"44AM1122-22-0/9-9", "6-1196525-6"		
CX5921-000	"EPD38848A-US-L016"		
CX1595-000	"EPD-DND-21441"		
E16904K001	"2-1201417-3"		
125615-000	"1-1190913-2", "44AM4121-20-0/9-0"		
454595-000	"1-1193412-4", "EPD40250A"		
CZ7351-000			

967067-000	"6-1197477-4", "EPD52063A-20-0"		
609781K001	"9-1194821-3"		
3C0541-000	"4-1193002-8", "EPD5840-20-0"		
CS7766-000	"EPD-DND-21488-L099"		
CX6623-000			
831965-000	"1-1196496-9", "EPD52146A-24-0"		
265402-000	"8-1191957-7", "44A0811-14-0"		
905085-000	"1-1197033-0", "WXA-0165-10-0"		
644753-000	"7-1195092-8", "EPD52958A"		
EH2574-000	"44A9681-22-0/9-9CS3433"		
C31327K001	"9-1201652-0"		
971519K001	"8-1197509-1"		
317339-000	"3-1192404-6", "EPD52965A"		
668587-002	"7-1195264-1", "EPD23569B"		
EG8826-000	"400R1121-14-0/9-9"		
288589-002	"6-1192188-2", "EPD4761C"		
ER6312-000	"44A0321-16-0/9-US"		
746493-001	"5-1195823-7", "FB-44-7026A-0235CS896"		

443119K001	"8-1193330-8"		
208327K001	"7-1191509-7"		
486112-000	"2-1197928-3", "EPD92432A-US"		
496444-001	"1-1193712-8"		
221101K001	"8-1191629-7"		
720125-000	"44AM1121-14-0/9-9CS356", "6-1195631-9"		
343915-000	"5-1192590-7", "44AM1121-24-0/2-93"		
CA2940-000			
987918-000	"44A1121-18-0/6-9"		
382390-000	"6-1192862-8", "44A1141-20-0/1/2/9-9"		
CX7547-000	"EPD-DND-21447-L016"		
909702-000	"1198990-7", "EPD-ROK-10493"		
952074K001	"8-1197924-8"		
844971-000	"44AM1121-20-0/9-9CS1702", "9-1196591-9"		
163651K001	"9-1191180-9"		
117737-000	"1-1190857-0", "EPD40417A-US"		
746559-000	"345M13B-26-8-0CS2041", "4-1195824-0"		
618101K001	"1194884-1"		

306856-000	"7-1198288-2", "44AM1121-18-0/2-9"		
382254-009	"1-1192859-1", "44A1121-22-0/9-9-MX"		
153229K001	"1-1191107-2"		
924194-000	"5-1199368-2", "EPD95612A-US"		
EL6400-000	"44AM1131-18-0/2/9-9CS3451"		
A24354K001	"9-1200816-3"		
CP3772-000	"EPD100242 A-US"		
395383-000	"1-1192966-3", "44AM1121-16-05/24-9"		
493623K001	"9-1193691-0"		
CR3650-000	"EPD-RWC-22219"		
CU8788-000	"EPD-DND-21535-L146"		
322971K001	"7-1192444-1"		
717209-000	"4-1195610-2", "EPD52775A-20-0"		
658099-000	"44AM1161-26-0/2/3/5/6/9-9", "9-1195188-8"		
CY1336-000	"EPD-RWC-19863"		
128363-000	"8-1190932-0", "44A1811-10-0-9"		
CN7930-000	"EPD-RWC-17612CS3287"		
CS2137-000	"81044/12-22-0-BRL-L117"		

398057K001	"1-1192985-9"		
F81865-000	"EPD-RWC-17617", "2-1200355-4"		
EP2875-000	"44A1221-14-0/9-9-L409"		
425062-001	"9-1193199-6", "FB-44-4624-0209CS1578"		
723522-000	"44B1131-22-0/1/2-9CS3018", "2-1200000-5"		
902393-000	"EPD49715A-US"		
CX3824-000			
EF7264-000	"44A1121-20-0/9-9CS3068"		
382381-000	"3-1192862-8", "44A0121-16-0/9-MX"		
CU3936-000			
CR9807-000	"EPD72603A-US-L258"		
EL5757-000			
719139-000	"9-1195624-4", "EPD-RWC-11195"		
CS1831-000			
605359-000	"8-1194789-4", "EPD51032A-22-0"		
382394-003	"7-1192862-3", "44A1141-22-0/2/6/9-9"		
492593K001	"4-1193684-1"		
383343-000	"1192874-6", "44A1121-22-0/9-92-US"		
292762-000	"9-1198733-8", "44A1161-18-0/2/3/4/5/9-9"		
D87485K001	"8-1200876-8"		

383159-000			
CB5625-000			
382604-000	"1192866-1", "44A1121-20- 0/2-9-MX"		
485892-000	"44B1121-16- 0/9-91", "2- 1193636-1"		
CP3579-000	"EPD-RWC- 16867"		
737861-000	"4-1195760- 5", "FB-44- 7026A- 0216CS896"		
EG8830-000	"400R1121- 18-0/9-9"		
ER1423-000	"44A9089-16- 0/9-9CS2378"		
525777K001	"7-1194131- 0"		
374791-000	"3-1197838- 9", "44A0141- 22-0/2/6/9- MX"		
141931-000			
848222-000	"44B4141-24- ELC4- 9CS1873", "9- 1196614-0"		
953445-000	"44A4321-20- 0/9- 9CS2748", "9- 1197382-3"		
346993K001	"1192612-5"		
376432-000	"8-1201014- 1", "44A0122- 20-0/9"		
527893-000	"1-1194147- 8", "EPD- ROK-10310"		
476013K001	"3-1193565- 0"		
613143K001	"8-1197888- 8"		
CU8718-000	"EPD-DND- 21508-L177"		
316737-000	"1192400-1", "EPD30143B"		

976059-000	"3-1197542-4", "EPD-ADD-10161"		
C02834-000	"4-1201391-1", "EPD-RWC-18510-L016"		
840544-000	"8-1196557-6", "EPD8494C"		
698405K001	"9-1195480-4"		
843005K001	"8-1196575-9"		
EK3792-000			
CL6053-000	"EPD-RBS-10075"		
759348-000	"44A1821-18-0/2-9", "1195916-3"		
109449-000	"2-1197970-6", "EPD70555A-US"		
C39813K001	"5-1201719-8"		
409725K001	"6-1193090-6"		
CF8496-000	"44A1131-22-0/2/9-9CS406"		
017995-000	"5-1190140-2", "EPD51040A-18-0"		
597815-000	"44A9650-14-0/9-0", "8-1194726-4"		
390845-000	"4-1192934-2", "EPD-RWC-10426"		
267453-000	"2-1191974-1", "44A9091-16-0/2/5/9-9"		
382469-000	"9-1192863-0", "44A1124-26-0/9-9"		
138655-000	"5-1191005-5", "44A1231-18-0/2/9-0"		

876532K001	"2-1199946-6"		
307314-000	"9-1197927-6", "EPD92308A-US"		
461273-000	"44AM1121-22-0/8-9", "7-1193459-8"		
376181-000	"1192818-7", "44A0121-26-0/6-US"		
299387-000	"5-1192266-1", "EPD-RWC-14233"		
873473-000	"44AM1121-22-0/8-9CS356", "7-1196796-4"		
917961-000	"44AM1181-26-A233-9", "6-1197124-2"		
CP3571-000			
205657K001	"4-1191490-9"		
CM4223-000			
CN5743-000	"EPD90506A-US"		
326939K001	"8-1192473-8"		
396219K001	"1192972-1"		
515369-000	"44A1141-26-0/1/2/3-9", "7-1194047-9"		
903823-000	"6-1197023-7", "EPD51193A-22-0"		
CR9511-000	"44A1821-18-0/9-6"		
D20969-000	"6-1200402-6", "EPD96519A-US"		
EG8802-000	"400R0111-26-0"		

826516-000	"8-1199943-9", "FLDWC0311-18-0CS2979"		
441541-001	"345/37B-22-6-0CS1913", "1193320-1"		
D05767-000	"5-1202027-8", "44AM1141-20-G138-9CS356"		
541097-000	"7-1194243-1", "WXA-0165-22-0"		
303137-000	"2-1192296-4", "345M06B-22-80-0CS2041"		
748507K001	"6-1195838-8"		
856533-000	"44A0321-20-0/9CS2747", "9-1196675-9"		
CX8431-000			
986343K002	"7-1197618-2"		
583047K001	"5-1194618-0"		
EF5946-000			
617064K001	"7-1198866-6"		
EL5746-000	"44AM1141-22-F003-9CS3450"		
CX1154-000			
CX1594-000	"EPD-DND-21440"		
139191K001	"4-1191009-6"		
103351K001	"1190756-2"		
424021K001	"8-1193192-0"		
479647-000	"8-1193590-3", "EPD-ROC-10049"		

598967K001	"6-1194735-3"		
382533-000	"9-1192864-4", "44A4121-22-0/9-9"		
887515-000	"6-1197875-2", "WXA-0085-12-0"		
EH6663-000	"EPD-DND-21487"		
A87860-000	"6-1200552-5", "FLDWD1321-10-0/9-9CS3050"		
EF7917-000	"EPD-RWC-23840", "8242611765"		
120473-000	"3-1190876-8", "EPD-ROK-10046"		
F95835-000	"EPD-RWC-17035", "6-1200287-6"		
508777-000	"8-1193999-4", "EPD52959A"		
A72881-000	"2-1200976-0", "EPD-RWC-18278CS3085-L101"		
119289-000	"9-1190867-0", "EPD51028A-26-0"		
343519K001	"7-1192587-7"		
EP4878-000	"EPD-RWC-25526-L002"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.