



07-Aug-2023

PCN #: P-23-024937

Subject : Controlled Electrical Cables as per attached parts list

Description of Change : TE Connectivity would like to inform the customers the change to foamed polyethylene is not going to be implemented as planned and previously communicated, ref. P-23-024487 and P-23-024488. Therefore, there will be no fit form function change in comparison to the product currently supplied.

Reason : Part status change.

Key Dates :

Contact By Date:07-Aug-2023

Implementation Date:07-Aug-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1981143001	4-1199482-6, 5030A1P14- 1L(CO)		
CT71563001	120-OHM-CSJR- 0(4M)		
CQ72293001	EPD121282A		
CQ28243001	EPD94392BCK02 06/1		
3253493001	1192462-1, 9530A1317-0(CO)		
5897653001	1-1194666-6, EPD69569A/1-1L		
1100893001	1-1190804-6, EPD32856A/1- 1L(CO)		
CQ61893001	EPD120656A/1- 9(M)		
C565283001	1-1201353-9, 2530A1P18- 1L(CO)		

6284413001	4-1194975-1, 7530E1P14-9(CO)		
4324313001	3-1193252-9, EPD60844B		
431175-000	1193243-4, EPD32707A/1		
A954783001	5-1200773-5, EPD2029J/2(CO)		
CQ22833001	EPD62444QCK02 06/6		
CQ80103001	EPD119201A		
C495213001	3-1201419-3, EPD95313A		
1501813001	1191086-1, EPD61455Q		
F959153001	EPD2029J, 1200752-2		
8664743001	7-1199192-8, EPD95011LCK02 32		
CQ05063001	EPD117170ACK0 298		
CD45233001	EPD45898QCK00 54, 9-1899308-4		
F044573001	CLFH-179-0(CO), 4-1201019-2		
A752283001	3-1201192-4, EPD92472A		
C042653001	0024A0311- 0(4M), 4-1200292- 5		
CQ70213001	EPD118342B		
7729693001	9-1196019-5, EPD43356A		
CQ23453001	EPD105670ACK0 206		
7786663001	EPD104306A/1- 1L(CO)		
CD02303001	EPD104855A/1- 9(CO), 3-1899102- 2		
CD69803001	5026C1P14- N(CO), 2- 1899423-5		
3535293001	1-1192655-7, EPD85996A/1(CO)		

4311753001	1193243-5, EPD32707A/1		
CQ60663001	EPD120521A		
CT02403001	EPD108852L, 1- 1899549-3		
CD55573001	EPD108017BCK0 202, 1-1899361-9		
1814413001	4-1191318-9, EPD60947Q		
C360583001	9-1201799-8, 0024F0P11- 1L(CO)		
1013813001	1190742-2, EPD40889J		
2001363002	8-1191449-1, 5024A1P11-1L		
CQ83853001	EPD118179A/5(C O)		
CT68233001	EPD105335B		
CQ98663001	EPD122399ACK0 308		
CQ17703001	120-OHM-2SJFR- 26-9(CO)		
1571233001	4-1191135-6, EPD70340L/1- 9(CO)		
CQ91683001	0024K1811-0(M4)		
CQ31663001	EPD118141A		
0022173001	1190017-8, EPD45898Q		
5592173001	3-1194414-9, EPD77124A/1(CO)		
3782133001	1192832-6, 5024A1811-0		
CD81963001	0024K1811- 0(3M), 8-1899469- 5		
9493573001	1197344-7, EPD30885Q/1- 9(CO)		
CQ82173001	EPD121826ACK0 627		
9581923001	1-1201148-7, EPD95070A		

E338833001	9-1202050-5, EPD101744B/2(C O)		
CT98953001	EPD116681A		
4379153001	4-1193291-9, 5026A1P11- N(CO)		
EQ09873001	EPD108173ACK0 308/2		
4097163001	5-1199663-6, EPD23197B(2M)		
440094W003	1193308-1, 5026A1318-0		
5946793001	3-1194701-8, EPD49551R/1- 1L(CO)		
1952313001	1191416-4, EPD42812B		
7086793001	1-1195554-5, EPD69569A		
CQ77083001	EPD121137A/1- 6(CO)		
6716173002	9-1195284-5, EPD42811B(HB)- OBS		
5142593001	5026A1P11- 9(CO), 1194040-3		
5286403001	9-1200883-9, EPD60603C/1- 9(CO)		
CQ37903001	EPD118397A		
A469083001	0024A0P11- 1L(SFS), 1- 1200767-7		
4885483001	4-1193655-6, 7526A1811-0		
CT98383001	5018F1811-0(2M)		
EQ05223001	EPD122871A/3- 5/9(CO)		
2682223001	6-1199602-8, 5030A1P14-9(CO)		
3570413001	2-1192679-9, EPD32856A/1-N		
A843803001	2-1201166-7, EPD100566A/3(C O)		

0867823001	9-1200146-7, EPD97331L/1(CO)		
C588213001	5-1202050-7, EPD101747B/1- 9(CO)		
CQ20603001	EPD62444QCK02 06/5		
F698023001	EPD104319A/1- 1L(CO)		
CQ72893001	EPD121342A		
CQ42243001	EPD119030A		
2433293001	6-1191785-4, EPD87667A/1(CO)		
EQ07233001	EPD108750A		
200217-000	7-1191450-6, 7528A1P17-1L		
CT74303001	EPD115106QCK0 456/1		
9453513001	4-1197316-9, EPD4044/1-0(M)		
3886093001	6-1192917-4, EPD67422A		
E475663001	9-1201921-1, EPD102735A		
5663973001	8-1194472-9, EPD61702L		
9579623001	5026A1317- 9(CO), 1-1198896- 2		
440077-003	4-1193307-6, 7524A1311-0, 7524A1311-0		
CQ95373001	EPD121052A		
9036793001	6-1197022-4, EPD73247A		
1239673001	6-1190901-8, EPD23197B		
CQ83663001	EPD116265A/2(C O)		
CQ91623001	0024K1811- 0(M2)(FS)		
E781803001	9-1201419-3, EPD96684Q		

CD17533001	7528A1318-0(CO), 9-1899165-8		
8151373001	7524A1811-0, 3-1196352-1		
CQ84233001	EPD106513ACK0213/5		
CQ72563001	EPD121309A		
CQ21033001	EPD117757A		
F214353001	5-1201143-6, EPD94821M/1-1L(CO)		
EQ01913001	EPD122153A		
C878183001	6-1202050-4, EPD101755B/1-9(CO)		
4419293001	6-1193322-6, 5020A3311-9		
CD53033001	EPD107883B, 8-1899347-9		
7202573001	5-1195632-2, EPD29110Q		
CQ83763001	EPD118179A/1-93(CO)		
CQ68293001	EPD94392BCK0206/2		
CD72963001	EPD65220QCK0503, 4-1899435-6		
CQ61883001	EPD120656A/1-1L(M)		
CQ82693001	EPD120795A		
9982293001	7530E1P14-1L(CO), 7-1197718-7		
F707893001	EPD94996L/1-9(CO), 4-1200931-0		
CQ83673001	EPD116265A/3(CO)		
A771503001	8-1201400-3, EPD98957BCK0900		
E234503001	2-1201194-5, 7820G0111-9(4M)		
EQ12273001	EPD122828ACK0624		

F119313001	3-1201156-9, EPD100628A/1- 9(CO)		
CQ60623001	0024B8911(CO)		
A389093001	EPD104306A/1- 9(CO)		
F313813001	8-1202044-6, EPD101755B		
CQ28103001	EPD113842Q/1- 9(M4)		
CT88113001	120-OHM-2SJFR- 24-1L(CO)		
4235633001	6-1193189-7, EPD22252C		
2021383001	6-1198863-4, EPD89109Q/1- 1L(CO)		
1978513001	9-1191433-2, CLFH316/1(CO)		
CQ27963001	EPD113842Q/1- 9CK0399/2		
CD29293001	CLFH178/1(FS), 9-1899222-4		
0454333001	1-1190349-7, CLFH400/1(CO)		
E257633001	0024A0311- 0(2M), 5-1199713- 8		
CQ03433001	0024A0311- 0CK0300		
1341963001	1200147-2, EPD93086R/1- 9(CO)		
CT91983001	EPD106513ACK0 202/3		
CD56093001	EPD108036A/1- 1L-9(CO), 5- 1899362-0		
CD76913001	EPD105601A/2, 1899449-2		
C825373001	2-1201012-3, EPD100170A		
7724573001	7-1196016-6, EPD60325A/1- 9(CO)		
9658233001	2524E0311-9(M), 3-1197469-2		

C635293001	EPD104343A/1-9(CO)		
4400883003	7-1193307-5, 7528A1318-0		
4128833001	4-1193113-4, 5020A3311-0(CO)		
5525433001	5026A1311-0(CO), 3-1194367-2		
7708113001	1-1196005-7, EPD48367A		
CQ44593001	7518A1311-0CK0503		
6076173001	5-1194806-6, 7522A1811-0(CO)		
1901273001	1-1191379-8, EPD26467Q		
CD86953001	EPD108829QCK0355, 1-1899490-5		
9332133001	5-1197232-9, EPD36388Q		
CD93853001	7-1899514-0, EPD111093A/2-0(6M)		
A806593001	3-1201747-6, EPD98865Q/1-9(CO)		
3W02273001	6-1193017-6, EPD21472B		
CQ04173001	EPD33374ACK0094/1		
EQ00273001	EPD121839A/1(M)		
CQ38203001	0028A0P11-1L(CO)		
D767463001	7520A1P11-9(CO), 1-1200600-7		
CD56453001	120-OHM-2SJR-20-1L(CO), 9-1899362-9		
CQ39853001	EPD45898QCK0503		
8816993001	6-1196863-0, EPD86444A/1(CO)		
1722873001	2-1191253-6, EPD71607A/1-1L		

CD79663001	EPD109318QCK0 456, 1-1899458-0		
D630573001	9-1199924-1, EPD96717A		
CQ72613001	EPD121314A		
CD69973001	5026C1314- 02(CO), 8- 1899423-7		
E736713001	1201058-3, FMC- 0002A/1-9(CO)		
CQ41973001	EPD119030A/3(C O)		
1473633001	1191065-2, EPD77622L/1- 9(CO)		
794567-000	2-1196151-0, EPD35077A		
0071903001	9-1199973-8, EPD96496A/1- 6(CO)		
CD35993001	4-1899258-4, EPD104098A/1- 6(CO)		
4959483001	1200145-6, EPD93086R		
CQ27953001	EPD113842Q/1- 1LCK0399/3		
3422853001	0024A0P11- 1L(CO), 1- 1192580-7		
CD40563001	100-OHM-2SJFR- 26-1L(CO), 2- 1899281-7		
CT82123001	EPD114511B/1(C O)		
CQ65813001	EPD35077ACK06 47		
CQ51973001	EPD119924A/1- 9(CO)		
CQ98353001	EPD29057ACK02 06		
F318073001	EPD97565Q/1- 1L(CO), 5- 1200674-1		
CD72743001	EPD107922ACK0 210, 2-1899435-0		
CQ49563001	EPD109318QCK0 456/11		

A750053001	8-1201400-0, EPD98487CCK09 00		
CQ72123001	EPD121265A		
CQ42203001	EPD119030B		
CQ60583001	0024B0P11- 1L(CO)		
378213-000	1192832-5, 5024A1811-0		
C424833001	7-1200885-1, EPD99530A/1- 1L(CO)		
4313853001	6-1193244-9, EPD69568A/1-9		
5444253001	8-1194270-3, EPD73307R/1- 2(CO)		
CQ67763001	EPD120650A/1- 2(CO)		
CQ60863001	EPD116262A/1- 9(CO)		
9994573001	7522A1P12- 1L(CO), 8- 1197726-5		
4418903001	4-1193322-1, 5024A1311-94		
CT74173001	EPD114357A/1- 1L(CO)		
CQ61523001	EPD120653A		
4405993001	7-1193312-6, 7528A1318-9		
9814713001	0024A0311- 0(CO), 6-1197583- 0		
CT87683001	EPD115985A/1(C O)		
CQ42063001	EPD119031A/1- 1L		
D597253001	6-1201419-0, EPD94863L		
8244473001	5-1196438-1, EPD65984Q		
CQ07293001	EPD78640LCK01 21/7		
CT75473001	EPD115224A/1- 1L(CO)		

7950893001	0022D0P11-1L(CO), 4-1196155-3		
6723003001	9-1195289-4, EPD24477A		
0215893001	6-1190167-2, EPD4044/2-1L(CO)		
CQ72593001	EPD121312A		
F492613001	9-1201461-9, EPD4045-C/5(CO)		
9253893001	0024E0811-0(CO), 7-1197177-8		
440555-000	1-1193312-4, 7522A1312-0		
E440393001	5-1201288-2, EPD100153A/1(M)		
CQ95283001	EPD121038A		
F400213001	EPD104315A/1-1L(CO)		
CQ87733001	EPD122014ACK0193		
D080913001	1202044-7, EPD101747B		
CQ36873001	EPD96642ACK0518		
8567713001	7528A1P14-1L(CO), 6-1196677-4		
CQ77103001	EPD121138A/1-9(CO)		
9338513001	7530A1P17-1L(CO), 8-1197236-1		
4182033001	5-1193151-8, EPD72718A		
D035093001	1-1200878-5, EPD98370BCK0339		
A054943001	4-1200886-9, EPD99528A/4(CO)		
EQ01903001	7526A1317-0(M)		
CQ77653001	EPD31475QCK0206/6		

CQ11953001	EPD117498ACK8 500		
CQ12163001	EPD113842QCK0 456/20		
CQ45873001	EPD116816ACK0 206/2		
CQ95303001	EPD121041A		
CQ19233001	EPD118024A		
CQ45563001	7528F1P14-9(CO)		
4675233001	3-1193504-7, EPD62976A/1- 9(CO)		
CD93053001	EPD109318Q/1- 1L(M, 1899511-1		
9479293001	5019D3318- 0(CO), 5-1197334- 6		
509531-000	7-1194005-4, EPD22545D		
1755183001	7-1198899-8, 5026A1317- 96(CO)		
EQ05133001	100-OHM-2SJR- 24-5(CO)		
CT05913001	EPD28251ACK04 40/2, 4-1899558-1		
CD31553001	120-OHM-2SJR- 22-9(CO), 1899237-7		
EQ06053001	EPD121860BCK0 202		
440564-000	2-1193312-5, 7522A1311-0		
5244353001	6-1194119-1, 6624D1P12- 1L(CO)		
CD37373001	EPD106513A, 6- 1899264-5		
440640-000	1193313-3, 9530A1317-9		
F830823001	3-1201424-9, EPD95315Q/1- 0(CO)		
CQ34143001	EPD109318Q/1- 1L(M1)CK0399		
CQ76073001	EPD121487A		

595063-000	1194706-8, EPD4044/2-1L		
C124923001	5-1200831-6, EPD95723Q/1- 9(CO)		
0267773001	5-1190207-1, EPD71607A/1- 1L(CO)		
440060-011	9-1193306-5, 5024A1311-0		
5973233001	6-1194723-7, EPD69095A		
CQ72813001	EPD121334A		
CQ67813001	EPD120650A/2(C O)		
CQ19023001	EPD35077ACK04 40		
CQ72533001	EPD121306A		
4401323004	4-1193308-8, 5026A1317-9		
CQ72373001	EPD121290A		
9302513001	4-1197211-8, EPD63054C/2(CO)		
7757053001	1196040-8, EPD91385ACK01 83		
CQ28093001	EPD113842Q/1- 9(M2)		
1532593001	3-1191107-8, EPD7875M		
4025273001	7-1193038-6, EPD87667A/4-9		
CQ15373001	EPD117597A		
CQ74623001	EPD118342C/1- 6(CO)		
F804103001	5-1202088-8, 0026A0014-9(CO)		
0869713001	8-1190641-0, EPD69065Q		
CT62693001	7530A1318-9(M), 7-1899599-6		
CT89523001	EPD116119A/1- 9(CO)		
4532933001	3-1193403-6, EPD49113Q		

CQ28063001	EPD113842Q/1-9(M4)(FS)		
EQ06423001	EPD122750A		
4142103001	6-1193122-5, EPD25986B		
815137W002	7524A1811-0, 3-1196352-2		
CQ69713001	EPD119343ACK0 206/1		
CQ74563001	EPD118341C/1-2(CO)		
1575013001	1191138-3, EPD85875A/1-1L(CO)		
3451153001	4-1192598-5, EPD32991Q		
2007783001	1191455-5, 2524E0P11-1L		
CT92493001	EPD116097A		
440808W002	5-1193314-7, 9530A1318-9		
A169333001	2-1201148-3, EPD95079A		
C772663001	6-1202050-2, EPD101747B/2(CO)		
3171853001	2-1192403-3, 5012A3811-0		
0349323001	5-1197947-9, EPD80977A		
CD68443001	EPD108173ACK0 266, 7-1899416-2		
EQ05103001	100-OHM-2SJR-24-1(CO)		
8778363001	5-1199972-0, EPD96496A/2(CO)		
EQ02423001	EPD122640A		
CT83673001	9530A1318-9(8M)		
CT95973001	EPD116546A/1-1L(CO)		
CQ76533001	EPD109382ACK0 298/6		
7506633001	1-1195854-0, EPD79182A/2(CO)		

9778713001	1197555-7, EPD7881J		
4276993001	1193218-7, 7520A1311-0(M)		
F023493001	EPD104448A/1- 1L(CO)		
1290073001	9-1190936-8, EPD82097A		
CQ42313001	EPD31475QCK02 13/2		
C382263001	EPD104317A/2(C O)		
8798113001	5030A1P17- 9(CO), 7-1196849- 8		
CQ41773001	EPD116262B/3(C O)		
1593473001	3-1191151-6, 7524A1811-0(CO)		
4451903001	0024A0311-0, 9- 1193345-7		
EQ05233001	EPD122871A/3- 6/9(CO)		
CQ85303001	EPD120934A		
CD08963001	9524A1P11- 9(CO), 9-1899132- 6		
4386793001	1193297-5, 7526A1317-0(CO)		
CD89583001	EPD106672A, 4- 1899498-6		
CD22573001	7528A1318- 0(5M), 1899198-2		
5447453001	1-1194273-1, 7522A1311-0(CO)		
EQ04163001	EPD122605ACK0 427		
4418243001	0022D0311-9(S), 9-1193321-7		
CD13843001	EPD105685A, 9- 1899153-1		
CD29303001	CLFH179/1(FS), 9-1899222-3		
CQ67753001	EPD120650A/1- 0(CO)		

2001213001	6-1191449-0, 5019D3P18-1L		
CQ83803001	EPD118179A/1- 91(CO)		
7743313001	1196030-1, EPD92872A		
D923253001	7-1201122-7, EPD99496A		
8176533001	5-1196371-6, EPD46481D		
5000693001	2-1193738-5, EPD71607A/2		
5963563001	8-1200337-7, EPD98008L/1- 1L(CO)		
CD93763001	6-1899514-1, EPD111033A/1- 9(CO)		
9785693001	3-1197560-0, EPD66400A		
CD75193001	EPD104280A/1- 9(CO), 6-1899443- 5		
0198333001	5-1190154-2, EPD62977ACK0 06		
EQ10493001	EPD123167A		
D435543001	1-1200674-4, EPD97565Q/1- 9(CO)		
CQ88133001	EPD111051A		
4229513001	1-1193185-6, EPD30506A		
CT94923001	EPD107550G/2- N(CO)		
CQ70253001	EPD111050ACK0 298/3		
1633733001	2-1191179-3, EPD32856A/1- N(CO)		
CD00353001	EPD100733Q, 9- 1899089-5		
CQ56233001	EPD116267ACK0 547		
3379473001	1192551-1, 5026A1314- 02(CO)		

CQ76903001	EPD31475QCK02 06/5		
5661153001	9-1194470-3, EPD66710Q/1(CO)		
CD31413001	EPD48325L/1(CO) , 2-1899236-2		
9024013001	4-1197013-0, EPD65742A		
F930513001	EPD104308A/1- 9(CO)		
CD38793001	EPD66813R/1- 9(CO), 4-1899272- 9		
F766673001	EPD99529A/2(CO) , 3-1200885-8		
2694013001	3-1191988-1, EPD72124B		
2000723001	1-1191449-7, 5022A1P11-1L		
CQ83753001	EPD118179A/1- 3(CO)		
E773543001	4-1200536-8, EPD98516B		
4262533001	1193208-1, 5028A1P17- 1L(CO)		
1054663001	5-1199016-8, 7522A1811-0(4M)		
CQ91613001	0024K1811- 0(M1)(FS)		
CQ75423001	EPD94392BCK02 06/4		
CQ45683001	EPD31475QCK02 13/3		
CT67163001	EPD104313B/1- 9(CO)		
7324733001	8-1195721-8, EPD72947A/1- 1L(CO)		
CT69673001	EPD114764A/1- 9(CO)		
440710-000	6-1193313-6, 7524A1311-9		
2770673001	7-1192051-7, EPD73307R/1- 9(CO)		

1834333001	3-1191332-8, EPD33017Q		
8125533001	4-1196321-1, EPD30885Q/1- 1L(CO)		
CQ63113001	7530A1318-9(CO)		
CQ38263001	EPD118758A		
CQ86563001	EPD120896B		
5851123001	4-1199515-6, EPD64983B/1- 9(2M)		
6778253001	1-1195329-5, EPD66710Q/2- 1L(CO)		
CD24363001	9530A1P18- N(CO), 6- 1899201-4		
D313923001	7-1202050-2, EPD101750B/1- 9(CO)		
7438733001	5028A1318- 0(CO), 3-1195803- 5		
F640103001	EPD98077L/1(CO) , 2-1200659-8		
5494953001	7-1194323-9, EPD66997B		
420079-000	7-1193164-4, 5028A3318-9		
F777963001	2-1201349-5, EPD98750A/2(CO)		
5774563001	4-1198981-6, CLFH400		
9780353001	2530A1P17- 1L(CO), 4- 1197556-2		
A056163001	1-1202176-4, EPD48679R/1- 1L(CO)		
E710853001	1200885-7, EPD99529A/5(CO)		
CD16643001	EPD104312B/2- 1L/9-0(CO), 4- 1899162-1		
C857773001	5-1201566-6, EPD102033A		

CQ99893001	EPD94392B		
CD16833001	EPD104312B/1-1L(CO), 8-1899162-0		
CQ20703001	EPD113842QCK5700		
CD76953001	EPD105568A/1-6(CO), 1899449-7		
CT89513001	EPD116119A/1-1L(CO)		
A210433001	4-1201344-8, 2530A1318-0(CO)		
A865373001	2-1201166-8, EPD100566A/2(CO)		
F407103001	0022E0P11-9(CO), 1-1200480-0		
1996613001	2-1191446-9, EPD44533B		
CQ78263001	EPD116448ACK0298		
CQ88103001	EPD122008A		
EQ10443001	5026C1314-0(M)		
CQ18413001	EPD113842Q/1-9(FS)		
CD74833001	EPD108166A, 2-1899441-9		
440101-002	1-1193308-0, 9530A1318-0		
3562433001	1-1192674-7, EPD67364QCK0208		
7010533001	7-1195502-7, 7526A1P11-1L(CO)		
2331513001	5-1191712-7, EPD44091Q		
2001653001	2-1191450-9, 5028A1P14-1L		
CT82763001	EPD115671A/1-9(CO)		
EQ08463001	EPD116255A-0CK0547		
CQ76573001	EPD118397ACK0298		

CQ74483001	EPD117170ACK0 298/3		
6342653001	7-1195016-2, EPD69569B/1- 9(CO)		
CQ42053001	EPD119031A/1-9		
2052513001	3-1191487-2, EPD69813A		
CT64843001	2020E0811-0-UK		
893343-000	0024A0311-0(FS), 5-1196948-0		
3H06613001	9-1193003-6, EPD7032B		
CQ02083001	EPD116816ACK0 206		
5283113001	9-1194149-1, EPD61702L/1- 0(M)		
CD84233001	EPD63976A/1- 1L(CO), 3- 1899479-4		
4297893001	8-1193232-7, 5012A3311-0(CO)		
CQ74503001	EPD118396ACK0 298		
445133-000	0022E0311-0, 4- 1193345-1		
A383613001	6-1201424-0, EPD96684Q/1- 1L(CO)		
D952573001	3-1201284-1, EPD99482BCK04 00		
6343393001	2-1195017-2, EPD31173A/1- 1L(CO)		
D767253001	2524E0P11- 9(SFS), 1- 1200677-5		
6658793001	5026A1P17- 9(CO), 3-1195246- 5		
9738633001	5-1197526-8, EPD26168D/1- 0(M)		
8725713001	8-1196789-7, EPD66710Q		
EQ03223001	EPD122728A		

9453673001	7522A1P11-9(CO), 5-1197316-7		
CQ82593001	EPD121661A/1-1L(CO)		
2734973001	9-1192025-0, EPD26168B		
CT53353001	EPD113521L/1(CO)		
1459853001	2-1191055-9, EPD25986B/1(CO)		
2832193001	2-1192133-6, EPD83126A		
CQ70193001	EPD118342B/1-2(CO)		
CD43153001	2024A0P11-1L(CO), 4-1899299-5		
0194653001	9-1190151-2, EPD67891L		
D515533001	1201175-8, 9530A1114-9(8M)		
CQ67843001	EPD120650A/5(CO)		
3689553001	9-1192764-7, EPD32856A/2		
C312383001	6-1200339-4, EPD98008L/2(CO)		
9279423001	6-1200777-4, EPD98932A		
4406723001	3-1193313-1, 7520A1311-0		
CQ19273001	EPD118014A/1-1L(CO)		
2000113002	0022D0P11-9, 5-1191448-3		
EQ12043001	EPD112330LCK0624		
CQ70123001	EPD118341B		
CD02293001	EPD104855A/1-1L(CO), 3-1899102-1		
136423-000	1190989-8, 5020A3811-0		
CQ56203001	EPD116267A		

CQ59603001	EPD109318QCK0 456/6		
4200303001	2-1193164-8, 5019D3318-0		
E900633001	8-1201288-1, CLFH- 179CK0135		
4404203001	8-1193310-7, 5038A1318-9		
2008503001	0020D0P11-1L, 7- 1191455-2		
C742633001	5024A1311- 0(2M), 4-1200424- 3		
8975153001	3-1196977-2, EPD65701F		
CQ83693001	EPD116265A/1- 9(CO)		
1442783003	9-1191042-0, 7820G0111-9		
C619973001	5-1202050-9, EPD101753B/2(C O)		
CD18383001	7520A1811- 0(3M), 1899172-4		
CQ79223001	EPD121405A		
CQ70243001	EPD109382ACK0 298/5		
CQ72193001	EPD121272A		
CQ86303001	EPD121730ACK0 627		
7716403001	1-1197945-6, EPD90786Q/1- 0(CO)		
CD85073001	EPD35077ACK02 06, 5-1899482-5		
4405553001	1-1193312-5, 7522A1312-0		
E621563001	9-1200930-5, EPD94996L/1- 1L(CO)		
E827303001	1-1201830-5, EPD93792A/1(CO)		
CT78683001	EPD115223A/1- 1L(CO)		

E020373001	5-1201004-1, EPD99489Q		
6306293001	7-1194990-7, EPD8851F/3- 95(CO)		
CQ32933001	EPD118663A		
7915673001	8-1196130-2, EPD44774MOBS		
4400605013	1193307-6, 5024A1311-0		
A228263001	5-1200886-3, EPD99528A/1- 9(CO)		
3012713001	4-1192282-4, 7530A1P14- 1L(CO)		
1582153001	1191143-1, EPD60608B/1- 1L(CO)		
CQ98143001	EPD120794ACK1 120		
CD17353001	7528A1P18-9(FS), 1-1899165-2		
CQ21043001	EPD117758A		
4409013001	4-1193315-7, EPD64720Q		
3317493001	8-1192506-4, EPD69821Q		
0058173001	4-1190044-8, EPD88002A		
4780483001	5-1197947-2, EPD93789A/1- 1L/9(CO)		
CQ21073001	EPD117761A		
4326313001	7-1193253-7, EPD72946Q/1-1L		
2389763001	3-1201141-0, EPD94821L/1- 1L(CO)		
CQ13013001	2024A0111-9(CO)		
CQ40393001	7528A1814-0(M)		
6373453001	8-1195038-9, EPD69569B/1- 1L(CO)		
CT73943001	120-OHM-2SJFR- 22-9(CO)		

2779793001	4-1192058-2, 5020A1P11- N(CO)		
CQ42213001	EPD119031B		
CQ17553001	EPD117867A		
4477173001	3-1193364-2, EPD4673G/2- 1L(CO)		
CQ95383001	EPD121054A		
E847763001	6-1201021-7, EPD100319A/1- 1L(CO)		
D351403001	EPD104310A/1- 1L(CO)		
EQ08423001	5024D3314-0		
CQ41963001	EPD119030A/2(C O)		
D654573001	1201920-3, EPD98957B/1- 9(FS)		
4615393001	1193462-5, 5024A1P11-9		
CQ73733001	EPD121177A		
CT85693001	100-OHM-2SJFR- 22-1L(CO)		
E508573001	5-1200834-3, EPD91697A		
CD83193001	EPD109729A, 6- 1899473-3		
0594953001	4-1190451-6, 5020A3311-9(CO)		
CQ73523001	EPD121391A		
E372033001	3-1200775-4, EPD98957B/1- 9(CO)		
CQ60633001	EPD120520A/1(C O)		
CQ42253001	EPD119031A		
C455603001	7-1199955-4, EPD78640LCK01 21/5		
420030-000	2-1193164-7, 5019D3318-0		
1554973001	5-1191123-6, EPD33374A		

1983053001	6-1191436-6, EPD60608B/1- 9(CO)		
3V00253002	1-1193016-6, EPD21929A		
CT04903001	EPD113319A, 2- 1899555-7		
3476353001	2-1192616-8, EPD60651B/1- 9(CO)		
A777173001	7-1201422-6, EPD96684Q/2- 1L/9(CO)		
CQ73413001	EPD121378A		
CQ70203001	EPD118342B/1- 6(CO)		
9813323001	2524E0311- 0(2M), 5-1199424- 7		
CQ34073001	EPD117755ACK0 298		
CQ16073001	EPD117248A		
EQ02643001	EPD35077ACK02 06/4		
CQ53763001	EPD119989A		
4400943001	9-1193307-4, 5026A1318-0		
EQ10183001	EPD35077ACK06 47/2		
6936963001	5026A1311- 9(CO), 7-1197946- 3		
A599173001	4-1202050-1, EPD101750B/2(C O)		
A187633001	EPD104317A/1- 9(CO)		
CQ73513001	EPD121390A		
9750493001	1-1197535-1, EPD84488A		
944147-000	5024A1P11-9(FS), 6-1197308-3		
CQ83723001	EPD121866A/1- 9(CO)		
1395113001	7-1191011-4, EPD32856A/1-1L		

CD59693001	EPD106482A/1-9(CO), 3-1899377-9		
3N08363001	1193015-2, EPD20664B		
2002173001	7-1191450-7, 7528A1P17-1L		
CQ79583001	2022A1P11-9(CO)		
461539W002	1193462-6, 5024A1P11-9		
CQ55913001	EPD77622M		
6271753001	6-1194966-0, EPD36197L		
E472043001	6-1200523-0, EPD96002A/1-2(CO)		
4402953001	1193310-8, 5026A1318-9		
2013633001	7-1191459-1, EPD60303B		
D548603001	4-1200503-8, EPD97016A		
CT87673001	EPD115985A		
CQ95293001	EPD121039A		
CQ05143001	EPD117170A/1(CO)		
EQ08473001	EPD121866A-0CK0547		
4408383001	8-1193314-5, 5018D3311-0		
3112553001	7-1192355-5, EPD73089L		
C187273001	EPD104308A/1-1L(CO)		
C522643001	EPD104448A/1-9(CO)		
C015353001	1-1201761-1, EPD101186A/2(CO)		
CD22323001	7528A1318-0(3M), 4-1899196-7		
4419443001	0024A0311-9, 7-1193322-4		
440564K003	2-1193312-7, 7522A1311-0		

CT68203001	EPD105062C/1(CO)		
CQ74763001	EPD121437A		
A228193001	7-1201141-8, EPD94822M/2(CO)		
C979413001	5-1201790-6, EPD101039L/2-1L/9(M)		
445190-000	0024A0311-0, 9-1193345-6		
C384143001	EPD104314A/1-9(CO)		
D177133001	3-1201348-1, EPD101254A/1(CO)		
4710813001	9-1193529-0, EPD70340L/1-1L(CO)		
0270753001	6-1190209-6, 5030A1318-9(CO)		
CT98823001	EPD115849A		
9193093001	9-1197133-3, EPD32644A/7(CO)		
CD46053001	EPD107519A/1(CO), 3-1899313-4		
7650513001	5026A1P17-1L(CO), 9-1195955-9		
CT73933001	2-1899634-3, 120-OHM-2SJFR-22-1L(CO)		
1202853001	1190875-6, EPD46419Q/1-1L(CO)		
E863193001	8-1201288-0, EPD96643A		
0318873001	3-1190247-3, EPD67364Q-0(CO)		
CQ47243001	EPD111050ACK0298/2		
CT95223001	EPD116439A		
5787123001	8-1201165-7, EPD100566A/1-9(CO)		

CD51433001	EPD107883A/1(CO), 5-1899338-0		
CD93493001	120-OHM-2SJR-24-9(CO), 3-1899512-4		
CD59713001	EPD35077ACK0503, 6-1899377-1		
5934333001	2524E0P11-9(CO), 2-1194692-6		
7211733001	4-1195639-3, CLFH179/1(CO)		
CQ48073001	EPD91697ACK0016		
8712693001	0024E0811-0, 9-1196780-1		
1051653001	8-1190768-2, EPD64158A		
D450303001	EPD104343A/1-1L(CO)		
EQ05043001	EPD122871A/3-0/9(CO)		
CQ11913001	EPD117497A/1-1L(M)		
0059873001	8-1190045-4, EPD77127L/2-1L/9(CO)		
CQ61093001	2530A0P14-9(CO)		
A543043001	7-1201018-5, EPD60608D/1-9(CO)		
CD04033001	EPD98865Q/1-2(CO), 7-1899110-9		
CQ48543001	EPD119844A		
A487383001	8-1201286-0, CLFH179-0(M)		
4345053001	6-1193267-8, EPD42233A		
F759343001	EPD25986A/1-1L(CO), 5-1201019-7		
CT64743001	EPD113520L		
445190K004	0024A0311-0, 1193346-1		
CD63423001	EPD107799A, 8-1899390-8		

CQ79623001	EPD117758ACK0 624		
9007623001	9-1197946-9, EPD93901A/1- 1L/9(CO)		
5858753001	3-1194638-0, EPD87667A/3- 9(M)		
CQ34043001	EPD118102A		
D141413001	2-1200827-1, EPD95723Q		
CQ71913001	EPD105273ACK0 298/4		
598901-000	0024F0611-9, 1- 1194735-0		
CQ41803001	EPD116262B/1- 0(CO)		
6772713001	2-1195325-0, 7524A1P11- 1L(CO)		
A702313001	5-1200682-7, EPD98370B		
A635943001	4-1201452-2, CLFH-179-0(8M)		
A752373001	7-1200885-0, EPD99529A/1- 9(CO)		
CD95833001	EPD111253A/1(C O), 2-1899521-0		
CD93773001	EPD111033A/2(C O), 6-1899514-2		
F455343001	6-1201547-6, 7528A1P14- N(CO)		
9618813001	3-1197441-5, EPD70340L/2		
CQ02453001	100-OHM-2SJFR- 24-1L(CO)		
6433013001	8-1195082-6, EPD79182A		
CQ56153001	EPD116267A/1- 96(CO)		
4189773001	8-1193156-2, 5030A1114-9(CO)		
2866813001	3-1192171-0, EPD20662B/1- 9(CO)		

2005363001	1-1191453-6, 5030A1P17-1L		
CQ79573001	2022A1P11- 1L(CO)		
8315683001	2524E0311- 9(2M), 2-1199424- 3		
CQ44463001	EPD35077ACK05 03/2		
CQ20433001	EPD67364QCK06 03/1		
CQ76603001	EPD117760ACK0 298		
F615273001	6-1201500-8, 5020A3811- 02(CO)		
C124163001	1-1201142-0, EPD94821L/2(CO)		
CQ73783001	EPD121177A/1- 1L		
4406403001	1193313-4, 9530A1317-9		
CD56143001	EPD108037A/1- 1L/9(CO), 5- 1899362-4		
EQ03453001	EPD109318QCK0 456/2		
CT82753001	EPD115671A/1- 1L(CO)		
2751653001	0020D0P11- 1L(CO), 9- 1192037-9		
CQ56183001	EPD116267A/3(C O)		
CQ00323001	EPD116027A		
4407103001	6-1193313-7, 7524A1311-9		
9015333001	2-1197007-6, EPD87108Q/1- 1L(CO)		
CD78743001	EPD62444QCK02 06/4, 6-1899452-2		
9808893001	7-1197579-5, EPD25986C		
7500973001	8-1195849-2, EPD49551R/1-9		

CQ69693001	EPD120794A		
2572753001	8-1191882-8, EPD49551R/1- 9(CO)		
CD31483001	EPD106743A/2(C O), 7-1899236-3		
CT36333001	EPD113286A, 7- 1899562-4		
CT89133001	EPD107550G/2(C O)		
7358383001	7-1199210-4, EPD95412Q/1- 1L(CO)		
6362853001	9-1195030-6, EPD20697A/1- 1L(CO)		
8987793001	2-1196986-4, EPD73248A/1- 9(M)		
1580643001	2-1201141-4, EPD94821L/1- 9(CO)		
CQ66853001	EPD119343ACK0 206		
EQ05173001	EPD122871A/3- 2/1L(CO)		
2216353001	9-1191632-2, EPD90230A		
440225-000	3-1193309-5, 5020A1311-0		
CQ93183001	EPD94392BCK02 06/7		
7828163001	9-1196079-9, EPD25986B(M)		
7305333001	1195707-2, EPD44774NOBS		
440094-000	9-1193307-3, 5026A1318-0		
C108323001	4-1201459-1, EPD24256A/1- 1L(CO)		
CD56173001	EPD108041A/1- 1L/9(CO), 5- 1899362-7		
CT98873001	EPD115973A		
CT98833001	EPD115850A		
CQ74803001	EPD121441A		

CT01923001	EPD113292A, 8-1899547-2		
1450463001	3-1191048-9, EPD26334B		
EQ06333001	0024K1811-5(CO)		
A494623001	3-1202050-8, EPD101753B/1-1L(CO)		
D936633001	1201442-9, 5026A3814-0		
E442733001	8-1201419-2, EPD94988A		
CD97503001	EPD111118A/1(CO), 8-1899527-3		
5185653001	1-1194070-8, EPD60897A		
1371093001	9-1190993-3, EPD86425A		
EQ06663001	0024K1811-4(CO)		
440088W007	7-1193307-9, 7528A1318-0		
A113163001	2-1200715-0, EPD78905ACK0323		
871269W002	0024E0811-0, 9-1196780-2		
A926993001	0024A0P11-9(SFS), 2-1200767-7		
2987203001	5-1199502-1, 9530A1317-9(8M)		
A284773001	3-1201408-0, 7524A1811-0(5M)		
CD51243001	0024E0P11-1L(CO), 8-1899337-8		
4435493001	7-1193333-6, 7530A1P17-9(CO)		
E050843001	8-1202050-7, EPD101755B/2(CO)		
CQ42033001	EPD119030A/1-9		
7672073001	1195979-8, EPD62444Q		
EM0645-000	2022A1811-0		
CQ87003001	EPD121857B		

D322563001	EPD104307A/1-1L(CO)		
CQ83793001	EPD118179A/1-1(CO)		
CQ88533001	EPD111051ACK0624		
CQ18653001	EPD106513ACK0213/2		
6748533001	8-1195307-1, EPD87667A/2(CO)		
CQ83573001	EPD118179A-0CK0547		
4624353001	3-1193468-8, 5028A1P18-1L(CO)		
A389363001	3-1202050-4, EPD101744B/1-9(CO)		
1914933001	8-1191388-1, EPD73248A		
6902833001	4-1195420-4, EPD72947A/1-9(CO)		
CQ98043001	0024A0311-0CK0202		
CQ70183001	EPD118342B/1-0(CO)		
F945593001	EPD91814A, 1-1200450-3		
CD15673001	EPD86888C/1-9(CO), 9-1899160-6		
EQ05163001	EPD122871A/3-2/0(CO)		
200556-000	3-1191453-5, 7520A1P11-1L		
EQ05143001	100-OHM-2SJR-24-6(CO)		
6489053001	3-1195122-7, EPD20662B/3-6(CO)		
4400775007	5-1193307-1, 7524A1311-0		
2751053001	6-1192037-2, EPD69568A		

C435203001	9-1201344-2, 0022D0311- 96(CO)		
4405643001	2-1193312-6, 7522A1311-0		
9939973001	5018D3311-9, 5- 1197688-5		
7611813001	6-1195928-1, EPD39928B		
345115-000	4-1192598-4, EPD32991Q		
CQ72343001	EPD121287A		
7596283001	5020A3311- 0(3M), 8-1198920- 2		
CT69993001	CLFH178(FS)		
D349773001	5026A1P11- 9(SFS), 5- 1200802-6		
CD76923001	EPD105601A/1- 2(CO), 1899449-3		
1986983001	1198701-8, EPD44774N/1- 0(8M)		
CQ20693001	EPD113842Q(FS)		
EQ15063001	EPD118745ACK0 202/5		
6746283001	1197959-3, EPD83644L/1- 1L(CO)		
445133W002	0022E0311-0, 4- 1193345-3		
2386973001	7-1191754-0, EPD62976A/1- 1L(CO)		
9500073001	7-1197347-8, EPD70340L/1-1L		
183433-000	3-1191332-7, EPD33017Q		
5667093001	1-1194475-0, EPD71607A		
4644273001	4-1193482-8, 7520A1811-0(M)		
CQ67853001	EPD120650A		
0517093001	8-1190395-9, 9530A1317-9(CO)		

CQ28923001	EPD117254ACK0 202		
8268013001	2-1196458-1, EPD66677A		
C928993001	EPD104309A/1- 1L(CO)		
CQ12533001	EPD117622A/5(C O)		
E820243001	5-1200996-1, EPD99292B/1- 6(CO)		
CQ06413001	EPD109318QCK0 456/25		
1446853001	0024A0P11- 9(CO), 8-1191045- 1		
CT88123001	120-OHM-2SJFR- 24-9(CO)		
CQ73003001	EPD121352A		
CD90373001	EPD94436B, 7- 1899500-3		
CD93893001	EPD111035A/1- 1L(CO), 7- 1899514-6		
EQ02793001	EPD120795B		
D774053001	8-1200681-7, EPD98824A		
4407873001	4-1193314-0, 7522A1311-9		
CD67373001	EPD108704A, 9- 1899409-4		
CQ16033001	EPD117622ACK0 202		
EQ05963001	EPD44533BCK06 56		
2366773001	2-1191740-8, EPD40252B		
E716903001	8-1202053-2, EPD101729M/1- 1L(CO)		
5944953001	9-1194699-8, EPD91387A/1-9		
A906603001	3-1201553-7, EPD101496ACK0 062		
CQ04183001	EPD109318Q/1- 1L(M1)		

CQ83713001	EPD121866A/1-6(CO)		
8679423001	9-1197946-2, EPD94102A		
1490543001	8-1199484-2, 5020A1811-0(12M)		
CT96803001	EPD109318QCK0646		
798383W001	2530A0614-9, 6-1196175-7		
CQ91653001	0024K1811-0(M1)		
CQ17513001	EPD117862A		
CD22533001	EPD106301A, 6-1899197-6		
155497-000	5-1191123-5, EPD33374A		
CQ76673001	EPD118141ACK0298		
200121-000	5-1191449-9, 5019D3P18-1L		
CQ78393001	EPD106513ACK0213/4		
CD80823001	EPD107731A, 6-1899466-9		
5231813001	4-1194110-5, EPD48915Q		
CQ17693001	120-OHM-2SJFR-26-1L(CO)		
3145253001	6-1192380-0, 5021K1P11-1L(CO)		
CQ87563001	EPD115373ACK0193		
440788-000	4-1193314-1, 5030A1318-9		
9242893001	9-1197169-2, EPD86166R/1-1L(CO)		
8279833001	7526A1811-0(CO), 2-1196466-9		
CD76593001	EPD108998L, 5-1899447-8		
A840543001	7-1201422-9, EPD94988A/1(CO)		

CQ79743001	EPD91158LCK06 24		
CQ78353001	EPD118102ACK0 298		
D832503001	7-1202176-7, EPD48679R/1- 9(CO)		
CQ64083001	EPD119157A		
CT74223001	5020A3312-0(CO)		
1313073001	7-1190954-2, EPD83644L/1- 9(M)		
CQ07523001	EPD90230ACK02 71		
E141933001	5-1201766-3, EPD101039L		
CD69773001	5026C1314- 0(CO), 1899423-1		
9175513001	9-1197121-0, 9530A1P17- 1L(CO)		
CD62993001	EPD108393A, 4- 1899388-6		
E761733001	EPD104314A/1- 1L(CO)		
CD69263001	9530A1318- 90(CO), 2- 1899421-0		
9741233001	3-1197528-4, EPD72946Q(S101)		
A345503001	2-1201708-7, EPD45898QCK03 91		
3656973001	2-1192742-2, EPD77127L/1- 1L(CO)		
A039143001	3-1200831-8, EPD95723Q/1- 1L(CO)		
CQ20423001	EPD67364QCK06 03		
CQ20523001	EPD109318Q/1- 1L(MARK1)		
CQ72213001	EPD121274A		
A878313001	9530A1P14- 9(CO), 1200600-7		

D430333001	1-1199839-8, 7526A1317- 0(12M)		
CQ74573001	EPD118341C/1- 6(CO)		
CQ72903001	EPD121343A		
CT85703001	100-OHM-2SJFR- 22-9(CO)		
EQ10503001	EPD123179ACK0 298		
8109673001	9-1196301-8, EPD32178C		
8170973001	4-1196367-0, EPD38753A		
CQ53823001	EPD107550G/3(C O)		
CD43343001	0028G1P14- 9(CO), 2-1899300- 5		
CT92613001	9524A0P11-9(CO)		
CQ57953001	EPD35767QCK04 99		
440107W003	1-1193308-9, 5028A1314-0		
8764493001	6-1196817-1, EPD63054C/1- 6(CO)		
D361883001	3-1200932-0, EPD94996L/2(CO)		
9711773001	5028A1P18- 9(CO), 2-1197507- 6		
CQ45263001	EPD105273ACK0 298/2		
CQ92403001	EPD109318QCK0 456/55		
CT82893001	EPD108704ACK0 254		
6542573001	5026A1P18- 1L(CO), 1195162- 9		
7173193001	5030A1P17- 1L(CO), 1- 1195611-7		
CQ84803001	EPD29116D		
CQ73803001	EPD121402A		

CT69663001	EPD114764A/1-1L(CO)		
CQ18953001	EPD117888A/2(CO)		
4645913001	8-1193483-0, EPD83644L		
CQ95333001	EPD121046A		
CQ34153001	EPD109318Q/1-9(M2)CK0399		
CQ02133001	EPD115540A		
CT98863001	EPD115853A		
D660153001	1-1201872-9, CLFH316		
3425653001	2-1192581-5, EPD72004A		
1875353001	1-1191361-9, EPD25986C/1-9(CO)		
CT75873001	0024K1811-0(CO)		
440672W002	3-1193313-2, 7520A1311-0		
CD93863001	7-1899514-1, EPD111093A/1-9(CO)		
2009433001	8-1191456-7, 5012A3P11-1L		
3991963003	1192995-3, FILLER-ROD-FOAM-045		
4330573001	3-1193257-5, 5026A1P11-1L(CO)		
CQ62943001	7528A1814-0(CO)		
CQ30073001	7524A1311-0(M2)CK2240		
CD84263001	EPD107551A/2(CO), 3-1899479-9		
4414673001	5-1193319-8, 5024A1811-0(M)		
965823-000	2524E0311-9(M), 3-1197469-1		
F456163001	2-1201505-0, EPD98738L/1-1L(CO)		
440569-000	3-1193312-1, 5026A1311-0		

CD05093001	EPD103722A/1(CO), 2-1899117-1		
CT53363001	EPD113521L		
810967-000	9-1196301-7, EPD32178C		
D774143001	6-1200811-7, EPD99113A/1-1L/9(CO)		
5144513001	2-1194041-8, EPD23197B(M)		
CQ18403001	EPD113842Q/1-1L(FS)		
CQ41873001	EPD116255A/1-9(CO)		
CQ11923001	EPD117497A/1-9(M)		
C138163001	6-1200773-2, EPD2029J/1-1L(CO)		
3969933001	7-1192977-4, EPD72946Q/1-9(CO)		
CQ13703001	EPD117487A		
D784493001	8-1202050-1, EPD101754B/1-1L(CO)		
6820833001	6-1195361-3, EPD24187D/1		
6943913001	5026A1811-0(CO), 1-1195448-4		
CD21803001	EPD105670A, 3-1899193-1		
CQ77343001	EPD60947QCK0503/1		
CD67783001	EPD75422B/1(CO), 2-1899412-6		
5194933001	4-1194076-1, 7520A1P11-1L(CO)		
D288443001	EPD104307A/1-9(CO)		
EQ06243001	EPD122605B/1(CO)		
CD00973001	EPD104855A/2(CO), 3-1899094-6		

5992853001	2524E0P11-9(M), 7-1194737-3		
CQ51983001	EPD119924A/3(C O)		
CQ83843001	EPD118179A/4(C O)		
E381493001	9-1201545-1, EPD101379Q		
CQ60823001	EPD116262ACK0 547		
D156513001	1-1199934-8, EPD84497B		
9268273001	7-1197187-9, CLFH178(S50)		
630519W002	1-1194990-0, EPD35767Q		
CQ89573001	EPD35589ACK02 13/1		
4401073001	1-1193308-8, 5028A1314-0		
CT69733001	EPD114765A/2(C O)		
C412993001	4-1200475-6, EPD91814A/1- 0(4M)		
CQ18893001	120-OHM-2SJFR- 26-2(CO)		
CD84023001	EPD109365A/5(C O), 1-1899478-1		
CD37363001	CLFH-179-0(3M), 6-1899264-4		
CQ17563001	EPD117898A		
440555W002	1-1193312-6, 7522A1312-0		
7672533001	5022A1P11- 1L(CO), 3- 1195979-7		
871269-000	8-1202162-2, 0024E0811-0		
8719113001	2-1196785-4, CLFH316(S50)		
5320833001	2-1194178-0, EPD31173A		
A404573001	EPD104311A/1- 9(CO)		

CQ77583001	EPD94392BCK02 06/6		
E862443001	5019D3P18- 9(CO), 7-1200745- 1		
6870993001	5024A1P14- 9(CO), 8-1195394- 7		
368955-000	9-1192764-6, EPD32856A/2		
CQ48063001	EPD117416ACK0 016		
CQ14263001	EPD94392BCK02 06		
CQ79393001	2018A1P11- 1L(CO)		
D849033001	8-1200805-6, EPD99114A		
5443493001	5018A1P11- 9(CO), 9-1194269- 0		
CT69723001	EPD114765A/1- 9(CO)		
CQ65783001	EPD65220QCK06 47		
D066293001	EPD104313A/1- 1L(CO)		
1330073001	1190966-1, 5020A1811-0(M)		
2004993001	9-1191452-0, 5018A1P11-1L		
8958613001	1196966-3, EPD23197B/1- 9(CO)		
A926753001	7820G0111- 9(3M), 7-1200716- 0		
0980283001	1199212-2, EPD95437Q/1- 9(CO)		
CD28673001	7528A1318- 0(2M), 2-1899220- 0		
CQ46813001	EPD111051ACK0 298/1		
CT89493001	EPD116118A/1- 1L(CO)		

200165-000	2-1191450-8, 5028A1P14-1L		
CQ02463001	100-OHM-2SJFR- 24-9(CO)		
440473-000	3-1193311-2, 5024A1312-9		
CQ30083001	7524A1311- 0(M3)CK2240		
CT94933001	EPD116422A		
6029273001	3-1194772-4, EPD66921L		
D247363001	EPD104312A/2- 1L/9(CO)		
3752853001	5-1192811-2, 9530A1318-9(CO)		
0157653001	5-1190123-5, EPD82741Q		
EQ03553001	EPD95014ACK02 13/2		
0577973001	9-1190438-6, 5028A1314-9(CO)		
420030W002	3-1193164-0, 5019D3318-0		
CQ12293001	EPD111557A		
CQ36083001	EPD117603ACK0 298/1		
4451333001	0022E0311-0, 4- 1193345-2		
EQ05393001	EPD122844ACK0 624		
CQ71073001	EPD117170ACK0 298/2		
CQ56143001	EPD116267A/1- 93(CO)		
F993703001	2-1201767-4, EPD101036Q		
A084833001	9-1201877-6, EPD103284Q/1- 1L(CO)		
C951483001	2-1200866-3, CLFH178(CO)		
4402253016	3-1193309-9, 5020A1311-0		
CQ99213001	EPD122349A/1(C O)		

CQ70533001	EPD118745ACK0 202/1		
5199403001	5026A1317- 92(CO), 4- 1198905-8		
5284033001	4-1194150-9, EPD44306A		
9146933001	4-1197101-2, EPD26337B		
7173233001	2-1195611-1, EPD87108Q/1- 9(CO)		
8279633001	7528A1318-0(M), 1-1196466-6		
1397653001	5-1191013-7, 5028A1P14- 1L(CO)		
F722923001	2-1201349-4, EPD98750A/1- 9(CO)		
1752153001	1191274-4, EPD33537R		
CQ74633001	EPD118342C		
144278W001	9-1191042-3, 7820G0111-9		
EQ05263001	100-OHM-2SJR- 24-9(CO)		
CQ77073001	EPD121137A/1- 9(CO)		
3280333001	6-1192481-0, EPD26168D		
CQ87823001	EPD35767QCK02 06		
CD43163001	2024A0P11- 9(CO), 4-1899299- 6		
CD62733001	EPD108392A, 3- 1899387-4		
CQ88013001	EPD111050ACK0 624		
CQ79183001	EPD121023A		
D335463001	8-1200819-3, EPD99111A		
9528673001	5024A1311- 0(CO), 6-1197378- 0		

C205553001	9-1201424-7, EPD96684Q/1- 9(CO)		
CQ60833001	EPD116262ACK0 547/2		
C825683001	2-1200878-5, EPD60603C		
4101093001	3-1193093-4, 5026A1317-0(CO)		
4451733004	2524E0311-0, 7- 1193345-0		
9850413001	7522A1311- 02(CO), 6- 1197609-3		
CQ28083001	EPD113842Q/1- 1L(M3)		
5167273001	8-1194057-0, EPD77564A		
CQ76543001	EPD117757ACK0 298/1		
CQ11963001	EPD117497ACK8 500		
4263353001	5-1193208-3, EPD61324Q		
E859813001	EPD104346A, 7- 1899071-1		
4405633002	2-1193312-4, 7526A1317-0		
CQ28053001	EPD113842Q/1- 9(M2)(FS)		
CQ13743001	EPD117489A		
F539293001	1-1202051-8, EPD101750B/1- 1L(CO)		
6305193001	1194990-9, EPD35767Q		
E296603001	6-1202053-8, EPD101729M/2(C O)		
C468603001	8-1200522-4, EPD96002A/2(CO)		
9441473001	5024A1P11-9(FS), 6-1197308-4		
CT64513001	2020E0P11-9(CO)		
CQ72703001	EPD121323A		

5982693001	0024E0811-0(M), 4-1194730-8		
CD31493001	EPD106743A/3(C O), 7-1899236-4		
1770573001	1-1191287-5, EPD33631A		
CQ45653001	EPD118392A		
CQ34183001	EPD116438A		
CD50143001	7524A1P11- N(CO), 1899332-8		
6647563001	4-1199422-1, 7524A1811-0(3M)		
2901053001	6-1192199-5, EPD26467Q(S8M)		
CQ29913001	5020A1311- 0(M1)CK2240		
2993173001	1192266-9, EPD20662B/1- 1L(CO)		
D787103001	EPD104346A/1- 1L(CO)		
8221353001	7-1196411-2, EPD85875A/1- 0(CO)		
CQ79413001	2018A1811-0(CO)		
CQ95343001	EPD121048A		
1511013001	4-1191092-6, 7526A1P17-9(CO)		
CQ02493001	7522D5811-0(3M)		
E353583001	2-1201866-6, EPD95014A		
CT75433001	5020A3312-0(3M)		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.