



13-Nov-2023

**PCN #:** P-23-025350

**Subject :** Information ton inform customers of change to molded component part material

**Description of Change :** Changing molding material Ryton PPS R-4 and R-4-02 to Ryton PPS R-4-200NA and R-4-200BL. The affected component prints are not changing. TE raw material print 99640-000 is being updated to include/change the superseded Solvay part numbers.

**Reason :** Document clarification.Our material supplier Solvay has informed us that they are discontinuing the Ryton PPS R-4 and R-4-02 brands effective immediately. These products are being replaced with a direct alternative material defined as Ryton PPS R-4-200NA and R-4-200BL. The R-4-200 series materials have similar or better performance characteristics. Please find attached (TE Ryton Notification Letter PCN) datasheets for Ryton products along with supplemental data for review. TE is updating the raw material part number 99640-000 to accommodate the legacy and new changes as stated by Solvay. The below listed part numbers are end items affected by this change.

**Key Dates :**

**Contact By Date:**27-Nov-2023

**Implementation Date:**27-Nov-2023

| <b>Product Affected</b> | <b>Alias Part Number</b> | <b>Substitute Part Number</b> | <b>AliasSub Part Number</b> |
|-------------------------|--------------------------|-------------------------------|-----------------------------|
| 9-1616920-6             | BH494C                   |                               |                             |
| 1616017-9               | DH7N                     |                               |                             |
| 1616009-6               | BP494E                   |                               |                             |
| 1616004-8               | B312E                    |                               |                             |
| 1616010-6               | BR312BY                  |                               |                             |
| 1616031-1               | B459                     |                               |                             |
| 3-1616988-0             | BP494D1                  |                               |                             |
| 1616004-1               | B301EA                   |                               |                             |
| 1616073-4               | NN448B2                  |                               |                             |
| 1616056-9               | A400S                    |                               |                             |
| 7-1616923-0             | BH494F                   |                               |                             |
| 7-1616941-3             | K400B3C05                |                               |                             |

|             |            |  |  |
|-------------|------------|--|--|
| 2-1616988-9 | BP493B1    |  |  |
| 9-1616920-4 | BP493G     |  |  |
| 5-1616946-6 | K400B712C  |  |  |
| 1616119-5   | BPE494H    |  |  |
| 7-1616946-0 | K500B4B01  |  |  |
| 9-1616932-8 | BR312CJ    |  |  |
| 6-1616960-5 | BH494E2    |  |  |
| 5-1616918-6 | BR301AY    |  |  |
| 1-1616037-6 | DHR7B      |  |  |
| 2252005-7   | K4001A3C1  |  |  |
| 1616056-7   | A400F      |  |  |
| 1-1616522-0 | DH7BK      |  |  |
| 3-1616026-4 | B312CS     |  |  |
| 1616056-8   | A400G      |  |  |
| 1616062-1   | AP1077     |  |  |
| 1616037-8   | DH7BC      |  |  |
| 3-2252004-9 | KD400B2C3  |  |  |
| 1616520-2   | BR312K     |  |  |
| 1616527-1   | NN448E     |  |  |
| 4-1616954-1 | DH7NE      |  |  |
| 9-1616932-9 | BR312CL    |  |  |
| 1616045-3   | B461       |  |  |
| 1616045-6   | B461G      |  |  |
| 3-2252009-7 | DH7MAB1    |  |  |
| 7-1616969-6 | BR312Y     |  |  |
| 2-1616933-8 | DH7BH      |  |  |
| 2-1616975-4 | K4001A3B01 |  |  |
| 1616523-3   | BH360B     |  |  |
| 4-1616988-2 | K4001A3B02 |  |  |
| 1616004-3   | B301T      |  |  |
| 8-1616977-1 | K200A3C    |  |  |
| 4-1616932-9 | B312CY     |  |  |
| 1616031-3   | B459D      |  |  |
| 6-1616932-2 | B481A      |  |  |
| 1616045-2   | B460       |  |  |
| 4-1616057-4 | A400G1     |  |  |

|             |           |  |  |
|-------------|-----------|--|--|
| 8-2252006-8 | DR7M1     |  |  |
| 8-2252002-9 | K4001A1C2 |  |  |
| 1616050-1   | DH18      |  |  |
| 1616119-1   | BPE35325  |  |  |
| 2-1616988-1 | D7BE1     |  |  |
| 4-1616923-1 | DH7ND     |  |  |
| 6-1616993-0 | K400A5C2  |  |  |
| 1616524-3   | DH18Y     |  |  |
| 1-1616056-2 | A400AA1   |  |  |
| 1616045-5   | B461D1    |  |  |
| 9-1616932-5 | BR301AZ   |  |  |
| 1616533-1   | B396D     |  |  |
| 1616005-9   | B463      |  |  |
| 6-1616932-3 | B481F     |  |  |
| 1616025-1   | BP4931    |  |  |
| 1616069-4   | K400B5C   |  |  |
| 4-2252007-2 | DH7B1     |  |  |
| 1616032-6   | BH360A    |  |  |
| 6-1616932-1 | B462      |  |  |
| 2-1616520-7 | B312CC    |  |  |
| 1616068-6   | K300B2C   |  |  |
| 6-1616969-5 | BH494H1   |  |  |
| 8-1616932-6 | BH466A1   |  |  |
| 1616031-2   | B459A     |  |  |
| 1616521-3   | BP493     |  |  |
| 2-1616520-8 | B312BG    |  |  |
| 1616009-3   | BP494     |  |  |
| 1616119-4   | BPE494    |  |  |
| 1-1616037-7 | DHR7BE    |  |  |
| 6-1616949-1 | A400G2    |  |  |
| 1616017-7   | DH7MCA    |  |  |
| 1616520-9   | BH494     |  |  |
| 1616119-2   | BPE35335  |  |  |
| 1616024-1   | BH493     |  |  |
| 5-1616105-4 | BR301G4   |  |  |
| 6-1616998-5 | K4001A1C1 |  |  |

|             |           |  |  |
|-------------|-----------|--|--|
| 3-1616988-1 | BPE4941   |  |  |
| 2-1616992-8 | K500B1C   |  |  |
| 9-1616990-1 | K500A1E2  |  |  |
| 1616054-2   | SA174C    |  |  |
| 1616009-4   | BP494A    |  |  |
| 6-1616953-2 | DH7MAB    |  |  |
| 8-1616984-1 | K4001B3C3 |  |  |
| 1616518-2   | DHR7M     |  |  |
| 1616026-3   | DHR16D1   |  |  |
| 8-1616966-9 | K100B3C   |  |  |
| 1616518-1   | DHR7N     |  |  |
| 4-1616938-6 | BH494E    |  |  |
| 1616025-3   | BP493C    |  |  |
| 1616008-7   | BH494A    |  |  |
| 1-1616980-4 | DEH31     |  |  |
| 1616977-6   | AH600A1C  |  |  |
| 4-1616057-3 | A400BA    |  |  |
| 7-1616927-0 | K500B2C   |  |  |
| 1616062-2   | AP1077A   |  |  |
| 2-1616520-2 | B312K     |  |  |
| 1616054-4   | SAH163    |  |  |
| 6-1616968-5 | K4001A3C  |  |  |
| 1616023-6   | B493E     |  |  |
| 1616119-3   | BPE35360  |  |  |
| 2-2252001-7 | DH7ME4B   |  |  |
| 4-1616932-8 | B301E     |  |  |
| 1616004-7   | B312DB    |  |  |
| 1616017-6   | DH7M      |  |  |
| 3-2252001-3 | E145S1    |  |  |
| 1616032-7   | BH360C2   |  |  |
| 1616016-4   | D7MM      |  |  |
| 4-1616959-0 | K4001B3C  |  |  |
| 1616037-6   | DH7B      |  |  |
| 1-1616957-4 | D7GSZ     |  |  |
| 1616050-9   | DHR181    |  |  |
| 9-1616932-6 | BR301Z    |  |  |

|             |             |  |  |
|-------------|-------------|--|--|
| 1-1616005-1 | B481A2      |  |  |
| 1-1616057-2 | A300A       |  |  |
| 5-1616986-8 | K4001B8C2   |  |  |
| 2-1616955-0 | DR7M        |  |  |
| 1616048-3   | D18AA       |  |  |
| 1-1616530-5 | A400L       |  |  |
| 5-1616932-7 | B408        |  |  |
| 2252011-4   | DGH7B2A     |  |  |
| 1-1616580-3 | K400B5C1    |  |  |
| 9-1616957-6 | K400A4C     |  |  |
| 6-2252005-3 | KS4001B1C01 |  |  |
| 7-2252003-3 | K500B3C02   |  |  |
| 1616077-1   | B396D1      |  |  |
| 1616025-4   | BP493D      |  |  |
| 1616085-1   | AP1077B     |  |  |
| 3-2252004-7 | K4001B8C9   |  |  |
| 4-1616988-0 | K500A3B02   |  |  |
| 1-1616957-3 | D18ZZC      |  |  |
| 1616036-5   | D7GRZ       |  |  |
| 1616010-5   | BR312B      |  |  |
| 4-1616932-3 | B241DC      |  |  |
| 1616031-5   | B466B       |  |  |
| 1616009-1   | BP353       |  |  |
| 1616056-6   | A400DC      |  |  |
| 1616023-3   | B451        |  |  |
| 1616056-1   | A400        |  |  |
| 2-1616520-4 | B312E1      |  |  |
| 1616024-2   | BH493A      |  |  |
| 5-1616932-2 | B365E       |  |  |
| 9-1616920-5 | BP494K      |  |  |
| 2-1616970-8 | K500A7C01   |  |  |
| 3-1616991-3 | K500B7C02   |  |  |
| 3-2252009-0 | K4001A1H01  |  |  |
| 1-1616050-0 | DHR183      |  |  |
| 1616053-1   | NH505       |  |  |
| 4-1616959-8 | K4001B7C    |  |  |

|             |            |  |  |
|-------------|------------|--|--|
| 1-1616005-0 | B481A1     |  |  |
| 1616069-1   | K400A5C    |  |  |
| 1-1616978-4 | DH7ND1     |  |  |
| 7-1616998-7 | K500A3C03  |  |  |
| 1616520-6   | BR301E     |  |  |
| 1616037-7   | DH7BB      |  |  |
| 1616116-2   | B464       |  |  |
| 1616026-1   | DH16ED     |  |  |
| 1616107-1   | NN430A     |  |  |
| 1-1616005-2 | B490A      |  |  |
| 1-1616004-0 | B370       |  |  |
| 9-2252004-1 | K4001A12C1 |  |  |
| 1-1616980-3 | BEH494A    |  |  |
| 6-1616970-0 | K200B1C    |  |  |
| 6-1616984-2 | K200A3C1   |  |  |
| 3-1616975-3 | K500A3B01  |  |  |
| 2-1616520-9 | B312AE     |  |  |
| 2-1616960-7 | KA175B3C   |  |  |
| 4-1616951-4 | K500A2C    |  |  |
| 1-1616939-7 | K300A5C    |  |  |
| 3-2252001-4 | E145P1     |  |  |
| 1616004-4   | B312CH     |  |  |
| 2-1616933-7 | DH7B5      |  |  |
| 1616009-2   | BP353A     |  |  |
| 2-1616933-4 | DH18C      |  |  |
| 7-1616986-2 | K500B2C1   |  |  |
| 1-1616992-7 | K500A1C    |  |  |
| 1616527-3   | NN448B     |  |  |
| 2-1616963-0 | DP7B       |  |  |
| 2252009-1   | K4001A1C03 |  |  |
| 1616045-4   | B461D      |  |  |
| 8-1616984-2 | K4001B8C1  |  |  |
| 1616506-1   | SAH106T    |  |  |
| 1616031-4   | B466       |  |  |
| 1616986-6   | KD400A7C   |  |  |
| 6-1616972-9 | A400DB2    |  |  |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.