



23-Dec-2014

PCN #:E-14-018034

Subject:AMPMODU SYSTEM 50 HEADER ASSEMBLIES

Description of Change: CONSOLIDATION OF COPPER ALLOY POST MATERIAL TEMPER DUE TO CORPORATE METALS RAW MATERIALS REDUCTION INITIATIVE.

Reason: Product Improvement. PRODUCT IMPROVEMENT. NEW MATERIAL PASSES 108-1093 REQUIREMENTS.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-Mar-2015

Implementation Date:01-Mar-2015

Product Affected

104477-8

104477-6

5-104549-7

6-104118-6

5-104068-2

5-104068-1

5-146085-1

6-104074-0

5-104076-5

5-104118-3

5-104068-9

5-104666-4

5-147377-6

6-104549-0

Product Affected

5-104178-6
5-104076-2
5-104076-1
6-104068-7
5-104076-3
5-104068-6
5-104071-3
5-104186-5
5-104549-3
6-104178-1
6-104068-2
5-104074-9
5-103916-2
5-147377-4
6-104074-6
5-104071-6
5-104074-3
5-104549-6
5-104071-4
104804-3
6-104068-0
5-147377-7
6-103916-3
6-104068-5
6-104074-7
5-104477-5
104666-7
5-104186-9
6-104186-1
5-103916-3
5-104666-1
5-104178-5
5-104074-8
5-104074-7
5-147377-8
6-104071-4
5-104549-9
6-104071-3
5-104666-9
5-147377-1

Product Affected

5-104666-3

6-104068-3

5-104477-4

6-104068-6

5-147377-9

6-104068-8

5-104076-7

5-104071-1

5-104076-8

6-104549-1

6-103916-7

5-146069-1

5-104477-9

6-103916-1

(Alias Part Numbers:

"2-42938-4381")

5-104074-2

5-104118-7

5-104178-1

5-104549-8

146397-1

(Alias Part Numbers:

"CV4742-000"

"AMP-0-0146397-1")

6-104074-8

5-104549-5

6-104074-4

5-104666-2

5-104666-5

5-104074-1

5-104186-3

6-104071-7

5-104068-5

5-104074-6

5-104071-2

5-104477-7

104666-6

5-104071-5

6-104071-1

5-147377-3

Product Affected

5-104746-2
6-104071-6
5-104549-2
6-104477-2
6-104071-0
6-104666-1
6-104074-9
5-147377-2
6-103916-6
6-104666-0
5-104074-5
5-104746-1
6-103916-4
5-104068-4
104076-6
5-147377-5
5-104118-1
5-104549-1
5-104477-2
5-104186-1
5-104068-3
6-104068-1
5-104071-7
5-104074-4
6-104074-1
6-104666-3
5-103916-9
5-104071-8
1-104666-1
1-104666-0
147377-9
147377-8
147377-6
147377-5
147377-4
147377-3
147377-2
147377-1
1-104549-0
104549-9

Product Affected

104549-8

104549-7

104549-6

104549-5

104549-3

104549-2

(Alias Part Numbers:

"1228905")

104549-1

(Alias Part Numbers:

"C77907-000"

"PER-104549-1")

104076-7

104076-5

104076-1

1-104074-9

1-104074-1

1-104074-0

104074-8

104074-7

104074-6

104074-5

104074-4

104074-3

104074-2

104074-1

1-104071-6

1-104071-3

1-104071-1

1-104071-0

104071-8

104071-7

104071-6

104071-5

104071-4

104071-3

104071-2

104071-1

1-104068-7

1-104068-6

Product Affected

1-104068-4

1-104068-3

1-104068-2

1-104068-1

104068-9

104068-8

104068-6

104068-5

104068-4

104068-3

104068-2

104068-1

104746-2

1-104186-1

1-103916-7

(Alias Part Numbers:

"010-0766-00")

1-103916-6

1-103916-1

103916-9

103916-2

104666-5

104666-4

104666-3

104666-2

104666-1

104477-9

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.