



09-Jan-2015

PCN #:P-15-010917

Subject:Dyanmic 2100 Rec HSG

Description of Change: Increase lock protection thickness from 0.8mm to 2.6mm.

Reason: Product improvement.Improve lock protection broken. this problem occured at restricted customer. When shipping transportation time and harness handring time, this portion is broken at the restricted customer.

Key Dates:

Contact By Date:30-Apr-2015

Implementation Date:30-Apr-2015

Product Affected

- 1-1318120-3
- 2-1318119-3
- 9-1318119-3
- 1-1318119-3
- 9-1318118-8
- 1-1318118-8
- 3-1318118-6
- 9-1318118-9
- 1-1318119-4
- 1-1318118-6
- 2-1318118-6
- 2-1318119-4
- 1-1318118-9
- 3-1318120-3

Product Affected

2-1318120-3

9-1318119-4

9-1318120-3

9-1318118-6

2-1318118-8

2-1318118-9

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.