



26-Feb-2015

PCN #:E-15-002423

Subject:1410187-X Right angle plug assembly, 7 Row, 20.3mm Multigig

Description of Change: TE production Drawing 1410187-X is missing the arrows pointer at the wafers location in Zones D7 and D8. There have been no changes to the existing parts, this is a revision increase only.

Reason: Document Clarification. Software glitched, it caused the TE PD 1410187-X missed the arrows pointer in Zone D7 and D8.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:02-Mar-2015

Implementation Date:02-Mar-2015

Product Affected

1410187-1

1410187-3

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE

Connectivity Sales Representative.