



03-Mar-2015

PCN #:E-15-003228

Subject:PTL Recptacle Contact 1971783, 1971779, 1971781, 1971785, 19

Description of Change: On all remove tear drop shaped cutout on underside and add reverse bow in front of latch window. On 1971783 drawing add 2x #22 AWG wire. This change is considered by TE Connectivity as an improvement.

Reason: Product Improvement. Improve allignment with Tab contact and facilitate manufacturing. For 1971783, expand wire range per customer request.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:09-Mar-2015

Implementation Date:09-Mar-2015

Product Affected

- 1971779-2
- 1971237-1
- 1971787-1
- 1971781-1
- 1971783-1
- 1971787-2
- 1971783-2
- 1971781-2
- 1971785-2
- 1971237-2
- 1971785-1
- 1971779-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.