



14-May-2015

PCN #:P-15-011645

Subject:1.2mm CB Receptacle

Description of Change: North America and South America customers only - TE Connectivity is informing you of a new capacity die to produce the below listed PNs. The new die will be located at TE Burgess Road facility in NC. Please contact your TE Sales Engineer or Customer Service Representative if you have additional questions.

Reason: Product improvement.Dear North America and South America customers, as a result of our continuous strive for improving our delivery and meet our customers' demand needs, we hereby inform you about the addition of new capacity die that will support North and South America customers only. Other global customers are not impacted by this capacity die. If you require a PPAP, please contact your TE Sales Engineer so that one can be requested on your behalf. SAP team, please do not place delivery block on this PN so as not to interrupt existing deliveries.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:30-Nov-2015

Implementation Date:30-Nov-2015

Product Affected

1418850-3

1418844-3

1670146-3

1418850-1

1418844-1

1670146-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.