



26-Jun-2015

PCN #:P-15-011770

Subject:DEUTSCH DT06-2S-XXXX DT 2 Way Plugs

Description of Change: Small bumps have been added to the leading surface of the DT 2 way front seals.

Reason: Product improvement. Dear customer, we are contacting you to notify you of a small change to the DT plug connector family. This change is necessary to facilitate the automatic assembly process. While there is a small impact to part form, the fit and function of the part are not impacted. Both configurations of the part function the same previous revision parts are not obsolete and may be used in addition to the new revision. Shipments of bump and non-bump parts may be mixed. **IMPORTANT:** This is a continual improvement so the current and previous revisions of these parts can be used interchangeably in the field. These changes are being phased-in gradually and previous revision can remain stocked until use.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:30-Sep-2015

Implementation Date:30-Sep-2015

Product Affected

DT06-2S-LC01

DT06-2S

(Alias Part Numbers:

"ZPF000000000130172"

"DT06-2S-AS"

"DT06-2S-LD"

"DT06-2S-LS"

"DT06-2S-L")

Product Affected

DT06-2S-P012

(Alias Part Numbers:

"ZPF000000000130186"

"DT06-2S-P012-AS"

"DT06-2S-P012-LD"

"DT06-2S-P012-LS"

"DT06-2S-P012-MS"

"DT06-2S-P012-E"

"DT06-2S-P012-L"

"DT06-2S-P012-M")

DT06-2S-CE03

DT06-2S-E005

(Alias Part Numbers:

"ZPF000000000130184")

DT06-2S-EP04

(Alias Part Numbers:

"ZPF000000000139813")

DT06-2S-CE01

(Alias Part Numbers:

"ZPF000000000130173")

DT06-2S-P060

DT06-2S-CE04

(Alias Part Numbers:

"ZPF000000000130174")

DT06-2S-E004

(Alias Part Numbers:

"ZPF000000000130183")

DT06-2S-E003

(Alias Part Numbers:

"ZPF000000000130182")

DT06-2S-C017

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.