



14-Dec-2015

PCN #:P-15-012409

Subject:Mass Parts Obsolescence

Description of Change: Parts not in stock or showing as having any global stock movements to be made obsolete.

Reason: Part status change.Part status change to help with tidying up of REACH/RoHS data.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:10-Dec-2015

Implementation Date:10-Dec-2015

Product Affected

884415-001

(Alias Part Numbers:

"9-1196882-8"

"TV06RW-11-01-PD-L/C")

C73724-000

(Alias Part Numbers:

"8-1201277-5"

"HSJC0/1-0/22615K")

682079-000

(Alias Part Numbers:

"5-1195361-9"

"D38999/24WF11SN")

1-161209-3

CH1337-000

(Alias Part Numbers:

Product Affected

"HSJC0-26802K"

"4-1899532-5")

CV0935-000

(Alias Part Numbers:

"6-1899735-8"

"KHKB-26411")

416637-000

(Alias Part Numbers:

"8-1193139-3"

"D38999/26WJ35SA")

D16577-000

(Alias Part Numbers:

"4-1202064-3"

"HSJC0/3-0/23987F")

E67020-000

(Alias Part Numbers:

"7-1201713-3"

"HSJC0/14-0/23381F")

CA6876-000

(Alias Part Numbers:

"HSJC0/19-0/24661K"

"1-1899128-8")

E26089-000

(Alias Part Numbers:

"1-1200624-5"

"HBJC3/6-0/21006G")

269257-001

(Alias Part Numbers:

"3-1191987-2"

"PTG55A-10-7-SN")

CV1463-000

(Alias Part Numbers:

"KHKB-25969")

D96759-000

(Alias Part Numbers:

"7-1200624-2"

"HSJC0/5-0/21036G")

D43133-000

(Alias Part Numbers:

"1-1899079-0"

Product Affected

"HSJC0/1-0/24327K")

CH4986-000

(Alias Part Numbers:

"4-1899654-1"

"HSJC0-27458K")

CV0516-000

(Alias Part Numbers:

"8-1899722-9"

"HBJC4-27627F")

CF7728-001

(Alias Part Numbers:

"10-241802-127"

"6-1899233-8")

D24003-001

(Alias Part Numbers:

"7-1201441-9"

"602GB06E12-10SN(416)")

CG6761-000

(Alias Part Numbers:

"HSJC0-25538K"

"7-1899268-2")

CH2997-000

(Alias Part Numbers:

"2-1899602-5"

"KHKB-27172")

CV1301-000

(Alias Part Numbers:

"5-1899751-0"

"KHKB-26464R11243")

CH1001-001

(Alias Part Numbers:

"TV06RW-11-02PN(W52)"

"2-1899522-5")

861754-000

(Alias Part Numbers:

"8-1199529-7"

"HSJC0/3-0/19591K")

CH1757-001

(Alias Part Numbers:

"9-1899551-9"

Product Affected

"RS-290-4588")

CH2805-000

(Alias Part Numbers:

"2-1899593-3"

"KHKB-27158")

314889-001

(Alias Part Numbers:

"1-1192383-0"

"CECC75201002-CD35MCAA01G")

CV0339-000

(Alias Part Numbers:

"7-1899711-6"

"KHKB-27576")

854597-001

(Alias Part Numbers:

"5-1196661-1"

"CECC75201002-AD97FCNA01G")

CV0306-000

(Alias Part Numbers:

"1899711-1"

"KHKB-27600")

318888-000

(Alias Part Numbers:

"8-1198300-8"

"D38999/26WC4SN")

CH3530-000

(Alias Part Numbers:

"6-1899613-2"

"HSJC0-27237K")

CH1350-000

(Alias Part Numbers:

"KHKB-26808"

"6-1899532-0")

CV0337-000

(Alias Part Numbers:

"7-1899711-4"

"KHKB-27574")

CH1357-000

(Alias Part Numbers:

"HSJC0-26812K"

Product Affected

"7-1899532-1")

368559-000

(Alias Part Numbers:

"3-1192762-9"

"HSJC0/6-6/14177K")

011315-000

(Alias Part Numbers:

"5-1190089-5"

"D38999/26WH21PN")

CJ7445-001

(Alias Part Numbers:

"M39029/58-353"

"1899304-8")

9-161117-3

CN6323-000

(Alias Part Numbers:

"7-1899489-2"

"KHKB-26045")

CH3597-000

(Alias Part Numbers:

"2-1899615-3"

"HSJC0-27179K")

CV0266-001

(Alias Part Numbers:

"4-1899710-9"

"418-5052/11-35SB(W52W280)")

CJ5941-001

(Alias Part Numbers:

"OC-015"

"1899294-9")

595385-000

(Alias Part Numbers:

"4-1194708-3"

"D38999/26WE35SA")

CN8125-000

(Alias Part Numbers:

"HSJC0-26038K"

"6-1899499-2")

CH2977-000

(Alias Part Numbers:

Product Affected

"8-1899600-2"

"KHKB-834747")

F51723-001

(Alias Part Numbers:

"3-1201549-2"

"102-1951")

CJ0048-000

(Alias Part Numbers:

"HSJC0/1-0/24603K"

"8-1899245-0")

CM3754-001

(Alias Part Numbers:

"TR1807PFS1NBE"

"5-1899410-9")

E91378-000

(Alias Part Numbers:

"1-1201489-8"

"HSJC0/2-0/22183K")

CV2035-000

(Alias Part Numbers:

"KHKB-8500")

184941-000

(Alias Part Numbers:

"1-1191343-6"

"62GB-56T-16-26S")

C54398-000

(Alias Part Numbers:

"HSJC0/108-4/24272K"

"3-1899067-6")

5-161107-0

CP8104-000

(Alias Part Numbers:

"HSJC0-26922K"

"7-1899555-3")

CH1056-001

(Alias Part Numbers:

"JT02RE-14-35SA-023"

"4-1899523-3")

CV2021-000

(Alias Part Numbers:

Product Affected

"9-1899767-2"

"KHKB-27814")

CG6752-000

(Alias Part Numbers:

"HSJC0-25529K"

"4-1899268-7")

699906-000

(Alias Part Numbers:

"HSJC0/4-1/24343K"

"8-1899068-6")

CV1294-000

(Alias Part Numbers:

"1899751-8"

"KHKB-27559R39030")

366453-001

(Alias Part Numbers:

"7-1192747-5"

"488-208")

CH2721-000

(Alias Part Numbers:

"1-1899590-9"

"HSJC0-27125K")

CA7681-001

(Alias Part Numbers:

"508/1/31026/140"

"1899132-3")

D77674-000

(Alias Part Numbers:

"HSJC0/4-4/24028F")

C15015-000

(Alias Part Numbers:

"3-1200625-4"

"HSJC0/5-0/21046G")

F39307-000

(Alias Part Numbers:

"6-1201547-5"

"D38999/20WD19PN")

605163-001

(Alias Part Numbers:

"3-1194788-1"

Product Affected

"CECC75201002-AB35FCNA01G")

CH3339-000

(Alias Part Numbers:

"2-1899610-4"

"KHKB-27254")

811703-000

(Alias Part Numbers:

"5-1196313-6"

"D38999/26WA98SA")

8-161117-4

CV0055-001

(Alias Part Numbers:

"5-1899704-1"

"418-5052/11-98SB(W52W280)")

CH1338-000

(Alias Part Numbers:

"KHKB-26802"

"4-1899532-6")

329669-000

(Alias Part Numbers:

"1192492-6"

"D38999/26WH53SN")

CJ3056-000

(Alias Part Numbers:

"D38999/26FC35SA"

"8-1899270-5")

EB1256-000

(Alias Part Numbers:

"D38999/26#E26PA-ZNCO")

822327-000

(Alias Part Numbers:

"1-1196413-7"

"D38999/20WC08PN")

646163-001

(Alias Part Numbers:

"418-1406-9"

"1195103-8")

CV1281-000

(Alias Part Numbers:

"6-1899750-1"

Product Affected

"KHKB-27682")

CN7743-000

(Alias Part Numbers:

"HSJC0-25984K"

"5-1899497-7")

CV1027-000

(Alias Part Numbers:

"6-1899740-7"

"KHKB-27664")

CA6704-000

(Alias Part Numbers:

"HSJC0-23942K/1-CS2106"

"5-1899126-9")

CH1767-000

(Alias Part Numbers:

"6-1899552-4"

"KHKB-26900")

CH2742-000

(Alias Part Numbers:

"3-1899590-6"

"KHKB-26936")

CN7329-001

(Alias Part Numbers:

"BACC63BP14D7PN"

"9-1899495-2")

CH2649-000

(Alias Part Numbers:

"7-1899588-8"

"KHKB-815933")

F69559-000

(Alias Part Numbers:

"1-1202092-4"

"HSJC0/1-0/22823K")

CH4290-000

(Alias Part Numbers:

"1899636-1"

"KHKB-27339")

CL0039-001

(Alias Part Numbers:

"163-448"

Product Affected

"8-1899316-0")

CF2763-001

(Alias Part Numbers:

"130106"

"1-1899206-4")

CV0583-001

(Alias Part Numbers:

"2-1899726-6"

"GF062HDC4LNE")

CH0815-000

(Alias Part Numbers:

"KHKB-26648"

"3-1899517-7")

CG6753-000

(Alias Part Numbers:

"HSJC0-25530K"

"4-1899268-8")

CN6328-000

(Alias Part Numbers:

"7-1899489-7"

"KHKB-26040")

F45815-001

(Alias Part Numbers:

"454-283"

"4-1199706-8")

CN0912-001

(Alias Part Numbers:

"180-091NFH7-13-4PN"

"9-1899459-4")

CN9320-000

(Alias Part Numbers:

"HSJC0-25998K"

"7-1899506-8")

CL8382-001

(Alias Part Numbers:

"5-1899370-7"

"KTFG-4518")

CJ3066-000

(Alias Part Numbers:

"62GB-56TG16-26S(416)"

Product Affected

"9-1899270-4")

C35024-000

(Alias Part Numbers:

"3-1200414-6"

"D38999/24WE35PC")

CH3203-000

(Alias Part Numbers:

"6-1899607-7"

"HSJC0-27142K")

E16084-000

(Alias Part Numbers:

"1-1200624-0"

"HBJC3/11-0/21037G")

042652-000

(Alias Part Numbers:

"9-1200085-6"

"HSJC0/5-2/20093F")

CH1815-000

(Alias Part Numbers:

"1-1899554-1"

"HSJC0-26903K")

628207-000

(Alias Part Numbers:

"8-1194973-1"

"D38999/26WB1PC")

CH5194-000

(Alias Part Numbers:

"2-1899660-2"

"KHKB-27380")

C56886-000

(Alias Part Numbers:

"8-1200624-2"

"HSJC0/2-0/21212G")

CJ8604-000

(Alias Part Numbers:

"KHKB-25578/1-MS"

"1-1899309-8")

A00265-000

(Alias Part Numbers:

"9-1201207-4"

Product Affected

"KTFA-4440")

CH2755-000

(Alias Part Numbers:

"8-1899590-6"

"HBJC0-27133F")

CV2663-000

(Alias Part Numbers:

"KHKB-27383R49552")

CM8398-001

(Alias Part Numbers:

"3-1899441-4"

"RS521-2/02")

D05494-000

(Alias Part Numbers:

"HBJC7/12-6/24179K"

"3-1899066-1")

CJ0597-001

(Alias Part Numbers:

"AB05-6100-10-06SN00"

"7-1899248-1")

CG6699-000

(Alias Part Numbers:

"HSJC0-25476K"

"9-1899265-4")

CH1907-000

(Alias Part Numbers:

"2-1899559-3"

"HSJC0-26955F")

004793-000

(Alias Part Numbers:

"6-1190036-5"

"D38999/24WC98SN")

EB1308-000

(Alias Part Numbers:

"D38999/26#J4PN-ZNCO")

CH3336-000

(Alias Part Numbers:

"2-1899610-1"

"KHKB-27251")

161204-9

Product Affected

983045-000

(Alias Part Numbers:

"2-1197595-2"

"HSJC0/4-2/16711K")

CN7579-000

(Alias Part Numbers:

"KHKB-25984"

"1899497-2")

CN9230-000

(Alias Part Numbers:

"HBJC4-26692F"

"1-1899506-3")

CJ1672-000

(Alias Part Numbers:

"HSJC0/2-2/24130K"

"9-1899254-6")

CN2289-001

(Alias Part Numbers:

"193376-0160"

"3-1899469-8")

CV0068-000

(Alias Part Numbers:

"8-1899704-0"

"KHKB-27485")

C58798-000

(Alias Part Numbers:

"HBJC8/20-3/24286K"

"4-1899066-2")

CH2565-000

(Alias Part Numbers:

"6-1899585-5"

"KHKB-26402")

491119-000

(Alias Part Numbers:

"7-1193673-6"

"D38999/26WE26SN")

CH3098-000

(Alias Part Numbers:

"2-1899605-9"

"KHKB-836508")

Product Affected

CF0050-001

(Alias Part Numbers:
"MS3456LS-36-52P"
"9-1899147-4")

CH1170-000

(Alias Part Numbers:
"KHKB-26707"
"1-1899527-1")

C19625-000

(Alias Part Numbers:
"HSJC0/5-1/24270K"
"1899069-2")

CH4702-000

(Alias Part Numbers:
"1-1899647-6"
"KHKB-16739")

310098-000

(Alias Part Numbers:
"3-1200084-8"
"HSJC0/5-2/20034F")

C67357-000

(Alias Part Numbers:
"9-1201283-1"
"GD400341-0316-00")

CN4589-000

(Alias Part Numbers:
"8-1899480-4"
"KHKB-26374")

CH2038-001

(Alias Part Numbers:
"6-1899564-8"
"608-36T18-32SC")

CH2546-000

(Alias Part Numbers:
"4-1899585-6"
"KHKB-27121LU")

CH5318-000

(Alias Part Numbers:
"3-1899668-4"
"HSJC0-27473K")

Product Affected

032043-000

(Alias Part Numbers:

"4-1190248-6"

"HBJC3/4-0/16713K")

CN8039-000

(Alias Part Numbers:

"KHKB-26587"

"1-1899499-3")

CH3237-001

(Alias Part Numbers:

"1899608-6"

"D38999/26#B2SB-ZNCO")

CL5321-000

(Alias Part Numbers:

"KHKB-25596/2-MS"

"8-1899352-4")

CN3575-001

(Alias Part Numbers:

"BACC63BV14B7S8"

"6-1899475-9")

CH2406-000

(Alias Part Numbers:

"5-1899581-1"

"HBJC4-25078K")

CN1942-000

(Alias Part Numbers:

"7-1899466-1"

"KHKB-25548")

CG6708-000

(Alias Part Numbers:

"HSJC0-25485K"

"1899266-5")

CH3315-000

(Alias Part Numbers:

"9-1899609-4"

"HSJC0-27263K")

161612-000

(Alias Part Numbers:

"9-1199142-6"

"D38999/26WD5PA")

Product Affected

CH1549-000

(Alias Part Numbers:

"KHKB-26523"

"1899542-4")

CH2892-000

(Alias Part Numbers:

"1899598-6"

"KHKB-23123")

A62628-000

(Alias Part Numbers:

"1-1200625-3"

"HSJC0/10-0/21026G")

CH2728-000

(Alias Part Numbers:

"2-1899590-5"

"KHKB-27125")

CN6338-000

(Alias Part Numbers:

"8-1899489-4"

"HSJC0-26040K")

CM8479-000

(Alias Part Numbers:

"9-1899441-1"

"KHKB-26353")

416415-6

416415-8

CH2155-000

(Alias Part Numbers:

"1-1899569-2"

"KHKB-12430")

CN2439-000

(Alias Part Numbers:

"602GB05EG10-6S(586)"

"6-1899470-5")

519232-000

(Alias Part Numbers:

"5-1199530-0"

"HSJC0/10-4/19572K")

C69498-000

(Alias Part Numbers:

Product Affected

"3-1202089-1"

"HSJC0/18-0/24096F")

CH4421-000

(Alias Part Numbers:

"8-1899638-3"

"KHKB-25408")

CG6731-000

(Alias Part Numbers:

"HSJC0-25508K"

"1-1899268-0")

CH2079-001

(Alias Part Numbers:

"9-1899565-4"

"APH21-033123-546")

CN5508-001

(Alias Part Numbers:

"RS-541-4599"

"8-1899486-9")

167551-001

(Alias Part Numbers:

"9-1191219-4"

"D38999/20WA35SN")

CH3260-000

(Alias Part Numbers:

"4-1899608-3"

"HSJC0-27227F")

F72814-000

(Alias Part Numbers:

"6-1202064-9"

"HSJC0/9-8/23967F")

CF7723-001

(Alias Part Numbers:

"120R-1/4-WATT"

"6-1899233-5")

D03521-000

(Alias Part Numbers:

"1200625-1"

"HSJC0/5-0/21051G")

129617-000

(Alias Part Numbers:

Product Affected

"3-1190941-2"

"D38999/26WF35SA")

D14810-000

(Alias Part Numbers:

"1200625-7"

"HSJC0/4-0/21235G")

CV1461-000

(Alias Part Numbers:

"KHKB-25963")

CN5405-000

(Alias Part Numbers:

"2-1899486-1"

"KHKB-26042")

9-161117-0

C16916-000

(Alias Part Numbers:

"HBJC2/8-0/24033F")

CN4588-000

(Alias Part Numbers:

"8-1899480-3"

"KHKB-26373")

CN5406-000

(Alias Part Numbers:

"2-1899486-2"

"KHKB-26046")

932403-000

(Alias Part Numbers:

"2-1197227-0"

"HSJC0/1-0/18221K")

CV1458-000

(Alias Part Numbers:

"2-1899756-1"

"HSJC0-25971K")

C75165-001

(Alias Part Numbers:

"5-1200620-1"

"MS3126E8-2PN")

E83613-000

(Alias Part Numbers:

"6-1200623-5"

Product Affected

"HSJC0/5-0/21050G")

770313-000

(Alias Part Numbers:

"7-1196001-5"

"D38999/26WG35SA")

CH4609-001

(Alias Part Numbers:

"1-1899645-3"

"D38999/26#G75SN-ZNCO")

A27399-000

(Alias Part Numbers:

"HSJC0/8-0/24155K"

"1-1899069-7")

CV0195-000

(Alias Part Numbers:

"1899708-9"

"KHKB-27559")

CH1326-000

(Alias Part Numbers:

"KHKB-26796"

"3-1899532-4")

CJ7107-001

(Alias Part Numbers:

"181-111"

"3-1899302-3")

158701-000

(Alias Part Numbers:

"8-1191146-0"

"HSJC0/38-13/13734K")

CF0369-001

(Alias Part Numbers:

"7-1899159-6"

"418-6031-13P1201-09")

EB1143-000

(Alias Part Numbers:

"D38999/20#F32SN-ZNCO")

CH3332-000

(Alias Part Numbers:

"1-1899610-6"

"KHKB-27247")

Product Affected

CH1351-000

(Alias Part Numbers:

"HSJC0-26809K"

"6-1899532-2")

CL3938-001

(Alias Part Numbers:

"CR06180-6"

"6-1899341-5")

CV0814-001

(Alias Part Numbers:

"7-1899732-4"

"418-6032-17P0601-04")

D54437-000

(Alias Part Numbers:

"5-1201836-7"

"HBJC6/12-0/23601F")

CH2541-001

(Alias Part Numbers:

"4-1899585-1"

"RS-267-3694")

CJ2766-001

(Alias Part Numbers:

"SB-ORD-130"

"5-1899266-9")

CH5181-000

(Alias Part Numbers:

"1899660-9"

"KHKB-27367")

CM8397-001

(Alias Part Numbers:

"RS-231-1374"

"3-1899441-2")

CH0764-000

(Alias Part Numbers:

"KHKB-736306"

"7-1899515-4")

CV0316-000

(Alias Part Numbers:

"1-1899711-0"

"KHKB-27610")

Product Affected

A72873-000

(Alias Part Numbers:

"6-1200318-1"

"HBJC4/4-0/20606F")

CH4530-000

(Alias Part Numbers:

"7-1899640-1"

"KHKB-27343HS")

CH7803-000

(Alias Part Numbers:

"5-1899685-6"

"KHKB-16687")

A08308-001

(Alias Part Numbers:

"5-1201445-4"

"5940-99-971-9170")

C99312-001

(Alias Part Numbers:

"5-1201510-5"

"534-783")

CJ0536-001

(Alias Part Numbers:

"HCPH380"

"5-1899248-0")

CM1009-001

(Alias Part Numbers:

"MS3106E-40-56P"

"4-1899387-3")

042749-000

(Alias Part Numbers:

"8-1190327-9"

"HSJC0/1-0/18218K")

CJ8561-001

(Alias Part Numbers:

"M80-8890405"

"8-1899308-9")

CH0819-000

(Alias Part Numbers:

"KHKB-26708"

"4-1899517-1")

Product Affected

CH1165-000

(Alias Part Numbers:

"KHKB-26702"

"1899527-6")

C56560-000

(Alias Part Numbers:

"1-1201760-5"

"HSJC0/2-0/23119K")

CH3350-000

(Alias Part Numbers:

"3-1899610-5"

"KHKB-27265")

979557-000

(Alias Part Numbers:

"6-1197566-8"

"HSJC0/1-0/18223K")

CG6705-000

(Alias Part Numbers:

"HSJC0-25482K"

"1899266-2")

CV1278-000

(Alias Part Numbers:

"5-1899750-8"

"KHKB-27679")

CH4983-001

(Alias Part Numbers:

"3-1899654-8"

"PC10015-06-20-2PA-1-ZB")

336431-000

(Alias Part Numbers:

"3-1192540-3"

"D38999/20WA98SN")

CG6644-000

(Alias Part Numbers:

"HSJC0-25421K"

"3-1899265-0")

CH1575-000

(Alias Part Numbers:

"9-1899543-5"

"HSJC0-26860K")

Product Affected

CL0025-001

(Alias Part Numbers:

"15366021"

"6-1899316-8")

CH4412-000

(Alias Part Numbers:

"3-1899638-7"

"KHKB-25542")

A82097-000

(Alias Part Numbers:

"2-1201852-7"

"HBJC3/14-2/23354K-10")

CH4405-000

(Alias Part Numbers:

"3-1899638-0"

"KHKB-25490")

CN9454-001

(Alias Part Numbers:

"RS-408-9451"

"8-1899507-4")

CH2527-000

(Alias Part Numbers:

"6-1899584-9"

"HSJC0-27120K")

CM9446-001

(Alias Part Numbers:

"PC4D0002-C-19A-1-CZ"

"6-1899448-9")

CN6342-000

(Alias Part Numbers:

"HBJC0/4-2/23302K"

"8-1899489-9")

CH4406-000

(Alias Part Numbers:

"3-1899638-1"

"KHKB-25491")

CN2625-001

(Alias Part Numbers:

"RS-613-9233"

"3-1899471-9")

Product Affected

158482-000

(Alias Part Numbers:

"4-1198852-8"

"D38999/26WH35SC")

D03748-000

(Alias Part Numbers:

"HBJC7/48-6/24234K"

"1899067-5")

CH1219-001

(Alias Part Numbers:

"221C14F22"

"4-1899528-0")

CH1764-000

(Alias Part Numbers:

"6-1899552-1"

"HSJC0-26900K")

913067-000

(Alias Part Numbers:

"1197090-4"

"HSJC0/10-0/12379K")

641617-000

(Alias Part Numbers:

"1-1195071-4"

"HSJC0/3-0/18317K")

CA7244-000

(Alias Part Numbers:

"HSJC0/2-0/24548K"

"9-1899129-3")

CH0760-000

(Alias Part Numbers:

"KHKB-736297"

"7-1899515-0")

CV1495-001

(Alias Part Numbers:

"RS-622-6977")

CH1565-000

(Alias Part Numbers:

"3-1899543-9"

"KHKB-26878")

D12355-000

Product Affected

(Alias Part Numbers:

"9-1200912-7"

"HSJC0/5-0/21564F")

CV0324-000

(Alias Part Numbers:

"6-1899711-1"

"KHKB-27612")

E04417-001

(Alias Part Numbers:

"7-1201648-8"

"99-0406-75-03")

433159-000

(Alias Part Numbers:

"1193258-5"

"HSJC0/15-8/16718K")

CH4446-000

(Alias Part Numbers:

"1-1899639-3"

"KHKB-25501")

986691-000

(Alias Part Numbers:

"9-1197620-7"

"D38999/26WG41SN")

308585-000

(Alias Part Numbers:

"3-1192337-2"

"D38999/24WJ8AC")

CJ3989-001

(Alias Part Numbers:

"EGG-0K-303-CLL"

"7-1899276-8")

CN7480-000

(Alias Part Numbers:

"KHKB-26036"

"6-1899496-7")

E99542-000

(Alias Part Numbers:

"HSJC0/8-1/24296K"

"2-1899069-3")

CG6817-000

Product Affected

(Alias Part Numbers:

"HSJC0-25594K"

"8-1899269-1")

CG6744-000

(Alias Part Numbers:

"HSJC0-25521K"

"3-1899268-6")

CF0388-000

(Alias Part Numbers:

"HSJC0/12-12/24963K"

"5-1899161-9")

CN0016-000

(Alias Part Numbers:

"KHKB-VCS/CONNECTORS"

"9-1899453-6")

CH2425-000

(Alias Part Numbers:

"7-1899581-0"

"KHKB-25075")

085053-000

(Alias Part Numbers:

"1-1190628-2"

"D38999/24WF35SN")

E84328-000

(Alias Part Numbers:

"3-1201825-2"

"HSJC0/3-0/22180K")

CH2615-001

(Alias Part Numbers:

"7-1899587-0"

"380-A-S-009-N-14-05-F3")

CH6164-000

(Alias Part Numbers:

"3-1899677-4"

"KHKB-18879")

CA6660-001

(Alias Part Numbers:

"DTS26Z17-28PN951H"

"3-1899126-2")

CH2525-001

Product Affected

(Alias Part Numbers:

"6-1899584-2"

"RS-267-3587")

CH5321-000

(Alias Part Numbers:

"3-1899668-7"

"HSJC0-24931K")

CV2354-000

(Alias Part Numbers:

"KHKB-26811R78969")

003447-000

(Alias Part Numbers:

"1-1190026-1"

"HBJC4/7-0/16784K")

A62735-000

(Alias Part Numbers:

"2-1200085-4"

"HBJC3/10-0/20114F")

CH2039-001

(Alias Part Numbers:

"6-1899564-9"

"CH2038-001")

A72891-000

(Alias Part Numbers:

"1-1200625-8"

"HSJC0/5-0/21056G")

CH4947-000

(Alias Part Numbers:

"2-1899653-0"

"KHKB-27436")

CM2985-000

(Alias Part Numbers:

"3-1899402-8"

"KHKB-25596")

CG6766-000

(Alias Part Numbers:

"HSJC0-25543K"

"8-1899268-1")

CN7568-000

(Alias Part Numbers:

Product Affected
"KHKB-25695"
"8-1899496-9")
CN5447-000
(Alias Part Numbers:
"5-1899486-0"
"HSJC0-26032K")
CV2574-000
(Alias Part Numbers:
"KHKB-27825")
C45971-001
(Alias Part Numbers:
"9-1201890-3"
"BCPC6S-1")
CH8060-000
(Alias Part Numbers:
"7-1899687-2"
"KHKB-16721")
335715-000
(Alias Part Numbers:
"8-1192535-1"
"HSJC0/4-0/16760K")
CH3334-000
(Alias Part Numbers:
"1-1899610-8"
"KHKB-27249")
CH4002-000
(Alias Part Numbers:
"2-1899627-1"
"KHKB-27329")
CH1585-000
(Alias Part Numbers:
"1899544-6"
"KHKB-26861")
CH8059-000
(Alias Part Numbers:
"7-1899687-1"
"KHKB-16742")
CJ1445-001
(Alias Part Numbers:
"RR00E22-7SN-9443"

Product Affected
"4-1899253-7")
939891-001
(Alias Part Numbers:
"617050-001"
"2-1197278-9")
D21617-000
(Alias Part Numbers:
"1201727-8"
"HSJC0/10-0/23042K")
CH1557-000
(Alias Part Numbers:
"KHKB-26854"
"8-1899542-0")
CV0988-000
(Alias Part Numbers:
"KHKB-27661HS")
CN7483-000
(Alias Part Numbers:
"KHKB-26583"
"7-1899496-0")
716379-000
(Alias Part Numbers:
"8-1195604-9"
"D38999/24WD35PN")
CA4946-000
(Alias Part Numbers:
"HSJC0-24759F"
"2-1899116-8")
CM1013-001
(Alias Part Numbers:
"MS3106R-28-51S"
"4-1899387-5")
CH1898-000
(Alias Part Numbers:
"1-1899559-3"
"HSJC0-26945F")
CN3075-000
(Alias Part Numbers:
"7-1899473-1"
"KHKB-18853")

Product Affected

CH3826-000

(Alias Part Numbers:

"5-1899622-9"

"KHKB-862872")

772124-001

(Alias Part Numbers:

"454-277"

"9-1199705-2")

CF0954-000

CF0128-000

(Alias Part Numbers:

"HSJC0/62-0/21476K"

"1899152-8")

752828-000

(Alias Part Numbers:

"1-1200085-5"

"HSJC0/5-0/20098F")

CH2500-000

(Alias Part Numbers:

"3-1899583-5"

"KHKB-27090")

F19755-000

(Alias Part Numbers:

"HBJC3/31-12/24255K"

"6-1899066-8")

CV0489-000

(Alias Part Numbers:

"3-1899719-8"

"HSJC0-19689K")

CN5449-000

(Alias Part Numbers:

"5-1899486-2"

"HSJC0-26042K")

947522-000

(Alias Part Numbers:

"9-1200083-3"

"HSJC0/5-2/20084F")

D67611-000

(Alias Part Numbers:

"8-1202076-0"

Product Affected
"HBJC5/19-0/24011F")
596945-001
(Alias Part Numbers:
"1-1194721-4"
"FV585080")
CH2610-001
(Alias Part Numbers:
"6-1899587-5"
"6020-18-32SF0")
CH3589-000
(Alias Part Numbers:
"9-1899614-0"
"KHKB-821659")
CJ3881-001
(Alias Part Numbers:
"USB -1.1-(A)-PLUG"
"6-1899276-4")
049801-000
(Alias Part Numbers:
"4-1190381-8"
"HSJC0/1-0/18146K")
CH3202-000
(Alias Part Numbers:
"6-1899607-6"
"HSJC0-27140K")
348001-000
(Alias Part Numbers:
"8-1192618-2"
"D38999/26WF32SN")
C60905-000
(Alias Part Numbers:
"HSJC0/3-0/24216K"
"8-1899068-1")
CG6820-000
(Alias Part Numbers:
"HSJC0-25597K"
"8-1899269-4")
251513-001
(Alias Part Numbers:
"1-1191843-4"

Product Affected
"C2507-10SL-3HNO")
F89814-000
(Alias Part Numbers:
"3-1201789-3"
"GD400054-0178-00R")
A37679-000
(Alias Part Numbers:
"1202036-9"
"HSJC0/10-0/23632K")
CG6812-000
(Alias Part Numbers:
"HSJC0-25589K"
"7-1899269-6")
137057-001
(Alias Part Numbers:
"6-1190993-2"
"D38999/24WB98SN")
CV3180-000
(Alias Part Numbers:
"G9588S1632NF6")
CH4814-000
(Alias Part Numbers:
"9-1899649-2"
"HBJC3-25297K")
CH3625-000
(Alias Part Numbers:
"3-1899617-5"
"KHKB-27298")
C40346-000
(Alias Part Numbers:
"7-1199521-0"
"HSJC0/14-0/19592K")
F92044-001
(Alias Part Numbers:
"5-1201760-8"
"DSS5XPXXB01X")
CV1497-001
(Alias Part Numbers:
"A30199")
CH4155-000

Product Affected

(Alias Part Numbers:

"3-1899631-5"

"KHKB-951088")

075479-000

(Alias Part Numbers:

"2-1190564-8"

"HBJC3/7-0/13547K")

889441-000

(Alias Part Numbers:

"62GB-523-08-33P"

"7-1196919-2")

579968-000

(Alias Part Numbers:

"8-1200084-3"

"HBJC4/9-0/20048F")

158978-000

(Alias Part Numbers:

"6-1197928-6"

"W700-ENG-CHG-FR")

CN0867-000

(Alias Part Numbers:

"7-1899459-7"

"KHKB-25401")

CH8967-000

(Alias Part Numbers:

"1899695-4"

"KHKB-26356")

A13966-000

(Alias Part Numbers:

"7-1201228-1"

"GD400087-0180-03")

CH3220-000

(Alias Part Numbers:

"8-1899607-4"

"KHKB-27142")

CH2401-000

(Alias Part Numbers:

"4-1899581-6"

"HSJC0-25072K")

CN9472-001

Product Affected

(Alias Part Numbers:

"222S14M12"

"1899508-2")

CH4958-001

(Alias Part Numbers:

"5-1899653-7"

"SC7065")

CH1794-000

(Alias Part Numbers:

"5-1899553-7"

"HSJC0-26906F")

CH1523-000

(Alias Part Numbers:

"KHKB-26836"

"7-1899541-2")

D40721-000

(Alias Part Numbers:

"5-1202079-6"

"HSJC0/4-0/23152K")

A45487-000

(Alias Part Numbers:

"6-1200625-7"

"HBJC4/8-2/21221G")

644519-000

(Alias Part Numbers:

"2-1195091-1"

"D38999/26WD97SB")

CN0480-000

(Alias Part Numbers:

"9-1899457-3"

"KHKB-26464")

CL8122-001

(Alias Part Numbers:

"5-1899369-4"

"440HJ030N1303")

E02467-000

(Alias Part Numbers:

"2-1201512-6"

"KHKB-20719")

CJ5554-001

Product Affected

(Alias Part Numbers:

"557T240NC132"

"2-1899292-8")

D36931-001

(Alias Part Numbers:

"795-305910"

"8-1899091-7")

CH4387-000

(Alias Part Numbers:

"1-1899638-2"

"KHKB-25424")

CH6173-000

(Alias Part Numbers:

"4-1899677-3"

"KHKB-18867")

CH1161-000

(Alias Part Numbers:

"KHKB-26647"

"1899527-2")

872111-001

(Alias Part Numbers:

"8-1196786-7"

"TV06RW-11-01-SN-L/C")

CN7482-000

(Alias Part Numbers:

"KHKB-26582"

"6-1899496-9")

E58569-000

(Alias Part Numbers:

"8-1202091-8"

"HSJC0/1-0/22822K")

CH0924-000

(Alias Part Numbers:

"1899522-1"

"HSJC0-26780K")

CH3444-000

(Alias Part Numbers:

"1-1899612-5"

"180-060XM06-17-08SN")

CH3328-000

Product Affected

(Alias Part Numbers:

"1-1899610-2"

"KHKB-27243")

D99255-000

(Alias Part Numbers:

"7-1202115-1"

"400Z860")

CH3137-000

(Alias Part Numbers:

"7-1899605-8"

"HSJC0-27218F")

CJ1015-001

(Alias Part Numbers:

"PAN6433-2F-18-35PB"

"1899251-7")

CH7222-000

(Alias Part Numbers:

"KHKB-25947")

EB1208-000

(Alias Part Numbers:

"D38999/26#B01SN-ZNCO")

E24742-000

(Alias Part Numbers:

"1-1201018-1"

"HSJC0/2-0/21058K")

679131-000

(Alias Part Numbers:

"6-1195338-8"

"HSJC0/10-0/12674K")

C15270-000

(Alias Part Numbers:

"3-1201813-5"

"HSJC0/6-6/22247K")

837685-000

(Alias Part Numbers:

"1-1196538-1"

"HBJC3/6-0/14542K")

765195-000

(Alias Part Numbers:

"1195957-7"

Product Affected
"D38999/26WE35PE")
CH2152-000
(Alias Part Numbers:
"1899569-9"
"KHKB-26193")
CH3302-000
(Alias Part Numbers:
"8-1899609-1"
"HSJC0-27250K")
CM9890-000
(Alias Part Numbers:
"62GB-56TG16-26PB"
"7-1899452-4")
921305-000
(Alias Part Numbers:
"4-1197148-0"
"D38999/20WJ46AN")
CL0385-000
(Alias Part Numbers:
"HSJC0/173-24/17331K"
"3-1899319-8")
CA5692-001
(Alias Part Numbers:
"457-5211")
CF0178-000
(Alias Part Numbers:
"7-1899152-1"
"HSJC0/8-0/21527K")
A45425-000
(Alias Part Numbers:
"1-1201233-0"
"KTFA-4468")
CH1825-000
(Alias Part Numbers:
"6-1899554-4"
"KHKB-VVR-MHSTK")
CH2229-000
(Alias Part Numbers:
"7-1899573-5"
"KHKB-27095")

Product Affected

CJ8399-000

(Alias Part Numbers:

"HBJC2-25771F"

"8-1899307-7")

CV4112-000

(Alias Part Numbers:

"KHKB-27847")

CM1237-001

(Alias Part Numbers:

"10-552944-99"

"1899389-9")

E73375-000

(Alias Part Numbers:

"HSJC0/8-0/24242K"

"2-1899069-2")

CV0297-000

(Alias Part Numbers:

"9-1899710-2"

"HSJC0-27603K")

CH2799-000

(Alias Part Numbers:

"1-1899593-4"

"KHKB-EPD101624A(HHB)")

CH5190-000

(Alias Part Numbers:

"1-1899660-8"

"KHKB-27376")

CG6749-000

(Alias Part Numbers:

"HSJC0-25526K"

"4-1899268-3")

CV3045-001

(Alias Part Numbers:

"ST1215")

CH1724-000

(Alias Part Numbers:

"1-1899551-0"

"KHKB-26895")

CN9247-001

(Alias Part Numbers:

Product Affected

"L24321201000"

"3-1899506-0")

CL9708-001

(Alias Part Numbers:

"TV07RW-23-35SN(W52)"

"8-1899377-5")

CM5196-001

(Alias Part Numbers:

"8D7-25Z19SA"

"5-1899420-2")

CV0345-000

(Alias Part Numbers:

"8-1899711-2"

"KHKB-27582")

D85137-000

(Alias Part Numbers:

"7-1201438-6"

"HSJC0/1-1/22220K")

CM1594-001

(Alias Part Numbers:

"10-40811-04"

"6-1899391-4")

CH2907-000

(Alias Part Numbers:

"6-1899598-8"

"KHKB-EPD107584A(HHB)")

175099-000

(Alias Part Numbers:

"2-1191273-9"

"HSJC0/6-0/16719K")

CH2042-001

(Alias Part Numbers:

"7-1899564-2"

"608-36T20-41PN")

CH1914-000

(Alias Part Numbers:

"3-1899559-0"

"HSJC0-26963F")

CH1579-000

(Alias Part Numbers:

Product Affected

"9-1899543-9"

"HSJC0-26864K")

CH9801-000

(Alias Part Numbers:

"5-1899697-9"

"HBJC3-26012K")

E96317-000

(Alias Part Numbers:

"HBJC4/12-3/24163K"

"2-1899066-6")

CH3326-000

(Alias Part Numbers:

"1-1899610-0"

"KHKB-27241")

541435-001

(Alias Part Numbers:

"1-1194246-5"

"CECC75201002-CD35FCNA01G")

CH3446-001

(Alias Part Numbers:

"1-1899612-7"

"800-006-16M6-7SN")

CH7809-000

(Alias Part Numbers:

"8-1899685-0"

"KHKB-16717")

CF0184-000

(Alias Part Numbers:

"HSJC0/36-36/21532K"

"7-1899152-9")

248104-000

(Alias Part Numbers:

"1200909-8"

"HBJC3/32-24/19648K")

CH1168-000

(Alias Part Numbers:

"KHKB-26705"

"1899527-9")

EB1122-000

(Alias Part Numbers:

Product Affected

"D38999/20#B98PA-ZNCO")

E59217-000

(Alias Part Numbers:

"6-1202002-0"

"HBJC5/20-0/23853K")

CM9983-000

(Alias Part Numbers:

"SBMS3106E-14S-5PNM11"

"3-1899453-8")

E42037-000

(Alias Part Numbers:

"2-1200624-3"

"HBJC4/17-4/21016G")

CH4414-000

(Alias Part Numbers:

"3-1899638-9"

"KHKB-25446")

027414-000

(Alias Part Numbers:

"8-1199531-5"

"HSJC0/1-1/19569K")

2091406-1

CN8714-000

(Alias Part Numbers:

"KHKB-26597"

"8-1899503-2")

CH0816-000

(Alias Part Numbers:

"KHKB-26649"

"3-1899517-8")

CF3463-000

CL7690-000

(Alias Part Numbers:

"HBJC2-26067F"

"1899368-6")

CJ0970-001

(Alias Part Numbers:

"602GB00E18-32PB(416)"

"7-1899250-5")

CV1455-000

Product Affected

(Alias Part Numbers:

"1-1899756-8"

"HSJC0-25963K")

CV1017-001

(Alias Part Numbers:

"M81511-26EJ01S1")

CV0786-001

(Alias Part Numbers:

"1899731-8"

"62GBSS-56T14-12PN")

CG6748-000

(Alias Part Numbers:

"HSJC0-25525K"

"4-1899268-1")

CF0193-000

(Alias Part Numbers:

"HSJC0/18-9/24830K"

"8-1899152-8")

877358-000

(Alias Part Numbers:

"5-1198263-7"

"HSJC0/10-4/18871K")

C88931-000

(Alias Part Numbers:

"7-1201866-9"

"HSJC0/10-0/23613K")

CH1720-000

(Alias Part Numbers:

"1899551-6"

"HSJC0-26886K")

A88307-001

(Alias Part Numbers:

"7-1202107-4"

"8197029-4")

CG6659-000

(Alias Part Numbers:

"HSJC0-25436K"

"4-1899265-5")

CN7577-000

(Alias Part Numbers:

Product Affected

"KHKB-25709"

"9-1899496-9")

A28698-000

(Alias Part Numbers:

"4-1201283-4"

"GD400109-0110-04")

CM4773-001

(Alias Part Numbers:

"CECC75201002-CA98FCCA01G"

"8-1899416-2")

E11318-000

(Alias Part Numbers:

"HBJC5/18-9/24192K"

"9-1899066-2")

CL3933-001

(Alias Part Numbers:

"CR06178-1"

"6-1899341-0")

D53768-000

(Alias Part Numbers:

"1-1201727-5"

"HSJC0/16-6/23162K")

CJ3490-001

(Alias Part Numbers:

"HARNWARE-TRAIN"

"4-1899273-3")

246787-000

(Alias Part Numbers:

"3-1191810-4"

"62GB-523-22-55P")

CN9263-001

(Alias Part Numbers:

"8HEB-7E-SP0022C"

"4-1899506-1")

E10765-000

(Alias Part Numbers:

"1-1201565-2"

"D38999/24WD5PN")

CV1979-000

(Alias Part Numbers:

Product Affected
"KHKB-22274")
C66757-001
(Alias Part Numbers:
"9-1201705-5"
"99-1430-820-04")
F31596-000
(Alias Part Numbers:
"HBJC3/8-4/24198K"
"8-1899066-4")
729441-000
(Alias Part Numbers:
"1195699-4"
"HSJC0/1-0/18228K")
316453-000
(Alias Part Numbers:
"2-1192398-0"
"HSJC0/17-9/16674K")
CF0156-000
(Alias Part Numbers:
"HSJC0/2-0/21509K"
"4-1899152-9")
CF2895-000
(Alias Part Numbers:
"GD400265-0380-05R"
"5-1899207-1")
CN3577-001
(Alias Part Numbers:
"BACC63BV14B7S6"
"7-1899475-1")
CH2559-000
(Alias Part Numbers:
"5-1899585-9"
"KHKB-26394")
CG6769-000
(Alias Part Numbers:
"HSJC0-25546K"
"8-1899268-5")
C16841-000
(Alias Part Numbers:
"5-1200582-8"

Product Affected
"D38999/20WG41SN")
D22397-000
(Alias Part Numbers:
"1200625-9"
"HSJC0/4-0/21220G")
CH4455-001
(Alias Part Numbers:
"4-1899639-9"
"DC-24660-33-OBS")
CH9805-000
(Alias Part Numbers:
"6-1899697-3"
"KHKB-26010")
427497-001
(Alias Part Numbers:
"5-1193216-9"
"M24308/2-3")
CV1012-000
(Alias Part Numbers:
"2-1899740-9"
"HSJC0/56-2/15852K")
CH2358-000
(Alias Part Numbers:
"6-1899579-1"
"HSJC0-27118F")
CH1771-000
(Alias Part Numbers:
"7-1899552-4"
"KHKB-26902")
1478388-1
(Alias Part Numbers:
"CV3778-000"
"AMP-0-1478388-1")
CJ3503-001
(Alias Part Numbers:
"HARNWARE-DATABUS-TRAIN"
"5-1899273-2")
D05693-000
(Alias Part Numbers:
"4-1200085-8"

Product Affected

"HSJC0/5-2/20026F")

E49108-000

(Alias Part Numbers:

"1201726-7"

"602GB06E12-3PN(416)")

F86910-000

(Alias Part Numbers:

"HSJC0/8-0/24241K"

"2-1899069-1")

CH2310-001

(Alias Part Numbers:

"9-1899576-9"

"DW-AD-623-M5-725")

CL1374-001

(Alias Part Numbers:

"8-1899326-7"

"TVP02RW-17-06SN(W52)(W404)")

CV1963-000

(Alias Part Numbers:

"KHKB-27378R19104")

C19920-001

(Alias Part Numbers:

"M39029/64-369")

CV1464-000

(Alias Part Numbers:

"KHKB-25971")

CM5681-000

(Alias Part Numbers:

"FV-700805"

"4-1899422-6")

CH4426-000

(Alias Part Numbers:

"8-1899638-8"

"KHKB-25473")

CH2479-000

(Alias Part Numbers:

"8-1899582-8"

"KHKB-27110")

5-161107-4

CF0123-000

Product Affected

(Alias Part Numbers:
"HSJC0/59-59/21471K"
"1899152-1")

CV1953-000

(Alias Part Numbers:
"KHKB-27382R91773")

CV3567-000

(Alias Part Numbers:
"KHKB-1991210-1")

CH3433-000

(Alias Part Numbers:
"9-1899611-8"
"HSJC0-27163K")

799391-001

(Alias Part Numbers:
"4-1196180-6"
"M81969/14-01")

809277-000

(Alias Part Numbers:
"3-1196289-9"
"D38999/26WD19PA")

F81932-000

(Alias Part Numbers:
"6-1201229-4"
"GD400256-0164-23")

CF0719-000

(Alias Part Numbers:
"HSJC0/5-0/25036K"
"3-1899180-5")

CV0343-000

(Alias Part Numbers:
"8-1899711-0"
"KHKB-27580")

D85933-000

(Alias Part Numbers:
"9-1201831-2"
"HSJC0/4-0/23022K")

CM4823-001

(Alias Part Numbers:
"62GB-523-08-02S")

Product Affected

"1-1899417-7")

A55888-000

(Alias Part Numbers:

"4-1202045-6"

"HSJC0/19-4/23943F")

CJ3501-001

(Alias Part Numbers:

"HARNWARE-ADMIN-TRAIN"

"5-1899273-1")

CL0375-000

(Alias Part Numbers:

"FGG-0B-560ZZC"

"3-1899319-2")

888209-000

(Alias Part Numbers:

"1196910-7"

"D38999/26WJ61PN")

530677-001

(Alias Part Numbers:

"1194168-9"

"CECC75201002-CA35MCNA01G")

CV0338-000

(Alias Part Numbers:

"7-1899711-5"

"KHKB-27575")

A24443-000

(Alias Part Numbers:

"5-1201437-5"

"HSJC0/6-0/22264K")

CV0443-001

(Alias Part Numbers:

"1-1899717-6"

"DEMM15F225")

CV0939-000

(Alias Part Numbers:

"7-1899735-2"

"KHKB-26415")

759585-000

(Alias Part Numbers:

"62GB-56TG16-26PN"

Product Affected
"7-1195917-3")
C11395-000
(Alias Part Numbers:
"7-1201421-9"
"GD400005-0130-00")
CM3375-001
(Alias Part Numbers:
"508-1-31720-220"
"1-1899407-6")
CL3949-001
(Alias Part Numbers:
"CR07188-2"
"7-1899341-7")
CH1583-000
(Alias Part Numbers:
"1899544-4"
"KHKB-26859")
CV3199-000
(Alias Part Numbers:
"KHKB-16693")
C69109-000
(Alias Part Numbers:
"3-1202091-5"
"HBJC5/24-0/22294K")
CN6728-000
(Alias Part Numbers:
"HSJC0-26593K"
"1899493-3")
CA4949-000
(Alias Part Numbers:
"HSJC0-24762F"
"3-1899116-1")
CG6687-000
(Alias Part Numbers:
"HSJC0-25464K"
"8-1899265-2")
402591-000
(Alias Part Numbers:
"2-1193039-4"
"D38999/20WD05SB")

Product Affected
E60973-000
(Alias Part Numbers:
"HBJC5/23-0/24159K"
"9-1899066-5")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the

TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.