



01-Mar-2016

PCN #:E-16-002055

Subject:PN 1355219 AMP MCP 2.8 SOCKET HSG., 21POS., PN 1355222 AMP MCP 2.8 SOCKET HSG., 21POS., SEALED WITH SECONDARY LOCKING DE

Description of Change: Minor change on Receptacle Housing. Adding to pockets in Rec. Housing, cavity block area to create more space for the counter part (cavity block) to avoid appearance of plastic chips in production. This change is considered by TE Connectivity as a manufacturing improvement; Location of change, on sales part not visible, part change of Housing to improve the fit of Cavity Block on Receptacle Housing. No Form, Fit or Function change on Sales part!

Reason: Product Improvement. Request by manufacturing due to appearance of plastic chips in production.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-May-2016

Implementation Date:31-May-2016

Product Affected

1-1355222-9

1-1534127-1

2-1355222-9

4-1534127-1

2-1534127-1

3-1355222-9

1-1355222-8

3-1534127-1

4-1355222-9

Product Affected

2-1355222-1

3-1355222-1

1-2208686-1

1-1355222-1

4-1355222-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.