



14-Mar-2016

PCN #:P-16-012732

Subject:Deutsch DRB Connector Series

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from TEC Hemet, CA manufacturing location to TEC Empalme, Mexico manufacturing location.

Reason: Dear Customer, we hereby inform you about a transfer of tools and processes. Mold Tooling will be transferred from Hemet, CA to Empalme, MX location. The parts will be manufactured by excellent existing equipment and assembly lines at Empalme, MX. The transfer follows a strict TEC procedure, which fully maintains quality, ability to supply and form, fit, and function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements and has been successfully manufacturing 4 million of parts per month for TE for over 3 years. Boxes will be clearly marked with the country of manufacture. We hereby reserve the right to swing the tools back to the current location in Hemet California if business needs shall require this. An internal release based on our specifications will be executed before any parts are delivered. Level 3 PPAP packages by product family will be offered upon customer request.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:01-Jul-2016

Implementation Date:01-Jul-2016

Product Affected

DRB16-60SAE-L018

(Alias Part Numbers:

"ZPF000000000131376"

"5-1899813-7")

Product Affected

DRBF-1B

DRB12-60PBE-L018

(Alias Part Numbers:
"ZPF000000000131374")

DRB12-128PBE-L018

DRB16-128SBE-L018

(Alias Part Numbers:
"4-1899816-0")

DRB12-128PDNE-L018

DRB16-128SCE-L018

DRB12-128PBNE-L018

DRB16-60SBE-L018

(Alias Part Numbers:
"ZPF000000000131377")

DRB12-48PBE-L018

(Alias Part Numbers:
"DRB12-48PBE-L018-LD"
"DRB12-48PBE-L018-LS"
"DRB12-48PBE-L018-L"
"7-1899817-0")

DRB12-60PANE

DRB12-102PBE-L018

DRB12-128PDE-L018

DRB12-128PAE-L018

(Alias Part Numbers:
"ZPF000000000145699"
"8-1899817-6")

DRBF-2A

(Alias Part Numbers:
"ZPF000000000131751"
"DRBF-2A-AS")

DRB12-128PCE-L018

DRB12-60PDE-L018

YDRBM-3A0000000000

(Alias Part Numbers:
"DRBM-3A")

DRBF-1A

(Alias Part Numbers:
"ZPF000000000131750"
"DRBF-1A-LD")

Product Affected

"DRBF-1A-LS"

"DRBF-1A-MS"

"DRBF-1A-L"

"DRBF-1A-M")

DRBF-3AB

(Alias Part Numbers:

"ZPF000000000131755")

DRB16-102SBE-L018

DRB12-48PCE-L018

DRB12-102PAE-L018

(Alias Part Numbers:

"ZPF000000000138178"

"DRB12-102PAE-L018-MS"

"DRB12-102PAE-L018-M"

"8-1899793-9")

DRB12-48PAE-L018

(Alias Part Numbers:

"ZPF000000000140760"

"DRB12-48PAE-L018-AS"

"DRB12-48PAE-L018-LD"

"DRB12-48PAE-L018-LS"

"DRB12-48PAE-L018-L"

"8-1899793-8")

DRB12-60PAE-L018

(Alias Part Numbers:

"ZPF000000000131373"

"6-1899818-7")

DRB16-128SDE-L018

DRB12-128PCNE-L018

DRBF-2B

(Alias Part Numbers:

"ZPF000000000131752")

DRB12-102PANE

(Alias Part Numbers:

"DRB12-102PANE-LS"

"DRB12-102PANE-L")

DRB12-128PANE-L018

(Alias Part Numbers:

"ZPF000000000146197"

"9-1899776-3")

Product Affected

DRB16-48SBE-L018

(Alias Part Numbers:

"DRB16-48SBE-L018-LD"

"DRB16-48SBE-L018-LS"

"1899763-5"

"DRB16-48SBE-L018-L")

DRB16-102SAE-L018

(Alias Part Numbers:

"ZPF000000000138177"

"DRB16-102SAE-L018-LD"

"DRB16-102SAE-L018-LS"

"DRB16-102SAE-L018-MS"

"3-1899772-4"

"DRB16-102SAE-L018-E"

"DRB16-102SAE-L018-L"

"DRB16-102SAE-L018-M")

DRB16-128SAE-L018

(Alias Part Numbers:

"ZPF000000000145698"

"DRB16-128SAE-L018-LS"

"8-1899773-9"

"DRB16-128SAE-L018-L")

DRB16-48SAE-L018

(Alias Part Numbers:

"ZPF000000000140759"

"DRB16-48SAE-L018-AS"

"DRB16-48SAE-L018-LD"

"DRB16-48SAE-L018-LS"

"3-1899779-0"

"DRB16-48SAE-L018-L")

DRBM-2A

(Alias Part Numbers:

"ZPF000000000131756")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.