



# TE Connectivity

**Product Change Notification:** P-16-012579

**PCN Date:** 02-FEB-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY Delay of Migration: Southwest DC to New El Paso DC

**Description of Changes**  
UPDATE TO PCN P-16-012527. To ensure a smooth and stable transition from SWDC to EPDC, TE will be delaying the transition from the current Santa Teresa, NM DC (SWDC) to the new El Paso, TX DC (EPDC), originally scheduled to implement February 8th - 15th, is now scheduled to implement April 11th - 15th. This delay will allow extended testing on all SAP systems and procedures to ensure a seamless transition into the new warehouse. As we migrate the product and go-live on the new SAP WM software, it is critical to ensure this testing and training is fully incorporated into the systems and operational processes in the new El Paso warehouse. Based on the revised timing of transition, both Customer Shipments and Supplier Deliveries will continue to process from the Santa Teresa, NM location: Address: 101 Lindbergh, Santa Teresa, NM 88008, DUNS Code: 036967748. See attached Customer Letter.

**Other attachments:**  
[Customer Letter](#)

**Reason for Changes:**  
Customer Request. The team arrived at this decision to delay the migration with a focus on our customers and to provide a seamless transition to the new warehouse in El Paso. Per PCN P-16-012527, as of the end of August 2015, our current distribution center located in Santa Teresa, New Mexico was divested to Commscope. As a result, TE has established a new Distribution Center in El Paso, TX to support our South-West Customers. In conjunction with the relocation, our new El Paso Distribution Center will be operating on SAP Warehouse Management. The transition will be transparent with the exception of the SAP Packing List. Currently with the use of MOVE in our Santa Teresa DC, Packing Lists can only be printed by carton or by pallet. With the use of SAP Warehouse Management in our El Paso DC, the Packing Lists will be printed by shipment and/or by pallet.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	11-APR-2016
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-104450-0</a>	NO					
<a href="#">1-104479-0</a>	NO					
<a href="#">1-104479-3</a>	NO					
<a href="#">1-104480-7</a>	NO					
<a href="#">1-1123722-5</a>	NO					
<a href="#">1-1123723-2</a>	NO					
<a href="#">1-1123723-3</a>	NO					
<a href="#">1-1414602-0</a>	NO					
<a href="#">1-160759-1</a>	NO					
<a href="#">1-160759-2</a>	NO					
<a href="#">1-170823-3</a>	NO					
<a href="#">1-172128-1</a>	NO					

<a href="#">1-172131-1</a>	NO				
<a href="#">1-172132-1</a>	NO				
<a href="#">1-172134-1</a>	NO				
<a href="#">1-176497-1</a>	NO				
<a href="#">1-324227-0</a>	NO				
<a href="#">1-332006-2</a>	NO				
<a href="#">1-33220-2</a>	NO				
<a href="#">1-35115-0</a>	NO				
<a href="#">1-413889-3</a>	NO				
<a href="#">1-413889-4</a>	NO				
<a href="#">1-480270-0</a>	NO		"1-0480270-0"		
<a href="#">1-480271-0</a>	NO				
<a href="#">1-480283-0</a>	NO				
<a href="#">1-480284-0</a>	NO				
<a href="#">1-480318-0</a>	NO		"A77825-000", "AMP-1-0480318-0"		
<a href="#">1-480319-0</a>	NO				
<a href="#">1-480319-9</a>	NO				
<a href="#">1-480350-0</a>	NO				
<a href="#">1-480358-0</a>	NO				
<a href="#">1-480387-0</a>	NO				
<a href="#">1-480388-0</a>	NO				
<a href="#">1-480416-0</a>	NO				
<a href="#">1-480416-1</a>	NO				
<a href="#">1-480698-0</a>	NO		"834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341"		
<a href="#">1-480699-0</a>	NO		"402376412", "1-0480699-0", "500-060-1982", "4- 27202-1755"		
<a href="#">1-480700-0</a>	NO		"AMPS-1-0480700-0", "F47049-000", "1-0480700-0", "2-42932-9342"		
<a href="#">1-480701-0</a>	NO				
<a href="#">1-480705-0</a>	NO		"1-0480705-0"		
<a href="#">1-480706-0</a>	NO		"873818-000", "AMPS-1-0480706-0", "2-42934-0301"		
<a href="#">1-552699-0</a>	NO				
<a href="#">1-626065-2</a>	NO				
<a href="#">1-66101-9</a>	NO		"C35858-000", "AMPS-1-0066101-9"		
<a href="#">1-66105-8</a>	NO				
<a href="#">1-770904-0</a>	NO				
<a href="#">1-770968-1</a>	NO				
<a href="#">1-794606-2</a>	NO				
<a href="#">1-794608-0</a>	NO				
<a href="#">1-794615-8</a>	NO				
<a href="#">1-794617-2</a>	NO				
<a href="#">1-794617-6</a>	NO				
<a href="#">103653-1</a>	NO		"010-0961-00"		
<a href="#">103653-2</a>	NO		"010-0962-00"		
<a href="#">103653-4</a>	NO				
<a href="#">104257-1</a>	NO				
<a href="#">104257-2</a>	NO		"AMP-0-0104257-2", "C75259-000", "030-0095-00"		
<a href="#">104257-3</a>	NO				
<a href="#">104257-5</a>	NO		"030-0096-00"		
<a href="#">104479-2</a>	NO				
<a href="#">104479-8</a>	NO				
<a href="#">104479-9</a>	NO				
<a href="#">104480-2</a>	NO				
<a href="#">104505-8</a>	NO				

<a href="#">104920-4</a>	NO				
<a href="#">104922-4</a>	NO				
<a href="#">106455-3</a>	NO				
<a href="#">106455-4</a>	NO				
<a href="#">1123721-2</a>	NO				
<a href="#">1217031-1</a>	NO				
<a href="#">1217082-1</a>	NO				
<a href="#">1217088-1</a>	NO				
<a href="#">1217089-1</a>	NO				
<a href="#">1217097-2</a>	NO				
<a href="#">1217138-1</a>	NO				
<a href="#">1217160-1</a>	NO				
<a href="#">1217175-1</a>	NO				
<a href="#">1217183-1</a>	NO				
<a href="#">1217243-1</a>	NO				
<a href="#">1217421-1</a>	NO				
<a href="#">1217497-1</a>	NO				
<a href="#">1217497-2</a>	NO				
<a href="#">1217595-1</a>	NO				
<a href="#">1217886-1</a>	NO				
<a href="#">1217887-1</a>	NO				
<a href="#">130232</a>	NO				
<a href="#">1318306-1</a>	NO				
<a href="#">1375819-3</a>	NO				
<a href="#">1393110-7</a>	NO		<b>KU-17D45-110</b>		
<a href="#">1393303-9</a>	NO		"V23134-B0053-C642", "V23134B 53C642"		
<a href="#">1393768-2</a>	NO		<b>R10-E5841-3</b>		
<a href="#">140526</a>	NO				
<a href="#">140731-2</a>	NO				
<a href="#">142685-3</a>	NO				
<a href="#">1437597-7</a>	NO		<b>2SKF132AEL01</b>		
<a href="#">1445049-4</a>	NO				
<a href="#">1445389-3</a>	NO				
<a href="#">147250-3</a>	NO				
<a href="#">150656-1</a>	NO				
<a href="#">154717-3</a>	NO				
<a href="#">154717-6</a>	NO				
<a href="#">154717-7</a>	NO				
<a href="#">154718-3</a>	NO				
<a href="#">154718-6</a>	NO				
<a href="#">154719</a>	NO		"154719-0"		
<a href="#">154719-1</a>	NO		"0-0154719-1"		
<a href="#">154719-2</a>	NO				
<a href="#">156503-2</a>	NO				
<a href="#">1586406013</a>	NO		2-1191146-1, <b>HTAT-8/2-0-50MM</b>		
<a href="#">1599298-5</a>	NO				
<a href="#">1601016-2</a>	NO		"131-036-002"		
<a href="#">1601018-2</a>	NO		"131-044-014"		
<a href="#">1601021-2</a>	NO		"131-047-014"		
<a href="#">1601037-2</a>	NO		"131-083-010"		
<a href="#">1601046-1</a>	NO		"131-101-000"		
<a href="#">1601051-2</a>	NO		"131-113-014"		
<a href="#">1601063-2</a>	NO		"131-129-021"		
<a href="#">1601075-2</a>	NO		"131-145-014"		

<a href="#">1601095-2</a>	NO	"131-165-014"			
<a href="#">1601104-2</a>	NO	"131-175-021"			
<a href="#">1601117-1</a>	NO	"150-003-000"			
<a href="#">1601137-2</a>	NO	"151-003-014"			
<a href="#">1601140-1</a>	NO	"153-001-000"			
<a href="#">1601144-3</a>	NO	"159-003-120"			
<a href="#">1601172-2</a>	NO				
<a href="#">1601194-2</a>	NO				
<a href="#">1601215-2</a>	NO				
<a href="#">1601261-2</a>	NO				
<a href="#">1601484-1</a>	NO				
<a href="#">1601517-1</a>	NO	"G061D16BX"			
<a href="#">1601555-1</a>	NO	"L032B12B"			
<a href="#">1601623-1</a>	NO	"L061D16TB"			
<a href="#">1601698-1</a>	NO	"L125/076C18BSP"			
<a href="#">160173-2</a>	NO				
<a href="#">160457-3</a>	NO				
<a href="#">160467-2</a>	NO				
<a href="#">160684-4</a>	NO				
<a href="#">160759-2</a>	NO				
<a href="#">160759-3</a>	NO	"0-0160759-3"			
<a href="#">160789-2</a>	NO				
<a href="#">160859-2</a>	NO				
<a href="#">160859-5</a>	NO				
<a href="#">160860-2</a>	NO				
<a href="#">160887-4</a>	NO				
<a href="#">160915-2</a>	NO				
<a href="#">160927-4</a>	NO				
<a href="#">160928-4</a>	NO				
<a href="#">163300-6</a>	NO				
<a href="#">163301-6</a>	NO				
<a href="#">163306-2</a>	NO				
<a href="#">170002-5</a>	NO				
<a href="#">170003-4</a>	NO				
<a href="#">170003-5</a>	NO	"0-0170003-5"			
<a href="#">170030-1</a>	NO	"0-0170030-1"			
<a href="#">170360-3</a>	NO				
<a href="#">170362-3</a>	NO				
<a href="#">171637-1</a>	NO				
<a href="#">172159-1</a>	NO				
<a href="#">1734328-2</a>	NO				
<a href="#">1744144-1</a>	NO				
<a href="#">177898-1</a>	NO				
<a href="#">177914-1</a>	NO				
<a href="#">177915-1</a>	NO				
<a href="#">177916-1</a>	NO				
<a href="#">177918-1</a>	NO				
<a href="#">179463-1</a>	NO				
<a href="#">179593-1</a>	NO				
<a href="#">1813674006</a>	NO	7-1197934-1, <b>RNF-100-NR823-0-SP</b>			
<a href="#">1977808-1</a>	NO				
<a href="#">2-1393298-6</a>	NO	"V23136-E7-X70", "V23136E 7X 70"			
<a href="#">2-1393768-1</a>	NO	<b>R10-E6282-3</b>			
<a href="#">2-1393768-5</a>	NO	<b>R10-E6339-1</b>			

<a href="#">2-1601016-2</a>	NO	"131-048-002"			
<a href="#">2-1601018-2</a>	NO	"131-042-014"			
<a href="#">2-1601021-2</a>	NO	"131-046-014"			
<a href="#">2-1601042-2</a>	NO	"131-090-120"			
<a href="#">2-1601046-1</a>	NO	"131-102-000"			
<a href="#">2-1601051-2</a>	NO				
<a href="#">2-1601063-2</a>	NO	"131-130-021"			
<a href="#">2-1601075-2</a>	NO	"131-146-014"			
<a href="#">2-1601095-2</a>	NO	"131-166-014"			
<a href="#">2-1601104-2</a>	NO	"131-176-021"			
<a href="#">2-1601121-2</a>	NO	"150-024-014"			
<a href="#">2-1601140-1</a>	NO	"153-004-000"			
<a href="#">2-1601171-2</a>	NO				
<a href="#">2-1601203-2</a>	NO				
<a href="#">2-31819-1</a>	NO				
<a href="#">2-31894-2</a>	NO	"405223587"			
<a href="#">2-31895-1</a>	NO				
<a href="#">2-31897-2</a>	NO	"F55945-000", "RAYVOSS-22-16/22-18-R3/8"			
<a href="#">2-320563-2</a>	NO				
<a href="#">2-320568-1</a>	NO	"403802838"			
<a href="#">2-322994-1</a>	NO				
<a href="#">2-325034-1</a>	NO				
<a href="#">2-32952-1</a>	NO				
<a href="#">2-33457-2</a>	NO	"401771357"			
<a href="#">2-33458-3</a>	NO				
<a href="#">2-34112-2</a>	NO				
<a href="#">2-34113-2</a>	NO				
<a href="#">2-34118-2</a>	NO				
<a href="#">2-34123-1</a>	NO	"405109166"			
<a href="#">2-34140-1</a>	NO				
<a href="#">2-34144-1</a>	NO				
<a href="#">2-34161-1</a>	NO				
<a href="#">2-34162-1</a>	NO				
<a href="#">2-34163-1</a>	NO				
<a href="#">2-34164-2</a>	NO				
<a href="#">2-34837-4</a>	NO				
<a href="#">2-35109-1</a>	NO	"1140297", "1139542"			
<a href="#">2-35495-2</a>	NO				
<a href="#">2-36153-2</a>	NO				
<a href="#">2-36160-1</a>	NO				
<a href="#">2-36161-2</a>	NO	"402624795"			
<a href="#">2-604771-0</a>	NO				
<a href="#">2-66102-2</a>	NO				
<a href="#">2-794617-4</a>	NO				
<a href="#">201310-1</a>	NO				
<a href="#">201532-4</a>	NO				
<a href="#">201692-4</a>	NO				
<a href="#">202119-2</a>	NO				
<a href="#">2029154002</a>	NO	1-1191471-8, <b>RNF-150-1/2-0-SP</b>			
<a href="#">205720-2</a>	NO				
<a href="#">206036-2</a>	NO				
<a href="#">206037-1</a>	NO	"A33294-000", "AMPS-0-0206037-1"			
<a href="#">206037-2</a>	NO				
<a href="#">206070-8</a>	NO				

<a href="#">206150-1</a>	NO				
<a href="#">206151-2</a>	NO				
<a href="#">206322-9</a>	NO				
<a href="#">206705-4</a>	NO				
<a href="#">206708-1</a>	NO				
<a href="#">206966-9</a>	NO				
<a href="#">208652-1</a>	NO				
<a href="#">2118016-1</a>	NO				
<a href="#">2118016-2</a>	NO				
<a href="#">2132781-3</a>	NO				
<a href="#">2132813-2</a>	NO				
<a href="#">2176104-1</a>	NO		<b>R217120RJ</b>		
<a href="#">2176195-1</a>	NO		<b>R211820RJ</b>		
<a href="#">2201778-1</a>	NO				
<a href="#">2525596002</a>	NO		5-1191848-0, <b>RBK-ILS-125-NR1-0-50MM</b>		
<a href="#">2525596021</a>	NO		9-1199922-3, <b>RBK-ILS-125-NR1-0-30MM</b>		
<a href="#">269647-000</a>	NO		1-1191990-6, <b>ES-CAP-HW-NO.3-M8-0-45MM</b>		
<a href="#">3-1414997-0</a>	NO				
<a href="#">3-1611473-3</a>	NO		<b>4700R09K18K999</b>		
<a href="#">3-640252-1</a>	NO				
<a href="#">3-640311-1</a>	NO				
<a href="#">3-640401-1</a>	NO				
<a href="#">3-641190-5</a>	NO				
<a href="#">3-644511-5</a>	NO				
<a href="#">3-644694-6</a>	NO				
<a href="#">3-770060-1</a>	NO				
<a href="#">3-794121-1</a>	NO				
<a href="#">3-794122-1</a>	NO				
<a href="#">3-794636-8</a>	NO				
<a href="#">316086-1</a>	NO				
<a href="#">316088-1</a>	NO				
<a href="#">31818</a>	NO		"768360-000", "AMPS-0-0031818-0"		
<a href="#">31895</a>	NO		"C58079-000", "AMPS-0-0031895-0"		
<a href="#">320619</a>	NO		"AMPS-0-0320619-0", "C41604-000", "4-00520-1990"		
<a href="#">320677</a>	NO				
<a href="#">320764</a>	NO				
<a href="#">321201</a>	NO				
<a href="#">321253</a>	NO				
<a href="#">321576</a>	NO				
<a href="#">321867-1</a>	NO				
<a href="#">322870-1</a>	NO				
<a href="#">324047</a>	NO		"A42815-000", "AMP-0-0324047-0"		
<a href="#">324523</a>	NO				
<a href="#">32463</a>	NO				
<a href="#">3257456002</a>	NO		8-1192464-9, <b>RBK-VWS-125-NR2-X-50MM</b>		
<a href="#">330367</a>	NO				
<a href="#">330368</a>	NO				
<a href="#">330369</a>	NO		"CR5073-000", "AMPS-0-00330369-0"		
<a href="#">33220</a>	NO				
<a href="#">33460</a>	NO		"CS4742-000", "AMPS-0-0033460-0"		
<a href="#">33465</a>	NO		"AMP-0-0033465-0", "F07864-000"		
<a href="#">3371890001</a>	NO		7-1192545-8, <b>ES-CAP-NO.1-C1-0-30MM</b>		
<a href="#">3371890002</a>	NO		8-1192545-4, <b>ES-CAP-NO.1-C1-0-30MM</b>		
<a href="#">34070</a>	NO		"268412-000", "AMPS-0-0034070-0"		

<a href="#">34072</a>	NO	"611528-000", "AMPS-0-0034072-0"			
<a href="#">34125</a>	NO	"AMP-0-0034125-0", "F03616-000"			
<a href="#">34130</a>	NO				
<a href="#">34137</a>	NO	"F21569-000", "AMPS-0-0034137-0"			
<a href="#">34138</a>	NO	"CM8395-000", "AMP-0-0034138-0"			
<a href="#">34318</a>	NO	"AMPS-0-0034318-0", "C05587-000"			
<a href="#">3463012004</a>	NO	7-1192606-8, <b>HTAT-24/6-0-STK</b>			
<a href="#">3463016015</a>	NO	8-1192606-9, <b>HTAT-24/6-0-45MM</b>			
<a href="#">3463016047</a>	NO	3-1899154-8, <b>HTAT-24/6-0-90MM</b>			
<a href="#">34846</a>	NO				
<a href="#">350210-1</a>	NO	"407072693"			
<a href="#">350218-1</a>	NO				
<a href="#">350390-2</a>	NO				
<a href="#">350536-1</a>	NO	"403429822"			
<a href="#">350537-3</a>	NO				
<a href="#">350558-1</a>	NO				
<a href="#">350561-1</a>	NO	"0-0350561-1", "CU3085-000", "AMPS-0-0350561-1"			
<a href="#">350570-1</a>	NO				
<a href="#">350767-1</a>	NO	"AMP-0-0350767-1", "F84278-000"			
<a href="#">350778-1</a>	NO	"403738545", "AMPS-0-0350778-1", "E83488-000", "500-020-2698", "500-020-0104"			
<a href="#">350851-1</a>	NO	"0-0350851-1", "2021755", "CU3086-000", "AMPS-0-0350851-1"			
<a href="#">350923-3</a>	NO	"403980899"			
<a href="#">35109</a>	NO	"AMPS-0-0035109-0", "F67095-000"			
<a href="#">35110</a>	NO	"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
<a href="#">35669</a>	NO				
<a href="#">35776</a>	NO				
<a href="#">36946</a>	NO	"CN3419-000", "AMPS-0-0036946-0"			
<a href="#">36951</a>	NO				
<a href="#">36958</a>	NO				
<a href="#">4-1415009-6</a>	NO	"V23136-L0031-X088"			
<a href="#">4-1419148-9</a>	NO	<b>T9AV1D22-22</b>			
<a href="#">4-146461-0</a>	NO				
<a href="#">4-1601110-2</a>	NO				
<a href="#">4-794630-0</a>	NO				
<a href="#">4-794636-2</a>	NO				
<a href="#">4-794636-6</a>	NO				
<a href="#">41765</a>	NO				
<a href="#">41766</a>	NO				
<a href="#">41770</a>	NO				
<a href="#">41904</a>	NO				
<a href="#">42776-1</a>	NO				
<a href="#">4367790003</a>	NO	1-1193283-5, <b>ES-CAP-NO.2-B9-0-35MM</b>			
<a href="#">493176-1</a>	NO				
<a href="#">5-104809-3</a>	NO				
<a href="#">5-1393208-6</a>	NO	<b>T90H5D12-12</b>			
<a href="#">5-1393302-8</a>	NO	"V23134A1052C643"			
<a href="#">5-147324-1</a>	NO				
<a href="#">5-867052-1</a>	NO				
<a href="#">505044-1</a>	NO				
<a href="#">505079-1</a>	NO				
<a href="#">505081-1</a>	NO				
<a href="#">5052844025</a>	NO	4-1193821-8, <b>RNF-100-3/64-0-SP</b>			
<a href="#">5052846079</a>	NO	8-1193821-6, <b>RNF-100-3/64-0-40MM</b>			

<a href="#">5053094268</a>	NO	4-1193845-5, <b>RNF-100-1/4-BK-SP</b>			
<a href="#">5053194052</a>	NO	2-1193862-7, <b>RNF-100-1/2-0-SP</b>			
<a href="#">5053194267</a>	NO	3-1193862-4,, <b>RNF-100-1/2-0, RNF-100-1/2-BK-SP</b>			
<a href="#">5053344102</a>	NO	4-1193882-5, <b>RNF-100-1-1/2-BK-SP</b>			
<a href="#">5058724002</a>	NO	5-1193906-0, <b>VERSAFIT-3/16-0-SP</b>			
<a href="#">5058744001</a>	NO	1193907-8, <b>VERSAFIT-1/4-0-SP</b>			
<a href="#">5068106020</a>	NO	2-1193937-9, <b>CGPT-19/9.5-2-50MM</b>			
<a href="#">5068106029</a>	NO	3-1193937-3, <b>CGPT-19/9.5-2-30MM</b>			
<a href="#">5069794007</a>	NO	4-1193947-1, <b>CGPT-1.2/0.6-0-SP</b>			
<a href="#">5069826024</a>	NO	1193949-5, <b>CGPT-3.2/1.6-0-25MM</b>			
<a href="#">5070064069</a>	NO	2-1193963-6, <b>RNF-100-1/4-CL-SP</b>			
<a href="#">508471-000</a>	NO	4-1193997-8, <b>RBK-85-KIT-0405-A0</b>			
<a href="#">51863</a>	NO	"4-16211-9784"			
<a href="#">51863-1</a>	NO				
<a href="#">51864-3</a>	NO				
<a href="#">51986-1</a>	NO				
<a href="#">52041</a>	NO				
<a href="#">52943-1</a>	NO	"401771464"			
<a href="#">53128-1</a>	NO				
<a href="#">53408-2</a>	NO				
<a href="#">53418-2</a>	NO				
<a href="#">53831-1</a>	NO				
<a href="#">5428154001</a>	NO	4-1194256-8, <b>LSTT-19-0-SP</b>			
<a href="#">5428156129</a>	NO	7-1194257-5, <b>LSTT-19-0-45MM</b>			
<a href="#">5433694001</a>	NO	9-1194261-9, <b>CGPT-24/8-0-SP</b>			
<a href="#">5510320002</a>	NO	3-1194355-8, <b>PD-CAP-1/8-0</b>			
<a href="#">55785-1</a>	NO	"AMP-0-0055785-1", "D10979-000"			
<a href="#">5628374001</a>	NO	9-1194446-7, <b>LSTT-32-0-SP</b>			
<a href="#">5677554004</a>	NO	2-1194493-3, <b>RNF-3000-1.5/0.5-0-SP</b>			
<a href="#">5677556037</a>	NO	4-1194493-8, <b>RNF-3000-1.5/0.5-0-10MM</b>			
<a href="#">581913P002</a>	NO	9-1194609-1, <b>QS1500-NO.2-F6-0-50MM</b>			
<a href="#">581913P003</a>	NO	9-1194609-2, <b>QS1500-NO.2-F6-0-65MM</b>			
<a href="#">6-1393298-0</a>	NO	VF4A-15F11, <b>VF4-15F11</b>			
<a href="#">6-1414921-8</a>	NO				
<a href="#">6-1414926-2</a>	NO				
<a href="#">60319-2</a>	NO				
<a href="#">60620-1</a>	NO	"110000"			
<a href="#">61085-1</a>	NO				
<a href="#">61117-1</a>	NO	"403631302"			
<a href="#">61118-1</a>	NO	"0-0061118-1"			
<a href="#">61314-1</a>	NO	"403334121", "0-0061314-1", "14629", "1101201"			
<a href="#">61366-1</a>	NO				
<a href="#">61622-1</a>	NO				
<a href="#">62000-2</a>	NO				
<a href="#">62001-1</a>	NO				
<a href="#">62001-2</a>	NO				
<a href="#">62002-2</a>	NO				
<a href="#">62194-2</a>	NO				
<a href="#">62305-2</a>	NO				
<a href="#">62306-2</a>	NO				
<a href="#">62309-2</a>	NO				
<a href="#">62310-2</a>	NO				
<a href="#">62311-2</a>	NO				
<a href="#">62429-1</a>	NO				



<a href="#">62781-1</a>	NO				
<a href="#">62781-2</a>	NO				
<a href="#">62781-3</a>	NO				
<a href="#">62935-1</a>	NO				
<a href="#">63044-1</a>	NO				
<a href="#">63458-1</a>	NO				
<a href="#">63590-3</a>	NO				
<a href="#">63658-1</a>	NO				
<a href="#">63658-2</a>	NO				
<a href="#">636901P003</a>	NO		7-1195035-5, <b>QS1500-NO.3-F7-0-50MM</b>		
<a href="#">63773-1</a>	NO				
<a href="#">63810-1</a>	NO				
<a href="#">63861-1</a>	NO				
<a href="#">63864-1</a>	NO				
<a href="#">63965-1</a>	NO				
<a href="#">640251-7</a>	NO				
<a href="#">640388-2</a>	NO				
<a href="#">640388-3</a>	NO				
<a href="#">640456-2</a>	NO		"403612641", "2-42934-0583"		
<a href="#">640456-5</a>	NO				
<a href="#">640903-2</a>	NO				
<a href="#">640923-2</a>	NO		"1181513"		
<a href="#">644943-7</a>	NO				
<a href="#">647402-2</a>	NO				
<a href="#">647402-3</a>	NO				
<a href="#">66098-8</a>	NO				
<a href="#">66100-8</a>	NO				
<a href="#">66102-2</a>	NO				
<a href="#">66102-8</a>	NO				
<a href="#">66104-8</a>	NO				
<a href="#">66105-4</a>	NO				
<a href="#">66358-9</a>	NO				
<a href="#">66359-9</a>	NO				
<a href="#">6823356011</a>	NO		4-1195363-8, <b>CGPT-6/2-0-25MM</b>		
<a href="#">7-1393114-8</a>	NO		<b>KUHP-11D51-24</b>		
<a href="#">7121976001</a>	NO		7-1195578-7, <b>RBK-VWS-125-NR3-X-65MM</b>		
<a href="#">7501716003</a>	NO		3-1195850-2, <b>RBK-ILS-125-NR4-0-75MM</b>		
<a href="#">7501716011</a>	NO		3-1195850-8, <b>RBK-ILS-125-NR4-0-30MM</b>		
<a href="#">7501716013</a>	NO		9-1200321-0, <b>RBK-ILS-125-NR4-0-40MM</b>		
<a href="#">7501716014</a>	NO		2-1200380-0, <b>RBK-ILS-125-NR4-0-50MM</b>		
<a href="#">7501716015</a>	NO		1201508-6, <b>RBK-ILS-125-NR4-0-35MM</b>		
<a href="#">770007-1</a>	NO				
<a href="#">770008-3</a>	NO				
<a href="#">770476-1</a>	NO				
<a href="#">770476-2</a>	NO				
<a href="#">770579-1</a>	NO		"0-0770579-1"		
<a href="#">770580-1</a>	NO		"0-0770580-1"		
<a href="#">770849-4</a>	NO				
<a href="#">770903-1</a>	NO		"E25278-000", "DUL-PIN-22-18AW-S/M-UMNL"		
<a href="#">770904-1</a>	NO		"2-42939-6041"		
<a href="#">774185P002</a>	NO		8-1196028-0, <b>QS1500-NO.1-F5-0-50MM</b>		
<a href="#">7753956003</a>	NO		8-1196037-5, <b>RBK-85-NR5050/A-X-8MM</b>		
<a href="#">794212-1</a>	NO				
<a href="#">794219-1</a>	NO				

<a href="#">794221-1</a>	NO				
<a href="#">794223-1</a>	NO				
<a href="#">794272-1</a>	NO				
<a href="#">794412-1</a>	NO				
<a href="#">794606-1</a>	NO		"AMPS-0-0794606-1", "F30642-000"		
<a href="#">794616-4</a>	NO				
<a href="#">794616-6</a>	NO				
<a href="#">794617-8</a>	NO				
<a href="#">794758-1</a>	NO				
<a href="#">794781-1</a>	NO				
<a href="#">796075-1</a>	NO				
<a href="#">796286-1</a>	NO				
<a href="#">796288-1</a>	NO				
<a href="#">8-1393099-1</a>	NO		<b>KA-81017-1</b>		
<a href="#">8-1393099-3</a>	NO		<b>KA-81253</b>		
<a href="#">8-1393099-6</a>	NO		<b>KA-81406</b>		
<a href="#">8-1393099-7</a>	NO		<b>KA-81409</b>		
<a href="#">8-1393099-9</a>	NO		<b>KA-81468</b>		
<a href="#">8-1393298-1</a>	NO		VF4-15H11, <b>VF4A-15H11</b>		
<a href="#">8-1393768-7</a>	NO		<b>R10-R0082-2</b>		
<a href="#">8-1393768-8</a>	NO		<b>R10-R0083-2</b>		
<a href="#">87631-2</a>	NO				
<a href="#">881606-4</a>	NO				
<a href="#">9-1393099-0</a>	NO		<b>KA-81469</b>		
<a href="#">9-1393109-6</a>	NO		<b>KU-11D45-12</b>		
<a href="#">9-1393109-7</a>	NO		<b>KU-11D45F-24</b>		
<a href="#">9-1393114-1</a>	NO		<b>KUHP-5D51-24</b>		
<a href="#">9-1414780-4</a>	NO		"V23134-B0052-X490"		
<a href="#">917684-1</a>	NO				
<a href="#">917686-1</a>	NO				
<a href="#">917687-1</a>	NO				
<a href="#">917688-1</a>	NO				
<a href="#">917699-1</a>	NO				
<a href="#">917780-1</a>	NO				
<a href="#">925014</a>	NO				
<a href="#">925075</a>	NO				
<a href="#">925076</a>	NO				
<a href="#">926291-1</a>	NO				
<a href="#">926647-1</a>	NO				
<a href="#">926852-2</a>	NO				
<a href="#">926882-3</a>	NO				
<a href="#">926887-1</a>	NO				
<a href="#">927841-2</a>	NO		"0-0927841-2"		
<a href="#">C452154003</a>	NO		8-1201917-6, <b>RPT-120-27/12.7-0-SP</b>		
<a href="#">CH01006003</a>	NO		4-1899281-8, <b>TECT-13.5/4.5-0-30MM</b>		
<a href="#">CH02268001</a>	NO		7-1899395-7, <b>TSAS-UNSLT-NR501-X-100006</b>		
<a href="#">CH02438001</a>	NO		3-1899398-2, <b>TSAS-UNSLT-NR502-X-100006</b>		
<a href="#">CH40676001</a>	NO		9-1899627-8, <b>RBK-VWS-125-NR3-X-95MM</b>		
<a href="#">CH84276001</a>	NO		5-1899689-1, <b>CGPT-6/2-0-28MM</b>		
<a href="#">CV1952-000</a>	NO		5-1899806-2, <b>RBK-105-KIT-2402-A0</b>		
<a href="#">CV19896001</a>	NO		5-1899806-1, <b>ATUM-12/3-2-30MM</b>		
<a href="#">CV19906001</a>	NO		5-1899806-0, <b>ATUM-16/4-2-65MM</b>		
<a href="#">CV20036001</a>	NO		4-1899806-9, <b>ATUM-16/4-2-50MM</b>		
<a href="#">CV20596001</a>	NO		4-1899806-8, <b>CGPT-19/9.5-2-70MM</b>		

<a href="#">CV39806001</a>	NO		4-1899806-7, <b>RNF-3000-1.5/0.5-0-40MM</b>			
<a href="#">CV39816001</a>	NO		4-1899806-6, <b>RNF-3000-1.5/0.5-0-60MM</b>			
<a href="#">EG75736001</a>	NO		6-1899831-6, <b>RNF-3000-1.5/0.5-X-50MM</b>			
<a href="#">F313754003</a>	NO		7-1201918-5, <b>RPT-120-19/6-0-SP</b>			